

Wah Hong Motors & Credit Pte Ltd (Co.Reg.No:199806235M)

38 Toh Guan Road East, #01-57, Enterprise Hub
Singapore 608581

Tel: +65 6773 7377 Email: motor@wahhong.sg

TP INSURER:
UNKNOWN

EQ Insurance Company Ltd (HQ)

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	WH0939
Policy No:		Date of Loss:	30/11/2021
Vehicle Reg. No.:	SMJ4955L	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	LYE LI TENG, CHERYL		
Make/Model:	HONDA FIT, 1.3 GF CVT (A)	Vehicle Reg. Date:	08/03/2019
Vehicle Colour:	RED	Chassis No:	GK31341334
Engine No:	L13B1449342		
Odometer:	35618 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	14		
Present Location:	WAH HONG MOTORS & CREDIT PTE LTD (HQ)		

COST OF CLAIMS	Amount
Parts	5,168.90
Miscellaneous Items	495.00
Labour	3,520.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	9,183.90
+ GST 7.00% (S\$)	642.87
Nett Amount (S\$)	9,826.77

This claim is handled by: THONG ZHONGMING

Generated using Merlmen e-Claims Internet Estimation & Adjusting System

PAIR DETAILS

Reference

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 01 Dec 2021)

Parts: 143

HONDA FIT 1.3 GF CVT (A) (Catalogue: Merimen Singapore 1.0)

Labour: Repairer's

(Price-denominated Standard List)

Print Code: Wah Hong Motors & Credit Pte Ltd/SMJ4955L/01/12/2021 16:24

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*Rear windscreen moulding / <i>DEC</i>	0.00	0.00	*80.00 F ✓
2	1		*Boot lid / <i>DD</i>	0.00	0.00	*570.00 F ✓
3	1		*Boot lid outer center garnish X <i>AN</i>	0.00	0.00	*130.00 F ✓
4	1		*Boot lid inner trim board X <i>AN</i>	0.00	0.00	*60.00 F ✓
5	1		*Boot lid Weatherstrip / <i>CR4</i>	0.00	0.00	*50.00 F ✓
6	1		*Boot lid logo badge / <i>DEC</i>	0.00	0.00	*20.00 F ✓
7	1		*Boot lid emblem "fit" / <i>DEC</i>	0.00	0.00	*80.00 F ✓
8	1		*Boot lid lock / <i>GT</i>	0.00	0.00	*220.00 F ✓
9	1		*Rear bumper / <i>DD</i>	0.00	0.00	*255.00 F ✓
10	1		*End panel / <i>DD</i>	0.00	0.00	*280.00 F ✓
11	1		*Bonnet X <i>R</i>	0.00	0.00	*210.00 F ✓
12	1		*Center grille / <i>CUT</i>	0.00	0.00	*130.00 F ✓
13	1		*Center grille top chrome / <i>CUT</i>	0.00	0.00	*18.00 F ✓
14	1		*Center grille logo badge / <i>DEC</i>	0.00	0.00	*460.00 F ✓
15	1		*Front bumper / <i>CR4</i>	0.00	0.00	*120.00 F ✓
16	1		*Front bumper lower center grille / <i>CUT</i>	0.00	0.00	*13.00 F ✓
17	1		*Front bumper towing cover / <i>CR4</i>	0.00	0.00	*185.00 F ✓
18	1		*Front reinforcement / <i>DD</i>	0.00	0.00	*130.00 F ✓
19	1		*Center grille lower chrome / <i>BR</i>	0.00	0.00	*24.00 F ✓
20	1		*Rear bumper side retainer LH/RH@2*\$12 / <i>BR</i>	0.00	0.00	*50.00 F ✓
21	1		*Rear bumper center garnish / <i>BR</i>	0.00	0.00	*40.00 F ✓
22	1		*Rear bumper side fog cover LH/RH@2*\$20 / <i>CR4</i>	0.00	0.00	*48.00 F ✓
23	1		*End panel top garnish / <i>CR4</i>	0.00	0.00	*460.00 F ✓
24	1		*Tail lamp LH/RH@2*\$230 / <i>CUT</i>	0.00	0.00	*16.00 F ✓
25	1		*Front bumper side retainer LH/RH@2*\$9 / <i>BR</i>	0.00	0.00	*50.00 F ✓
26	1		*Front bumper lower headlamp bracket LH/RH@2*\$25 X <i>AN</i>	0.00	0.00	*890.00 F ✓
27	1		*Headlamp LH/RH@2*\$445 X <i>AN</i>	0.00	0.00	*56.00 F ✓
28	1		*Fog lamp cover LH/RH@2*\$26 (LH) - <i>BR</i> (RH) - <i>CUT</i>	0.00	0.00	*34.00 F ✓
29	1		*Fog lamp cover top garnish LH/RH@2*\$17 (LH) - <i>CR4</i>	0.00	0.00	*- F
30	1		*Rear floor panel (Repair refer to labour) X <i>R</i>	0.00	0.00	*- F
31	1		*Front support panel (Repair refer to labour) X <i>R</i>	0.00	0.00	

F=Franchise part.

Sub Total (S\$) 4,699.00
+ Margin on L,N Items 10.00% (S\$) 469.90
Total Parts (S\$) 5,168.90

Wah Hong Motors & Credit Pte Ltd/SMJ4955L/01/12/2021 16:24. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

2812
+ 10%
3093.20

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	Center grille clips - nec	35.00
2	1	End panel sealant - nec	60.00
3	1	Front bumper clips - nec	35.00
4	1	Front Car plate with holder - OT	35.00
5	1	Rear bumper clips - nec	35.00
6	1	Rear car plate with Holder X 11	35.00
7	1	Rear reverser sensor - OR	200.00
8	1	Rear windscreen sealant - nec	60.00
375			41
Sub Total (S\$)			495.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	New	1,800.00
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	New	1,400.00
3	To perform anti-rust treatment on affected areas	New	40 60.00
4	To remove and refix wiring system at accident damaged area and check for all electrical proper function	New	30 60.00
5	To remove and refit rear compartment fitting, trimmings, garnish and etc	New	80 100.00
6	To remove and replace rear windscreen	New	100.00
3450			
Gross Labour Cost (S\$)			3,520.00

= 6918.20

Wah Hong Motors & Credit Pte Ltd/SMJ4955L/01/12/2021 16:24. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Supp + 1296.40
= 8214.60

Steve (LKK)
2/12/21, 1.30pm

WL PL
P/P
My Pol sy
12 days

cost + 10% workshop provide invoice