

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21012216/KGA3Q2**Date:** 09/06/2022**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100482380
Claimant Vehicle No :	SLU8204Z	Insured Vehicle No :	SLF9457H
Date of Loss:	30/11/2021	Nature of Claim:	TP
		Claim No:	1353915794SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLU8204Z	Engine No:	LEB5964690
Make & Model:	HONDA VEZEL, 1.5 X CVT (A)	Chassis No:	RU31264670
Reg. Date:	14/12/2017 (Man. Year: 2017)	Odometer:	146206 km
Colour:	Metallic Red		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50 R18	Rear Tyre Size:	225/50 R18
Front Left Side:	Continental 8 mm	Rear Left Side:	Continental 8 mm
Front Right Side:	Continental 8 mm	Rear Right Side:	Continental 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,821.36	955.44	2,865.92	75.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,100.00	1,170.00	930.00	44.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,921.36	2,125.44	3,795.92	64.11
Approved Total (Overridden) (S\$)		1,700.00		
(S\$)	5,921.36	1,700.00	4,221.36	71.29
+ GST 7.00/7.00% (S\$)	414.50	119.00	295.50	71.29
Nett Amount (S\$)	6,335.86	1,819.00	4,516.86	71.29
+ Loss of Use (5.0 x S\$50.00/day) (S\$)		250.00		
(S\$)		2,069.00		
Liabile Amount (50.00%) (S\$)		1,034.50		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,036.50		
Global Sum Settlement (S\$)		1,000.00		

INSPECTION

Date of Assignment:	01/12/2021	
Date Inspected:	03/03/2022 Inspected At:	Lim Tan Motor Pte Ltd (HQ) Blk 176 Sin Ming Drive #03-09/10, Sin Ming Auto Care Singapore 575721
Estimated Period of Repair:	4.0 days	

Adjuster: KENNETH KONG

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*O/S REAR FENDER ARCH GARNISH	Dented / Cut	210.20 FL	*210.20 FL
2	1		*O/S REAR DOOR	Bent	930.60 FL	*930.60 FL
3	1		*O/S REAR DOOR FRAME TAPE	Necessary	28.40 FL	*28.40 FL
4	1		*O/S REAR DOOR STICKER	Necessary	25.10 FL	*25.10 FL
5	1		*O/S REAR RIM	Serviceable	1,350.40 FL	*- FL
6	1		*O/S REAR SHOCK ABSORBER	Serviceable	385.40 FL	*- FL
7	1		*O/S WHEEL BEARING HUB	Serviceable	263.40 FL	*- FL
8	1		*REAR AXLE ASSY	Serviceable	1,583.20 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	4,776.70	1,194.30
- List Item Discount on L Items 20.00/20.00% (\$)	955.34	238.86
Total Parts (\$)	3,821.36	955.44

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PUTTY & SPRAY PAINT	New	1,000.00	700.00
2	TO TRANSFER DOOR FITTING	New	40.00	40.00
3	TO ANTI RUST	New	50.00	30.00
4	TO REPLACE UNDER-CARRIAGE	New	350.00	0.00
5	TO CHECK WHEEL ALIGNMENT	New	60.00	0.00
6	LABOUR CHARGE	New	600.00	400.00
			Gross Labour Cost (\$)	2,100.00
				1,170.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >