

JL Perfect Autowork Pte Ltd

Company Reg No: 202136905K

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778
E-mail:jlperfectautowork@gmail.com



DATE : 06.12.21

TO : **AUTO & GENERAL** MOTOR CLAIMS DEPTS
VEHICLE NO : **SJP1121A**
MODEL : **HYUNDAI HD AVANTE**
DATE OF ACCIDENT : 30.11.2021
TIME OF ACCIDENT : 16:40 HRS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>Dented</i>	1	\$ 447.90	\$ 447.90
2	REAR BUMPER RETAINER <i>Neo</i>	2	\$ 49.80	\$ 99.60
3	REAR BUMPER BRACKET <i>Dented</i>	5	\$ 19.80	\$ 99.00
4	REAR BUMPER REINFORCEMENT <i>Crushed</i>	1	\$ 298.70	\$ 298.70
5	REAR BUMPER REINFORCEMENT BRACKET <i>Dented</i>	2	\$ 26.60	\$ 53.20
6	REAR BUMPER SPONGE <i>Crushed</i>	1	\$ 129.30	\$ 129.30
7	BOOTLID <i>Repair</i>	1	\$ 985.90	\$ 985.90
8	BOOTLID REFLECTOR <i>2</i>	2	\$ 217.40	\$ 434.80
9	BOOTLID OUTER MOULDING	1	\$ 198.20	\$ 198.20
10	BOOTLID HINGE <i>1 set</i>	2	\$ 101.10	\$ 202.20
11	BOOTLID STOPPER <i>1 set</i>	2	\$ 18.10	\$ 36.20
12	BOOTLID INSULATOR	1	\$ 151.20	\$ 151.20
13	BOOTLID LOGO <i>3 sets</i>	1	\$ 32.70	\$ 32.70
14	BOOTLID EMBLEM 'AVANTE'	1	\$ 34.30	\$ 34.30
15	BOOTLID KEY LOCK <i>2</i>	1	\$ 167.50	\$ 167.50
16	BOOTLID TOP LOCK <i>1 set</i>	1	\$ 118.30	\$ 118.30
17	BOOTLID LOWER LOCK <i>1 set</i>	1	\$ 15.00	\$ 15.00
18	BOOTLID WEATHER STRIP <i>cut</i>	1	\$ 87.50	\$ 87.50
19	TAILLAMP <i>2H crushed</i>	2	\$ 288.40	\$ 576.80
20	REAR FENDER COWLING <i>2 set</i>	2	\$ 98.70	\$ 197.40
21	REAR FENDER INNER TRIM <i>1 set</i>	2	\$ 163.60	\$ 327.20
22	REAR END PANEL <i>Dented</i>	1	\$ 585.30	\$ 585.30
23	REAR END PANEL TOP GARNISH <i>crushed</i>	1	\$ 74.60	\$ 74.60
24	REAR FLOOR PANEL <i>2 set</i>	1	\$ 898.90	\$ 898.90
25	REAR FLOOR PANEL TOP BOARD <i>1 set</i>	1	\$ 220.40	\$ 220.40

288.40

TO : **AUTO & GENERAL** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SJP1121A**
 MODEL : **HYUNDAI HD AVANTE**
 DATE OF ACCIDENT : 30.11.2021
 TIME OF ACCIDENT : 16:40 HRS

26	REAR TOOLS SPONGE	1	\$ 94.60	\$ 94.60
27	REAR SPARE TYRE BOLT	1	\$ 32.10	\$ 32.10
28	REAR EXHAUST PIPE	1	\$ 735.10	\$ 735.10
29	REAR EXHAUST INSULATOR	1	\$ 113.10	\$ 113.10
30	REAR EXHAUST GASKET (SET)	1	\$ 60.00	\$ 60.00
31	REAR EXHAUST MOUNTING	2	\$ 19.20	\$ 38.40

2230.50

1784.40

TOTAL PRICE \$ 7,545.40
 LESS 20% \$ 1,509.08
SUB TOTAL PRICE \$ 6,036.32

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE (SPECIAL TYPE)	1	\$ 80.00	\$ 80.00
2	REAR BUMPER CLIP (SET)	1	\$ 80.00	\$ 80.00
3	BOOTLID OUTER MOULDING CLIP (SET)	1	\$ 40.00	\$ 40.00
4	BOOT LID INSULATOR CLIP (SET)	1	\$ 50.00	\$ 50.00
5	TAIL LAMP CLIP (SET)	1	\$ 30.00	\$ 30.00
6	TAILLAMP PANEL SEALANT	2	\$ 60.00	\$ 120.00
7	REAR FENDER INNER COWLING CLIP (SET)	1	\$ 50.00	\$ 50.00
8	REAR FENDER INNER TRIM CLIP (SET)	1	\$ 50.00	\$ 50.00
9	REAR END PANEL SEALANT	1	\$ 150.00	\$ 150.00
10	REAR END PANEL TOP GARNISH CLIP (SET)	1	\$ 50.00	\$ 50.00
11	REVERSE SENSOR	1	\$ 220.00	\$ 220.00

TOTAL \$ 920.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,800.00	600
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,600.00	800
3	REMOVE AND REFIX UPHOLSTRY AND ROOF LINING TO FACILITATE REPAIR	\$ 350.00	60
4	TUFF COAT	\$ 250.00	60
5	WIRING CHECK	\$ 180.00	30
6	CONDUCT WATER LEAKAGE TEST	\$ 80.00	X
7	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	50

TO : **AUTO & GENERAL** MOTOR CLAIMS DEPTS
VEHICLE NO : **SJP1121A**
MODEL : **HYUNDAI HD AVANTE**
DATE OF ACCIDENT : 30.11.2021
TIME OF ACCIDENT : 16:40 HRS

8	REAR CHASSIS ALIGNMENT	\$ 250.00	X
9	TRANSFER BOOTLID MECHANISM	\$ 80.00	X
10	REMOVE AND REFIX FUEL TANK TO FACILITATE FLOOR PANEL REPLACEMENT	\$ 80.00	X
11	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	X

TOTAL \$ 4,930.00

ESTIMATE REPORT

TOTAL PARTS COST : \$ 6,956.32
TOTAL LABOUR COST : \$ 4,930.00
TOTAL REPAIR COST : \$ 11,886.32

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
IRENE
HP : 8297 9787

Adrian L
L/s 07/12/21.
05 Days

total: 3684.40
L/s: 2.91k.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: