



BAN HOCK HIN
Co., Pte Ltd

Co. Reg. No: 197000268K
MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

AIG ASIA PACIFIC INSURANCE PTE LTD
CHARTIS BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120
ATTN: MOTOR CLAIMS DEPT

NO. : 39597

DATE : 01/12/2021
CLAIM NO. : 11826
POLICY NO. : MC/00914724
FROM : RAYMOND

VEHICLE NO. : FBP6918E
MAKE/MODEL : YAM / NMAX155 ABS

*not Arthur
Lila
2/12/21
take photo after repair
3 days
P/P &*

(Page 1 of 4)

S/N	Description	Action	Qty	Unit Price	Amount
1	BELLY PAN P/N: 58094 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$35.00	35.00 X
2	BOARD FOOTREST LH P/N: 59588 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$55.00	55.00 X
3	BOX FILTER AIR OUTER P/N: 58141 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$18.00	18.00
4	BOX FILTER AIR OUTER FRONT P/N: 58164 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$10.00	10.00 X
5	BUSH ENGINE P/N: 58144 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$8.00	16.00 X
6	CLIP NUT SPRING P/N: 59586 - (REPORTED BY MECHANIC)	REPLACE	5.00	\$1.50	7.50 X
7	COVER CLUTCH OUTER P/N: 58147 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$66.00	66.00 X
8	COVER FRONT (GREY) P/N: 63498 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$35.00	35.00 X
9	COVER SIDE LH (MATTE BLACK) P/N: 66090 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$38.00	38.00 X

*39597 *

bizSAFE₃



Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg

Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO.: 2002-1-0363
ISO 9001:2015

S/N	Description	Action	Qty	Unit Price	Amount
10	COVER SIDE LOWER LH (BLUE) P/N: 60906 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$21.00	21.00 X
11	COVER SIDE REAR LH (BLUE) P/N: 60903 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$28.00	28.00 X
12	COVER SIDE REAR RH (GREY) P/N: 63495 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$28.00	28.00 X
13	COWLING FRONT LH (BLUE) P/N: 60912 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$32.00	32.00 X
14	DAMPER PLATE P/N: 64847 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$3.00	3.00 X
15	EMBLEM (YAMAHA) LOGO P/N: 57069 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$14.00	28.00 X
16	ENGINE BRACKET COMP P/N: 61969 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$68.00	68.00
17	FOOTREST REAR ASSY 1 LH P/N: 58212 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$32.00	32.00 X
18	HEADLAMP ASSY P/N: 58174 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$299.00	299.00 X
19	HOOK COVER SIDE P/N: 57086 - (REPORTED BY MECHANIC)	REPLACE	4.00	\$1.50	6.00 X
20	LABOUR P/N: 06766 - LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS.	Supply/Install	10.00	\$63.00	630.00
21	LAMP SIGNAL FRONT LH P/N: 59587 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$34.00	34.00 X
22	LAMP TAIL ASSY P/N: 60928 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$223.00	223.00
23	LEVER BRAKE LH P/N: 58145 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$18.00	18.00 X
24	MIRROR LH P/N: 58099 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$35.00	35.00 X

*39597 *

bizSAFE₃

Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg

Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO.: 20024-0383
ISO 9001: 2015

S/N	Description	Action	Qty	Unit Price	Amount
25	MUDGUARD FRONT (GREY) P/N: 63496 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$45.00	17 45.00 ✓
26	MUDGUARD REAR P/N: 60932 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$49.00	17 49.00 ✓
27	PANEL 1 (MATTE BLACK) LH P/N: 63491 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$21.00	17 21.00 ✓
28	PLATE NUMBER REAR (6.5 INCH X 9 INCH) P/N: 26951 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$28.00	sent 15- 28.00 ✓
29	REFLECTOR REAR P/N: 67563 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$4.50	? 9.00
30	RIVET P/N: 56583 - (REPORTED BY MECHANIC)	REPLACE	12.00	\$3.00	? 36.00
31	SCREW (VISOR) P/N: 62053 - (REPORTED BY MECHANIC)	REPLACE	4.00	\$3.00	17 12.00 X
32	SEAT HANDLE (BLACK) P/N: 68460 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$135.00	sent n/c 135.00 X
33	SHAFT PIVOT P/N: 61967 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$12.00	17 12.00 X
34	SHOCK ABSORBER REAR P/N: 58133 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$105.00	? 210.00
35	STAND MAIN P/N: 58138 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$63.00	17 X 63.00
36	STICKER (MCDONALD) COVER SIDE P/N: 60256 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$18.00	17 X 18.00
37	STICKER (MCDONALDS) SIDE COVER / WINDSHEILD P/N: 56222 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$16.00	17 X 16.00
38	STICKER NUMBER PLATE FRONT (BLACK) STRAIGHT P/N: 32921 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$15.00	17 X 15.00
39	STOPPER, MAIN STAND P/N: 61968 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$7.00	17 X 7.00

*39597 *

bizSAFE₃

S/N	Description	Action	Qty	Unit Price	Amount
40	TRANSPORT CHARGES P/N: 07169 - BIKE TOWED BACK TO BHH	*	1.00	\$50.00	35 50.00
41	WINDSHIELD P/N: 58073 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$56.00	11X 56.00
SUB TOTAL					\$2,547.50
GST @ 7 %					\$178.33
GRAND TOTAL (SGD)					\$2,725.83

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- For legal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*39597 *

bizSAFE₃





Yamaha Aerox 155

Reg Date : 29/11/2019 Capacity : 155cc
Vehicle Type : Scooters Mileage : -

Posted on 26/11/2021

SGD \$9300

★ Paid Ad

★ Dealer Ad

Details >



Yamaha Aerox 155

Reg Date : 07/04/2020 Capacity : 155cc
Vehicle Type : Scooters Mileage : -

Posted on 26/11/2021

SGD \$9800

★ Paid Ad

★ Dealer Ad

Details >



Yamaha Aerox 155

Reg Date : 29/01/2019 Capacity : 155cc
Vehicle Type : Cubs Mileage : 41534km

Posted on 22/11/2021

SGD \$10888

★ Paid Ad

★ Dealer Ad

Details >



Yamaha Aerox 155

Reg Date : 06/08/2019 Capacity : 155cc
Vehicle Type : Scooters Mileage : 70148km

Posted on 22/11/2021

SGD \$10888

★ Paid Ad

★ Dealer Ad

Details >



Yamaha Aerox 155

Reg Date : 24/03/2020 Capacity : 155cc
Vehicle Type : Scooters Mileage : 25000km

Posted on 20/11/2021

SGD \$10588

★ Paid Ad

★ Dealer Ad

Details >

Yamaha Aerox 155

Reg Date : 13/07/2020 Capacity : 155cc
Vehicle Type : Scooters Mileage : 14617km

SGD \$13000

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	288K
Vehicle Details	
Vehicle No.:	FBP6918E
Vehicle to be Exported:	No
Intended Deregistration Date:	02 Dec 2021
Vehicle Make:	YAMAHA
Vehicle Model:	NMAX155 ABS
Primary Colour:	Grey
Manufacturing Year:	2019
Engine No.:	G3H6E0013884
Chassis No.:	MH3SG431000011161
Maximum Power Output:	-
Open Market Value:	\$2,480.00
Original Registration Date:	23 May 2019
First Registration Date:	23 May 2019
Transfer Count:	0
Actual ARF Paid:	\$372.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	22 May 2029
COE Category:	D - Motorcycle
COE Period(Years):	10
QP Paid:	\$3,602.00
COE Rebate Amount:	\$2,690.00
Total Rebate Amount:	\$2,690.00

The information contained herein is correct as at 02 Dec 2021

OK