

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: F13P6918Eat Workshop m/s BHM

of _____

Insured: SMA 816

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 88500

IDAC Accident Rpt: _____

Consistent? : Yes or No

GIA / PR Seen: _____

Consistent? : Yes or No

Est. Repairs: 3 days

Res: Yes or No

Lum Sum: 20 %

3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____

Person Contacted: LIA & 2690

Veh No

F13P6918E

Yr Regn:

23/5/19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make

Yamaha NMAX 155 cc

Colour

Grey

A/C: Insured / Std / NI / NA

Sp. Reading

T10285

T/Radio: Insured / Std / NI / NA

Eng/No

C/No:

MH356431000011161Gen. Cond. Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

110/70-13

R:

130/70-13

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Timsun

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

27/11/21

D.O.I.

2/12/21

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

bike never fall clear liability
 per shock absorber thrown away already so 4/5.
 12/1/22 4/5 \$500 insured Raymond

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) ___ S + RS ___ \$

) Photos

) Others

Report Format :

Lump Sum / I.B.I.: (\$ _____)

Add Fee:

☐

Site Insp (\$ _____)

☐

Interview (\$ _____)

☐

Tech. Invs (\$ _____)

☐

Weekend (\$ _____)

TOTAL



BAN HOCK HIN
Co., Pte Ltd

Co. Reg. No: 19700288K
MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

NO. : 39597

AIG ASIA PACIFIC INSURANCE PTE LTD

CHARTIS BUILDING

78 SHENTON WAY

#07-16

SINGAPORE 079120

ATTN: MOTOR CLAIMS DEPT

DATE : 01/12/2021

CLAIM NO. : 11826

POLICY NO. : MC/00914724

FROM : RAYMOND

VEHICLE NO. : FBP6918E

MAKE/MODEL : YAM / NMAX155 ABS

(Page 1 of 4)

S/N	Description	Action	Qty	Unit Price	Amount
1	BELLY PAN P/N: 58094 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$35.00	35.00 X
2	BOARD FOOTREST LH P/N: 59588 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$55.00	55.00 X
3	BOX FILTER AIR OUTER P/N: 58141 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$18.00	18.00
4	BOX FILTER AIR OUTER FRONT P/N: 58164 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$10.00	10.00 X
5	BUSH ENGINE P/N: 58144 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$8.00	16.00 X
6	CLIP NUT SPRING P/N: 59586 - (REPORTED BY MECHANIC)	REPLACE	5.00	\$1.50	7.50 X
7	COVER CLUTCH OUTER P/N: 58147 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$66.00	66.00 X
8	COVER FRONT (GREY) P/N: 63498 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$35.00	35.00 X
9	COVER SIDE LH (MATTE BLACK) P/N: 66090 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$38.00	38.00 X

*39597 *

bizSAFE₃



Address: No. 6, Defu lane 4, Singapore 539410 | Telephone: +65 6281 6520 | Web: www.bhh.com.sg

Fax: (Main) +65 6281 2830, (Spare Parts) +65 6285 7530, (Insurance/Project) +65 6284 2969, (Accounts) +65 6281 6759

CERT NO. 2002-4-0303
ISS. 01/11/2015

S/N	Description	Action	Qty	Unit Price	Amount
10	COVER SIDE LOWER LH (BLUE) P/N: 60906 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$21.00	17 21.00 X
11	COVER SIDE REAR LH (BLUE) P/N: 60903 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$28.00	17 28.00 X
12	COVER SIDE REAR RH (GREY) P/N: 63495 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$28.00	17 28.00 X
13	COWLING FRONT LH (BLUE) P/N: 60912 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$32.00	17 32.00 X
14	DAMPER PLATE P/N: 64847 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$3.00	17 3.00 X
15	EMBLEM (YAMAHA) LOGO P/N: 57069 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$14.00	17 28.00 X
16	ENGINE BRACKET COMP P/N: 61969 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$68.00	17 68.00 X
17	FOOTREST REAR ASSY 1 LH P/N: 58212 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$32.00	17 32.00 X
18	HEADLAMP ASSY P/N: 58174 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$299.00	17 299.00 X
19	HOOK COVER SIDE P/N: 57086 - (REPORTED BY MECHANIC)	REPLACE	4.00	\$1.50	17 6.00 X
20	LABOUR P/N: 06766 - LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS.	Supply/Install	10.00	\$63.00	150 630.00 X
21	LAMP SIGNAL FRONT LH P/N: 59587 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$34.00	17 34.00 X
22	LAMP TAIL ASSY P/N: 60928 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$223.00	one 223.00 ✓
23	LEVER BRAKE LH P/N: 58145 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$18.00	17 18.00 X
24	MIRROR LH P/N: 58099 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$35.00	17 35.00 X

*39597 *

bizSAFE₃

S/N	Description	Action	Qty	Unit Price	Amount
25	MUDGUARD FRONT (GREY) P/N: 63496 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$45.00	17 45.00 ✓
26	MUDGUARD REAR P/N: 60932 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$49.00	715 49.00 ✓
27	PANEL 1 (MATTE BLACK) LH P/N: 63491 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$21.00	17 21.00 ✓
28	PLATE NUMBER REAR (6.5 INCH X 9 INCH) P/N: 26951 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$28.00	15 cent 28.00 ✓
29	REFLECTOR REAR P/N: 67563 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$4.50	RM 9.00 ✓
30	RIVET P/N: 56583 - (REPORTED BY MECHANIC)	REPLACE	12.00	\$3.00	RM 36.00 ✓
31	SCREW (VISOR) P/N: 62053 - (REPORTED BY MECHANIC)	REPLACE	4.00	\$3.00	RM 12.00 ✓
32	SEAT HANDLE (BLACK) P/N: 68460 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$135.00	cent n/c 135.00 ✓
33	SHAFT PIVOT P/N: 61967 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$12.00	17 12.00 ✓
34	SHOCK ABSORBER REAR P/N: 58133 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$105.00	Bul/100 210.00 ✓
35	STAND MAIN P/N: 58138 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$63.00	17 X 63.00
36	STICKER (MCDONALD) COVER SIDE P/N: 60256 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$18.00	17 X 18.00
37	STICKER (MCDONALDS) SIDE COVER / WINDSHEILD P/N: 56222 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$16.00	17 X 16.00
38	STICKER NUMBER PLATE FRONT (BLACK) STRAIGHT P/N: 32921 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$15.00	17 X 15.00
39	STOPPER, MAIN STAND P/N: 61968 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$7.00	17 X 7.00

*39597 *

bizSAFE₃

S/N	Description	Action	Qty	Unit Price	Amount
40	TRANSPORT CHARGES P/N: 07169 - BIKE TOWED BACK TO BHH	*	1.00	\$50.00	35 50.00
41	WINDSHIELD P/N: 58073 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$56.00	11X 56.00
SUB TOTAL					\$2,547.50
GST @ 7 %					\$178.33
GRAND TOTAL (SGD)					\$2,725.83

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of

Acknowledge & Accepted By

BAN HOCK HIN CO PTE LTD



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

LKH Auto Consulting hence notify the Repairer of the following:

- To resurvey (before/after spray painting)
- To display (damaged parts) during resurvey
- Photos taken are subject to confirmation
- The display survey is on a "Without Prejudice" basis
- The resurvey (if necessary) is allowed
- Supplementary claim must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-500
650

*39597 *

bizSAFE₃

