

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No. : SH 9220E

Date: 18/10/2021

Make : HYUNDAI

Insurance: NTUC

Model : I-40

MVA: MS. Y Y

Qty	Parts Description / Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER <i>x Repair</i>			\$553.00
1	REAR BUMPER CLIPS <i>X</i>			\$22.00
1	REAR BUMPER UNDER COVER <i>X SNN</i>			\$228.00
SUB TOTAL				\$1,031.00
LESS 20%				\$206.20
DISCOUNTED TOTAL				\$824.80
1	REAR BUMPER ADVERTISEMENT LOGO <i>/ KCC</i>			\$50.00
1	REAR BUMPER RUBBER MAT <i>X SNN</i>			\$50.00
1	REAR BUMPER REVERSE SENSOR <i>X</i>			\$135.70
				-10%
				\$235.70
Labour Charge				
PANEL BEATING				\$300.00
SPRAY PAINTING CHARGE				\$300.00
REMOVE/REFIX REVERSE SENSOR				\$60.00
TOTAL LABOUR				\$660.00
ESTIMATE TOTAL				\$1,720.50

Nett
Nett
Nett
Nett

280
250
40

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

2 Days
01/12/21

12pm
Gino Guf

After up the photos

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: