

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	SOMPO INSURAN	CE SINGAPORE PL		Ref:	CS3/SMO21010120/Kvf3e2-1	
	50 RAFFLES PLAC SINGAPORE LANI	CE #03-03 D TOWERSINGAPORE 048623		Date:	09/12/2021	
				Code:	SMO	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SMR 6423A	Veh. Inspected		SKZ 28D	
	Policy No.	D21MTPV01005540	Coverage (\$)		0.00	
	Claim No.	CMTD2102902/MYE	Excess (\$)		0.00	
	Assign From	MELVIN YE YONG KANG	Assign Date		02/12/2021	
2.	Vehicle Particulars & Condition					
	Make & Model	TOYOTA VELLFIRE (A)	c.c		2494	
	Engine No.	HIDDEN	Year of Reg.		2018	
	Chassis No.	JTNGF3DH508018747	Colour		METALLIC PEARL WHITE	
	Odometer	168878 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM	
	General	GOOD				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	235/50 R18	PIRELLI		2 mm	
	L/H Front Tyre	235/50 R18	PIRELLI		2 mm	
	R/H Rear Tyre	235/50 R18	PIRELLI		3 mm	
	L/H Rear Tyre	235/50 R18	PIRELLI		3 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	25/09/2021	Inspection Date	е	04/10/2021	
	Survey held at	AH KOON MOTOR				
		BLK 1001 BUKIT MERAH LANE 3 #01-69 SINGAPORE 159718				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days					