



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Ref: CS3/LPC21011217/Guf3e2-1 Date: 24/12/2021 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	YN 80Z	Veh. Inspected	FBH 7071H	
Policy No.	Z/21/VC00/110348	Coverage (\$)	0.00	
Claim No.	21/21/21/VC00/025106	Excess (\$)	0.00	
Assign From	ONG LI LI	Assign Date	02/12/2021	
2. Vehicle Particulars & Condition				
Make & Model	YAMAHA FZ 16	c.c	153	
Engine No.	HIDDEN	Year of Reg.	2013	
Chassis No.	ME121C0G6D2013211	Colour	RED	
Odometer	23696 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	110/70-17	PIRELLI	6 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	150/60-17	PIRELLI	6 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	30/10/2021	Inspection Date	03/11/2021	
Survey held at	SPEEDY MOTOR CYCLE SERVICE CENTRE BLK 10 ANG MO KIO IND.PARK 2A #05-21 SINGAPORE 568047			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			3 Working Days	