



CLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
 209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

ESTIMATE

Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info														
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	<table> <tr> <td>Cust No/Name</td><td>/PRADEEP TIWARI</td></tr> <tr> <td>Reg No/Reg Date</td><td>SMX3397E / 07/01/202</td></tr> <tr> <td>Date In/Mileage</td><td>/ 0</td></tr> <tr> <td>Chassis No</td><td>KNACC81CVL5361363</td></tr> <tr> <td>Engine No</td><td>G4LEKS600320</td></tr> <tr> <td>Make/Model</td><td>KIA/NIRO 1.6 A SX SR ASY PE</td></tr> <tr> <td>Colour/Trim</td><td>KLG STEEL GREY / WK SATURN BLACK</td></tr> </table>	Cust No/Name	/PRADEEP TIWARI	Reg No/Reg Date	SMX3397E / 07/01/202	Date In/Mileage	/ 0	Chassis No	KNACC81CVL5361363	Engine No	G4LEKS600320	Make/Model	KIA/NIRO 1.6 A SX SR ASY PE	Colour/Trim	KLG STEEL GREY / WK SATURN BLACK
Cust No/Name	/PRADEEP TIWARI														
Reg No/Reg Date	SMX3397E / 07/01/202														
Date In/Mileage	/ 0														
Chassis No	KNACC81CVL5361363														
Engine No	G4LEKS600320														
Make/Model	KIA/NIRO 1.6 A SX SR ASY PE														
Colour/Trim	KLG STEEL GREY / WK SATURN BLACK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	22/11/2021/ 15:51	BLE	261 / Edwin Caina	42809			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000		3						1600 2400.00
RENEW LHR DOOR & LHR FENDER		4 X 400						
REPAIR LH ROCKER PNL								
E PNT98000		1						700 1050.00
RESPRAY LHR DOOR , LHR FENDER & LH ROCKER PNL		2 X 350						
E PNT88000								120.00
REMOVE & REFIT LHR DOOR COMPONENT								
A 13900099								200.00
REMOVE & REFIT FUEL TANK ASSY		(photo)						
E PNT88000								120.00
REMOVE & REFIT RR FLR BOARD, TRIM, CARPET & RR SEAT		(photo)						
A 54900099								30.00
CHECK WIRING ELECTRICAL SYSTEM								
A 10028901								120.00
TO CARRY OUT DIAGNOSTIC CHECK ON ELECTRONIC CONTROL SYSTEM								
E PNT88000								120.00
REMOVE & REFIT LHR QTR GLASS								
M SUNDRY								80.00
SUPPLY GLASS SEALANT								
M SUNDRY								100.00
INSTALL LHR QTR GLASS SOLAR FILM								
E PNT88000								80.00
REMOVE & REFIT REVERSE SENSOR								
M SUNDRY								40 80.00
APPLY ANTI CORROSION ON AFFECTED AREAS								
M SUNDRY								40 60.00
SUPPLY BODY PNL SEALANT								
M SUNDRY								20.00
Sundries								
M PANEL ASSY-REAR DOOR, LH		1.00			1542.00	20.00		1233.60
M HINGE ASSY-DOOR UPR, LHR		1.00			33.00	20.00		26.40
M HINGE ASSY-DOOR LWR, LHR		1.00			26.00	20.00		20.80
M MOULDING ASSY-RR DR FRAME, LH		1.00			33.00	20.00		26.40

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Movement that inspires

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	/PRADEEP TIWARI
	Reg No/Reg Date	SMX3397E / 07/01/202
	Date In/Mileage	/ 0
	Chassis No	KNACC81CVL5361363
	Engine No	G4LEKS600320
	Make/Model	KIA/NIRO 1.6 A SX SR ASY PE
	Colour/Trim	KLG STEEL GREY / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	22/11/2021/ 15:51	BLE	261 / Edwin Caina	42809			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	W/STRIP ASSY-RR DR BELT O/S LH	?	x nn		1.00	50.00	20.00	40.00
M	TAPE-RR DR BLACK FRAME FR,LH	ncc			1.00	11.00	20.00	8.80
M	TAPE-RR DR BLACK RR,LH	ncc			1.00	9.00	20.00	7.20
M	FILM-ANTI CHIPPG LH	ncc			1.00	15.00	20.00	12.00
M	MOULDING ASSY-RR DR W/LINE,LH	?	x nn		1.00	113.00	20.00	90.40
M	GARNISH ASSY-QTR SIDE,LH	?	CUT		1.00	144.00	20.00	115.20
M	PANEL ASSY-QUARTER OUTER,LH	00			1.00	1207.00	20.00	965.60
M	GLASS & MOULDING ASSY-QUARTER	ncc	(photo)		1.00	368.00	20.00	294.40

Estimate

SURVEYOR NAME: Steve CLKK
 SURVEYOR SIGNATURE: 3/12/21, 4.00pm
 DATE: 00-11-11
 REMARKS: EXCESS-?
P/P
My Bel smy
6 days

L&K Auto Detail is hereby notifying the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

Confirm & accepted by _____ is on a "Without Prejudice" basis

- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Authorized signatory and company stamp

Nett 7,420.80
 7% GST on 7420.80 519.46
 Total Payable 7,940.26

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.