

VEHICLE NO : SMX 3397 E

AIG- OD CLAIM SUNVEY: 03/12/21 LIGK- STEVE

WII	9: 42809	(a
COLUMN TO THE PARTY OF THE PART		
Material	:\$ 2,636.80	
Labour	:\$ 3,370.00	***************************************
Sub-Total	:\$ 6,006.80	
Less 2% Disc	: \$	
Less Excess	:\$ 600.00	
Total	:\$ 5,406.80	
GST 7%	:\$ 378.48	
Grand Total	:\$ 5,785.28	
Finalise By/Date	: Urny ON 23/12/21	
ALEXE CENTROLISMA COLUMN PROPRIO DE COMPANSA DE COMPANSA DE COMPANSA DE COMPANSA DE COMPANSA DE COMPANSA DE CO	THE RESERVE AND THE PARTY OF THE PARTY AND THE PARTY OF T	and the state of t
REVERT BAC OTHERWISE	CK WITHIN 7 DAYS, WILL PROCEED WITH INVOICING	3
SURVEYOR'S	REPORT REQUIRED	
REPAIR TOO	KO WORKING DAYS	





209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

PRO-FORMA INVOICE

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address		Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte.	Cust No/Name	/PRADEEP TIWARI
Ltd.	Reg No/Reg Date	SMX3397E / 07/01/2021
MOTOR CLAIM DEPARTMENT	Date In/Mileage	04/12/2021/ 17570
78 SHENTON WAY #09-16 AIG BUILDING	Chassis/Package	KNACC81CVL5361363 /ECB2020
SINGAPORE 079120	Engine No	G4LEKS600320
Contact No 64191000	Make/Model	KIA/NIRO 1.6 A SX SR ASY PE
04/12/2021	Colour/Trim	KLG STEEL GREY / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator		WIP No	
LAX00000	Credit	23/12/2021/ 16:01	BLE	884 / Lauro So	ngcuan	42809	
		Description of Good	s / Service	S	Qty	Unit Price Disc%	Amount
E PNT88000				- W			1600.00
	REAR DO	OR & LH REAR FENDER					
E PNT98000	TNT I U DI	EAR DOOR & LH REAR FI	ENDED				700.00
E PNT88000	INI LII KI	TAR DOOR & LE REAR FI	ENDER				120.00
	REFIT LI	REAR DOOR COMPONEN	TS				120.00
A 13900099		a same a sam					200.00
	REFIT FL	JEL TANK ASSY					200.0
E PNT88000				greenway			120.00
REMOVE & A 54900099	REFIT RE	AR FLOOR BOARD, TRI	M, CARPET	& REAR SEAT			
	DING & CL	HASSIS ELECTRICAL SYS	CTEM)	12001	1001	9)	30.00
A 10028901	KING & CI	MSSIS ELECTRICAL ST	STEM!			(0)	100.0
THE RESERVE THE PARTY OF THE PA	OUT DIAG	GNOSTIC CHECK ON ELEC	CTRONIC CO	ONTROL SYSTEM			120.0
E PNT88000				THE STOTELL			120.0
	REFIT LI	H REAR QUARTER GLASS					21.0.0
M SUNDRY		**					80.0
SUPPLY G	LASS SEAL	ANT					
E PNT88000	DEETT DE	EVERSE SENSOR					80.0
M SUNDRY	KLIII KL	VERSE SENSUR					*0.0
	TI CORROS	SION ON AFFECTED AREA	AS				40.0
M SUNDRY							40.00
	ODY PANEL	SEALANT					
M SUNDRY							20.0
SUNDRIES S SPECIALIS	T.10D						
		LH REAR QUARTER GLAS	CC COLAD 1	TIM (NTDO)			100.0
X EXC	INSTALL	LII KLAK QUARTER GLAS	33 SULAK F	ILM (NIRO)			600 0
EXCESS							-600.0
X PANEL AS	SY-REAR [OOOR,LH/			1.00	1542.00 20.00	1233.6
		FRAME FR,LH			1.00	11.00 20.00	8.8
X TAPE-RR	DR BLACK	RR,LH /			1.00	9.00 20.00	7.2
					His control of the co		





209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

PRO-FORMA INVOICE

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address		Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte.	Cust No/Name	/PRADEEP TIWARI
Ltd.	Reg No/Reg Date	SMX3397E / 07/01/2021
MOTOR CLAIM DEPARTMENT	Date In/Mileage	04/12/2021/ 17570
78 SHENTON WAY #09-16 AIG BUILDING	Chassis/Package	KNACC81CVL5361363 /ECB2020
SINGAPORE 079120	Engine No	G4LEKS600320
Contact No 64191000	Make/Model	KIA/NIRO 1.6 A SX SR ASY PE
04/12/2021	Colour/Trim	KLG STEEL GREY / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator		WIP No		
LAX00000	Credit	23/12/2021/ 16:01	BLE	884 / Lauro S	ongcuan	42809		
		Description of Good	ls / Servic	es	Qty l	Init Price	Disc%	Amount
X PANEL AS	ASSY-QTR SY-QUARTI MOULDING	SIDE,LH? SIDE,LH? ER OUTER,LH ASSY-QUARTER			1.00 1.00 1.00 1.00		20.00 20.00 20.00	12.0 115.2 965.6 294.4
	STEVE (LI	(K) 03/12/2021		For				
		EI(0)	FO		31		
	G	Guarantee Your Warra	nty, Mair	ntain with Cycle &	Carriage!			
Parts Labour Standard M Specialist			.00		7% GST on	Net 5406.8	30	5,406.8 378.4
Diagnostic Sundry/Oth Total (w/o	s Job ers	100 0 -420 5,406	.00		Tot	al Payabl	le	5,785.2

This is not an official tax invoice. This is a computer generated document, no signature is required.

CAR NO: SMX 3397#

WIP: 42809


(ADDITIONAL PARTS CHANGE)

S/NO	PARTS NAME			SIGN	PHOTO TAKEN	TAKEN
1	SARAISH ASSY-OTR SIDE	3015 H 3180PP	A de	7		
2		?/SUPP	Ď			
ω		?/SUPP	ď			
4		?/SUPP	P			
51		?/SUPP	Ď			
6		?/SUPP	Ď			
7		?/SUPP	Ď			
8		?/SUPP	ď			
9		?/SUPP	ď			23
10		?/SUPP	Ď			
11		?/SUPP	Ď			70 P
12		?/SUPP	Ď			74 27 27 28 28 28 28 28 28 28 28 28 28 28 28 28
13		?/SUPP	Ď			
14		?/SUPP	Ď		3 4	N 10 10 10 10 10 10 10 10 10 10 10 10 10
15		?/SUPP	Ď			
16		?/SUPP	Ď			
17		?/SUPP	Ď			
18		?/SUPP	P			
19		?/SUPP	P			
20		?/SUPP	P	127		

	DATE	TAKEN BY
PHOTO BEFORE PAINT	97 P	101
PHOTO AFTER PAINT		
PHOTO OF MOUNT TO CELLLETE BENCH		
REMOVE AND INSTALL ENGINE		
REMOVE AND INSTALL DASHBAORD		
REMOVE & INSTALL FUEL TANK		
PHOTO UNDERCARRIAGE PARTS		

MODEL: NIR

SURVEYOR: STEVE



VDN: 211220114I 12/20/21 16:44






System	Status	Result
ENGINE	No Current DTC	Good
мси	No Current DTC	Good
HCULDC	No Current DTC	Good
вмѕ	No Current DTC	Good
AT	No Current DTC	Good
ЕРВ	No Current DTC	Good

No History or Pending DTC	System	DTC	Description	State
			No History or Pending DTC	

S/W Ver.	M-E-K-01-00-0261	VCI Ver.	02.63	
ECU Ver.	M-E-K-01-00-0200	OS Ver.	Android 10	



VDN: 211220126I 12/20/21 18:30




System	Status	Result
ENGINE	No Current DTC	Good
MCU	No Current DTC	Good
HCULDC	No Current DTC	Good
BMS	No Current DTC	Good
AT	No Current DTC	Good
ЕРВ	No Current DTC	Good

System	DTC	Description	State
	No Histo	ory or Pending DTC	

S/W Ver.	M-E-K-01-00-0261	VCI Ver.	02.63	
ECU Ver.	M-E-K-01-00-0200	OS Ver.	Android 10	



VDN: 211220126I 12/20/21 18:32



System	Status	Result
ENGINE	No Current DTC	Good
мси	No Current DTC	Good
HCULDC	No Current DTC	Good
BMS	No Current DTC	Good
AT	No Current DTC	Good
ЕРВ	No Current DTC	Good

System	DTC	Description	Stat
		No History or Pending DTC	

S/W Ver.	M-E-K-01-00-0261	VCI Ver.	02.63	
ECU Ver.	M-E-K-01-00-0200	OS Ver.	Android 10	





209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

Movement that inspires

Co Reg No : 199405410K

Authorized signatory and company stamp

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address		Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte.	Cust No/Name	/PRADEEP TIWARI
Ltd.	Reg No/Reg Date	SMX3397E / 07/01/202
MOTOR CLAIM DEPARTMENT	Date In/Mileage	/ 0
78 SHENTON WAY #09-16	Chassis No	KNACC81CVL5361363
AIG BUILDING SINGAPORE 079120	Engine No	G4LEKS600320
Contact No 64191000	Make/Model	KIA/NIRO 1.6 A SX SR ASY PE
	Colour/Trim	KLG STEEL GREY / WK SATURN BLACK

Account No	Terms	Date/Time Pr	inted	CSE	Operator	CONTRACTOR OF THE PARTY OF THE	WIP No			
LAX00000	Credit	22/11/2021/		BLE	261 / Edwin Cain		42809		_	
		Description	of Goods	s / Services		Qty	Unit Price	Disc%		nount
E PNT88000 RENEW LHI	R DOOR &	3 LHR FENDER	4 X 4	00					1600	2400.00
REPAIR LI E PNT98000					a v 760				700	1050.00
RESPRAY I E PNT88000	LHR DOOR	, LHR FENDER	& LH R	OCKER PNL	3 × 222					120.00
	REFIT L	HR DOOR COMPO	NENT							
A 13900099		UEL TANK 100V	(n l	hoto)						200.00
E PNT88000	KEFII F	UEL TANK ASSY	(μ.		(4)					120.00
REMOVE &	REFIT R	R FLR BOARD	RIM, CAR	PET & RR S	EAT (photo)	几一	. 11			30.00
A 54900099 CHECK WI	RING FLF	CTRICAL SYSTE	- (211	110012	lile)			30.00
A 10028901			7	5) 1		7 PI	7			120.00
TO CARRY E PNT88000	OUT DIA	GNOSTIC CHECK	ON ELE	CTRONIC CO	NTROL SYSTEM					120.00
REMOVE &	REFIT L	HR QTR GLASS								80.00
M SUNDRY SUPPLY G	LASS SFA	LANT								
M SUNDRY									-	100.00
INSTALL E PNT88000	LHR QTR	GLASS SOLAR F	FILM						1	80.00
	REFIT R	EVERSE SENSOR	₹							0 00 00
M SUNDRY	ITT CORDO	SION ON AFFE	TED ADE	۸۶					4	0 80.00
M SUNDRY	III CURRU	SION ON AFFE	JIED AKE	AS					4	0 60.00
SUPPLY B	ODY PNL	SEALANT								20.00
M SUNDRY Sundries										
		DOOR,LH /	00			1.00	1542.00			1233.60
M HINGE AS			•			1.00		20.00		26.4
M HINGE AS	SY-DOOR	LWR,LHR ' R DR FRAME,LH				1.00		20.00		26.40

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Page 1 of 2





209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

Movement that inspires

Co Reg No : 199405410K

Authorized signatory and company stamp

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address		Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte.	Cust No/Name	/PRADEEP TIWARI
Ltd.	Reg No/Reg Date	SMX3397E / 07/01/202
MOTOR CLAIM DEPARTMENT	Date In/Mileage	/ 0
78 SHENTON WAY #09-16	Chassis No	KNACC81CVL5361363
AIG BUILDING SINGAPORE 079120	Engine No	G4LEKS600320
Contact No 64191000	Make/Model	KIA/NIRO 1.6 A SX SR ASY PE
	Colour/Trim	KLG STEEL GREY / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	A 19 19 19 18	WIP No		
LAX00000	Credit	22/11/2021/ 15:51	BLE	261 / Edwin Caina		42809		
		Description of Good	s / Services		Qty	Jnit Price	Disc%	Amount
M W/STRIP	ASSY-RR [OR BELT O/S LH ?			1.00	50.00	20.00	40.00
		FRAME FR, LH / 100			1.00		20.00	8.80
		RR, LH / nec			1.00	9.00	20.00	7.20
M FILM-ANT		IH . nec			1.00		20.00	12.00
		DR W/LINE LH ?			1.00	113.00		90.40
M GARNISH	ASSY-QTR	SIDE,LH ?			1.00	144.00		115.20
M PANEL AS	SY-QUARTI	ER OUTER, LH / 00		. \	1.00	1207.00		965.60
M GLASS &	MOULDING	ASSY-QUARTER	nec cpm	ทอ)	1.00	368.00	20.00	294.40
			NAME:	Stere CLKK) 3/12/21, 4.00pm 00-14				
		DATE:		Exass-? P/P Bel 6 days				
Confirm &	accepted	REMARKS		Exass-? P/P M Bel 6 days		Ne 7420 .	ett 80	7,420.8 519.4
Confirm &	accepted	REMARKS		Exass-? P/P M Bel 6 days	SM 7% GST on		80	

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Page 2 of 2