

VEHICLE DAMAGE INSPECTION REPORT

Our File No: MS21-III-020137/TPPRIATN
Date: 21/04/2021

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	D20MFL0005826
Claimant Vehicle No :	SJZ6116E	Insured Vehicle No :	SMW6410K
Date of Loss:	24/02/2021	Nature of Claim:	TP
			Claim No: MFL2021D0000870

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJZ6116E
Make & Model:	BMW 328i, 2.0 (A)
Reg. Date:	28/08/2012 (Man. Year: 2012)
Colour:	Black
Engine Capacity:	1997 cc
Market Value/New Car Price:	N/A
Sum Insured (\$\$):	Market Value/New Car Price
Engine No:	A8930186N20B20A
Chassis No:	WBA3A56000NP02494
Odometer:	16551 km

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/40R18	Rear Tyre Size:	235/40R18
Front Left Side:	Dunlop 5 mm	Rear Left Side:	Dunlop 5 mm
Front Right Side:	Dunlop 5 mm	Rear Right Side:	Dunlop 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (\$\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment:	26/02/2021		
Date Inspected:	26/02/2021 Inspected At:	Nxpress Performance Pte Ltd (HQ) 25, Kaki Bukit Road 4, Synergy @ KB, #01-39, Singapore 417800 Contact: Mr Pan(Ah Nam) 82170834 Singapore 417800	
Estimated Period of Repair:	3.0 days		

Adjuster: Anthony Lim Motor Surveyor	Manager: Candy Cai Duanting
--	------------------------------------

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

JP KNIGHTS PTE LTD

No. 33, Ubi Ave 3 #05-47, Vertex Tower A Ubi Singapore 408868 . Tel: (65) 6345 0068 Fax: (65) 6344 5328
Email: admin@jpknights.com Website: www.jpknights.com Co. Reg & GST No. 200723763Z

SPECIAL REMARKS

Impact to the rear left portion.

Rear bumper dented, rear LH fender scratched, etc.

Market value - \$45,000.00

PARF/COE rebate - \$35,857.00

Economical repair limit - \$9,143.00

Estimated cost of repair \$2,500.00

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 21 Apr 2021)

Parts: 143 BMW 328i 2.0 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: JP Knights Pte Ltd/SJZ6116E/21/04/2021 15:53

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

JP Knights Pte Ltd/SJZ6116E/21/04/2021 15:53. Not valid without Reference section.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

JP Knights Pte Ltd/SJZ6116E/21/04/2021 15:53. Not valid without Reference section.

< END OF ESTIMATES >