

Our Job Ref No : 305496379
Date : 07/12/21

ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508999
Fax: 6546 6156

FINALIZATION FORM

To : LKK
Attn : THEVAN
Vehicle Reg No. : SHC 653E

Fax :

Date of Accident : 01/12/21

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: TOKIO MARINE --- SJD8090Y
2. The finalized amount shall be:
 - (a) Spare Parts after List discount \$613.60
 - (b) Labour Charges (include advertisement sticker etc) \$831.00
 - Total for Part-By-Part Repair Cost \$1,444.60
 - (c) Lumpsum Repair (if applicable)
Total for Lumpsum repair cost after Less: 20%
Final Lumpsum Repair cost
3. Estimated normal period for repairs: 2 working days.
4. We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days
5. Thank you for your assistance. We confirm the estimates and finalized amount

Signature : 
Name : LIM T S
Tel : 62148398
Fax : 65468156

Signature : 
Name : THEVAN
Date : 7/12/21

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid	---	N		
3. Survey Fees	-----	--		
4. LTA Search Fee	\$7.49 /\$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6 Overrun				

Remarks:

REPAIR ESTIMATE

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010070
ADDRESS : CITYCAB PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65551188

JOB NO : 303496379
REGN NO : SHC 653E
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G2)
DATE OF REGN : 02.07.2019
DATE/TIME IN : 01.12.2021 14.05
ACCIDENT DATE : 01.12.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT PRICE DISC% AMOUNT

PART REQUISITION

0001 28-01-0104-2029-A	REAR NO.PLATE W/TRIM CVR	1	55.00	55.00
0002 04-01-0104-2533-G	REAR BUMPER CTR MOULDING	1	451.25	20.00 361.00
0003 04-01-0101-0111-G	REAR BUMPER CLIPS	10	22.00	20.00 17.60
0004 09-01-9999-0068-A	REVERSE SENSOR	1	180.00	180.00

SUB-TOTAL : 613.60

JOB NATURE

0000 PB	PANEL BEATING-SHC 653E	350.00
0001 SP	SPRAYPAINT CHARGE	250.00
0002 L	R/I REVERSE SENSORS	20.00
0003 20-05	TP MERJIMEN	11.00
0004 L	Rear Fender Adv.Sticker RH/LH	200.00

SUB-TOTAL : 831.00

REPAIR DETAILS

Lim Tian Siong

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 01 Dec 2021)
Parts: 192 HYUNDAI IONIQ HYBRID 1.6 GLS DGT (A) (Catalogue Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: ComfortDelGro Engineering Pte Ltd/SHC653E/01/12/2021 16:02
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BUMPER	20.00	0.00	*459.40 FL X✓
2	1		*REAR BUMPER CENTRE MOULDING	20.00	0.00	*451.25 FL ✓
3	10		*REAR BUMPER CLIPS	20.00	0.00	*22.00 FL ✓
4	1		*REAR BUMPER TOW COVER	20.00	0.00	*98.80 FL X✓
5	1		*REVERSE SENSORS	0.00	0.00	*180.00 F ✓
6	1		*REAR BUMPER FOGLAMP	20.00	0.00	*201.50 FL X✓
7	2		*REAR FENDER ADVERTISEMENT STICKER RH/LH	0.00	0.00	*200.00 F ✓
8	1		*REAR NO.PLATE WITH TRIM COVER	0.00	0.00	*55.00 F ✓
Sub Total (S\$)						1,667.95
- List Item Discount on L Items (S\$)						246.59
Total Parts (S\$)						1,421.36

F=Franchise part L=ListItemDisc.

ComfortDelGro Engineering Pte Ltd/SHC653E/01/12/2021 16:02. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

Lim Tien Siong

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	OD/TP Case (Insurer)	11.00
Sub Total (\$\$)			11.00

Estimates on Labour

No	Particulars	Lab. Type	Amount
<u>Labour Items</u>			
1	PANEL BEATING	New	400.00 ³⁵⁰
2	SPRAY PAINTING	New	300.00 ²⁵⁰
3	R/I REVERSE SENSORS	New	120.00 ²⁰
Gross Labour Cost (\$\$)			820.00

ComfortDelGro Engineering Pte Ltd/SHC653E/01/12/2021 16:02. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Thuan @ Lkhauto.com

8223 7769

2/12/21 1600

plp ✓ after part photo

2 days w p ✓

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: