


Make/Model: TOYOTA CAMRY 2.5 HYBRID
Engine/Chassis No.: JTNB23HK103070515
Date of accident:
Damaged area: Rear

Date: 06/12/2021
Claim Type: TP
VRN: SMW3013T



Not withash
11 Rm @ 3400p
Return after Paint
4 days

List items				
S/N	Parts description	QTY	UNIT PRICE	AMOUNT
1	Bootlid 1031	1	\$ 2,513.00	\$ 2,513.00
2	Bootlid inner trim	1	\$ 181.00	\$ 181.00
3	Bootlid hinge	2	\$ 67.00	\$ 134.00
4	Bootlid lock	1	\$ 359.00	\$ 359.00
5	Bootlid lock striker	1	\$ 65.00	\$ 65.00
6	Bootlid release antenna	1	\$ 324.00	\$ 324.00
7	Bootlid release cable	1	\$ 153.00	\$ 153.00
8	Bootlid weatherstrip	1	\$ 185.00	\$ 185.00
9	Licence plate lamp	2	\$ 92.00	\$ 184.00
10	Bootlid outer garnish	1	\$ 277.00	\$ 277.00
11	Bootlid hinge garnish	2	\$ 49.00	\$ 98.00
12	Bootlid "TOYOTA" logo	1	\$ 113.00	\$ 113.00
13	Bootlid outer garnish "CAMRY" emblem	1	\$ 87.00	\$ 87.00
14	Bootlid "HYBRID" emblem	1	\$ 92.00	\$ 92.00
15	Bootlid lamp n/s	1	\$ 759.00	\$ 759.00
16	Bootlid lamp sponge seal n/s	1	\$ 8.00	\$ 8.00
17	Rear bumper 573	1	\$ 2,375.00	\$ 2,375.00
18	Rear bumper side retainer	2	\$ 187.00	\$ 374.00
19	Rear bumper reinforcement 510.90	1	\$ 776.00	\$ 776.00
20	Rear bumper lower diffuser	1	\$ 688.00	\$ 688.00
21	Taillamp n/s 605.70	1	\$ 989.00	\$ 989.00
22	Taillamp inner garnish n/s	1	\$ 137.00	\$ 137.00
23	Taillamp panel n/s	1	\$ 147.00	\$ 147.00
24	Taillamp lower bracket n/s	1	\$ 65.00	\$ 65.00
25	End panel	1	\$ 732.00	\$ 732.00
26	End panel top garnish	1	\$ 164.00	\$ 164.00
27	Rear bumper reflector	2	\$ 263.00	\$ 526.00
				\$ 12,505.00
List discount				25.00%
Total				\$ 9,378.75

Repair Estimate

Special nett items				
No.	Parts description	QTY	UNIT PRICE	AMOUNT
1	Rear licence plate & frame	1	\$ 55.00	\$ 55.00
2	Reverse camera	1	\$ 550.00	\$ 550.00
3	Reverse sensor	2	\$ 380.00	\$ 760.00
4	Bootlid inner trim clips	10	\$ 5.50	\$ 55.00
5	Rear bumper clips	12	\$ 5.50	\$ 66.00
6	Taillamp clips	6	\$ 5.50	\$ 33.00

24	Taillamp lower bracket n/s	1	\$ 65.00	\$ 65.00
25	End panel	1	\$ 732.00	\$ 732.00
26	End panel top garnish	1	\$ 164.00	\$ 164.00
27	Rear bumper reflector	2	\$ 263.00	\$ 526.00
				\$ 12,505.00
List discount				25.00%
Total				\$ 9,378.75

Repair Estimate

Special nett items				
No.	Parts description	QTY	UNIT PRICE	AMOUNT
1	Rear licence plate & frame	1	\$ 55.00	\$ 55.00
2	Reverse camera	1	\$ 550.00	\$ 550.00
3	Reverse sensor C 210	2	\$ 380.00	\$ 760.00
4	Bootlid inner trim clips	10	\$ 5.50	\$ 55.00
5	Rear bumper clips	12	\$ 5.50	\$ 66.00
6	Taillamp clips	6	\$ 5.50	\$ 33.00
7	Bootlid lamp clips	6	\$ 5.50	\$ 33.00
8	End panel sealant	1	\$ 120.00	\$ 120.00
9	End panel top garnish clips	8	\$ 5.50	\$ 44.00
10	Sundries	1	\$ 50.00	\$ 50.00
Total				\$ 1,766.00

Labour			
No.	Description	Work unit	Amount
1	To dismantle / renew accident damaged portion. To panel beat, reshape, straighten, orientate and align repair / replacement parts.	6	\$ 1,200.00
2	To disconnect rear wire harness of electrical components to facilitate repairs, reconnect and check functions including taillamp lightings.	0.25	\$ 50.00
3	To remove, refit bootlid components and replace bootlid, check and re-adjust close gap, alignment and water seepage.	0.5	\$ 100.00
4	Supply spray paint material and necessary items to respray affected area / panel.	6	\$ 1,200.00
5	To undercoat all affected portions after repair.	0.75	\$ 150.00
Total labour			\$ 2,700.00

Estimate Grand Total	\$ 13,844.75
----------------------	--------------

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Some items may item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: