

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

India International Insurance Pte Ltd
64 Cecil Street, #04-00 IOB Building
Singapore 049711

Our File No: CS/III21012238/EQF3E2

Date: 25/01/2022

REFERENCE

Insured/Claimant: GRAN RENTALS PTE LTD Policy No: D21MFL0000447
Date of Loss: 18/10/2021 Nature of Claim: OD Claim No: MFL2021D0004925

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLL8696J**
Make & Model: MAZDA 3, 1.4 SEDAN 1.5L SP.6E (A) Engine No: P520432572
Reg. Date: 14/03/2017 (Man. Year: 2017) Chassis No: JM6BN22A8H0145198
Colour: Blue Odometer: 0 km
Engine Capacity: 1496 cc
Market Value/New Car Price: S\$53,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R15 Rear Tyre Size: 205/55 R15
Front Left Side: West Lake 4 mm Rear Left Side: West Lake 4 mm
Front Right Side: West Lake 4 mm Rear Right Side: West Lake 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 02/12/2021

Date Inspected: 02/12/2021 Inspected At:

Pegasus Engineering & Trading Pte Ltd (Kian Teck)
74 Kian Teck Road
Singapore 628800

Estimated Period of Repair: 0.0 days

Adjuster: CHEN TSUE YEE

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

TOTAL LOSS ASPECT

Market Value :	\$53,000.00
OMV :	\$14,688.00
PARF Rebate (1) :	\$7,266.00
Quota Premium Paid :	\$49,430.00
COE Rebate (2) :	\$26,096.00
Total Rebate (1) + (2) = :	\$33,362.00

The total amount incurred will be Market Value \$53,000.00 minus Total Rebate \$33,362.00 = \$19,638.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 25 Jan 2022)

Parts: 143 MAZDA 3 1.4 SEDAN 1.5L SP.6E (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLL8696J)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >