

ComfortDelGro Engineering Pte Ltd 59 Loyang Drive Singapore 508969

| Our Ref | : 305496497 | Via Fax | :Email |
|-----------------|-------------------|--------------|------------|
| Date | 16-61-60 | Your Insured | SLT 9433C |
| Time of Fax | : | Date of Acc | : 01.12-21 |
| Attn: Motor Cla | aims DepartmentAC | 1 | |

Dear Sirs

SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO. SH _C 3787P.

Our client has engaged us to repair the above vehicle and submit claims against the other party/parties-involved in the accident.

In accordance to the motor claims framework, we hereby request your presence at 59 Loyang Drive, Singapore 508969 to survey our client's damaged vehicle.

Enclosed, please find:

- i) Our initial estimate of repairs of the damaged vehicle;
- ii) Accident report made by our client.

I would appreciate it if you could call us to arrange for the survey of the vehicle:

Ms. Loke Wei Yieng (yy) Tel: 62148355 or HP: 86285336 e Jumani Bin Masudin Tel: 6214 8315 or HP: 9635 5305 e Lim Tien Siong Tel: 6214 8398 or HP: 9635 8546 e Chiang Liat Choon Tel: 6214 8314 or HP: 9296 6006 Indicate the control of the contro

If we do not hear from you within the next 48 hours, we shall deem that you have waived your rights to survey our client's vehicle and we shall proceed to engage independent surveyor without further reference to you. We henceforth reserve our rights to claim for Loss of Use and Loss of Rental during any delayed period of this survey arrangement.

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the Insurance company.

Thank you.

Yours faithfully

For Vice President Taxi Accident Repair

COMFORT TRANSPORTATION PTE LTD

REPAIR ESTIMATE

Vehicle No.: SHC2787PDate: 02/12/21Make: HYUNDAIInsurance: AIG

Model: IONIQ(G3) MVA: MS. LOKE YY

| Qty | Parts Description / Labour | Туре | Unit Price | Amount |
|-----|------------------------------------|------|------------|------------|
| | 1 REAR BUMPER COVER | | | \$459.40 |
| 1 | REAR BUMPER CLIPS | | | \$22.00 |
| | 1 REAR BUMPER CENTRE MOULDING ASSY | | | \$451.25 |
| | 1 REAR BUMPER REINFORCEMENT | | | \$394.80 |
| | SUB TOTAL | | | \$1,327.45 |
| | LESS 20% | | | \$265.49 |
| | DISCOUNTED TOTAL | | | \$1,061.96 |
| | REAR FENDER ADVERTISEMENT LOGO LH | | | \$100.00 |
| • | REAR FENDER ADVERTISEMENT LOGO RH | | | \$100.00 |
| • | REAR BUMPER REVERSE SENSOR | | | \$180.00 |
| | | | | \$380.00 |
| | Labour Charge | | | |
| | PANEL BEATING | | | \$400.00 |
| | SPRAY PAINTING CHARGE | | | \$300.00 |
| | REMOVE/REFIX REVERSE SENSOR | | | \$60.00 |
| | TOTAL LABOUR | | | \$760.00 |
| | ESTIMATE TOTAL | | | \$2,201.96 |

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.



ComfortDelGro Engineering Pte Ltd 205 Braddell Road Singapore 579701 Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops
205 Braddell Road Singapore 579701
59 Loyang Drive Singapore 508969
383 Sin Ming Drive Singapore 575717

Date/Time: 02.12.2021 11:16

Page: 1

'eam:

" pie

ARC Repair TP(CLSO)1

JOB CARD Sales Order: 4147656

JC NO305496497

STOMER

COMFORT TRANSPORTATION PTE LTD

7010045

STOMER NO. 7010045
DRESS 383 SIN MING DRIVE DRESS

Singapore SINGAPORE 575717

65508755 (R)

(O)

(P)

COUNT CARD NO.

| REGN NO.: SHC2787P | MILEAGE |
|-----------------------------------|-----------------------|
| MAKE: HYUNDAI | FUEL E _b F |
| MODEL IONIQ(G3) 02. | 12.2021 09:25 |
| YR OF MANU. 30.10,2019 | TARGET DATE |
| CHASSIS CODE KMHC851CVLU187607 | COMPLETION DATE/TIME: |


JOB DESCRIPTION

ccident Date: 01.12.2021 [ATURE: 3P 01.12.2021 '

I/NO

LABOR CODE

DESCRIPTION



| CKED & PASSED OUT BY: | s. | | 13 | |
|-----------------------|----------------------|------------------|----------------------|--|
| SERVICE ADVISOR | | CUSTOMER'S SIGNA | CUSTOMER'S SIGNATURE | |
| wledgement Slip | Exit Pass | | | |
| No.: SHC2787P YY | Vehicle No.: SHC2787 | P | | |

of Service Advisor

Signature/Date

Name of Service Advisor

Date

eturned to Service Reception upon collection

To be kept by Security Guard