

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
 TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg
 GST:201006949C RCB NO:201006949C

M/S : VSP PTE LTD
 6 PENJURU PLACE #01-33
 PENJURU TECH HUB S(608781)

Estimate No: **EST1507591**
 Date: 30 Nov 2021
 Policy No: 20-MS003674-R01
 Veh Reg No: **GBF8849K**
 Make/Model: TOYOTA DYNA 150 5MT
 Chassis No: JTFAT35Y20K207643
 Engine No: 1KD2688595
 Reg. Date: 31/03/2017

ATTN: INDIA
 Your Ref No: TP 1121-6573
 Claim Type: Third Party
 Accident Date: 30/11/2021
 TP Veh Reg No: GBD 6267 M

Estimate Repair Cost to Vehicle No :GBF8849K

Description	U/Price	Quantity	Price	Amount
			<u>S\$</u>	<u>S\$</u>
List Price				
1 SIDE MIRROR W/BACKET ASSY - L	606.0000	1 PCS	606.00	
2 AIRCON CONDENSER W/FAN NOTOR ASSY, SMALL - LH	1,980.000	1 PC	1,980.00	
3 FRONT STEP GARNISH - LH	300.0000	1 PCS	300.00	
4 DYNA WORDING - CHROME	80.0000	1 PCS	80.00	
5 GRILLE TOP SEAL - GRAY COLOUR	0.0000	1 PCS	0.0000	
6 GRILLE ASSY	572.0000	1 PCS	572.00	
7 GRILLE LOGO - CHROME	90.0000	1 PCS	90.00	
8 GRILLE CLIPS - WHITE	5.0000	8 PCS	40.00	
9 GRILLE CLIPS - GREEN	8.0000	8 PCS	64.00	
10 HEADLAMP UNIT - LH	1,000.000	1 PCS	1,000.00	
11 HEADLAMP LOWER SEAL - LH	0.0000	1 PCS	0.0000	
12 CORNER PANEL - LH	282.0000	1 PCS	282.00	
13 FRONT BUMPER	545.0000	1 PC	545.00	
14 FRONT BUMPER BRACKET - RH/LH	255.0000	2 PC	510.00	
15 FRONT BUMPER REINFORCEMENT	190.0000	1 PC	190.00	
16 FRONT BUMPER COVER - LH	80.0000	1 PC	80.00	
17 FRONT DOOR - LH	1,600.000	1 PC	1,600.00	
18 FRONT DOOR RUBBER, FRONT - LH	65.0000	1 PC	65.00	
19 FRONT DOOR RUBBER - RH	195.0000	1 PC	195.00	
20 FRONT DOOR HINGE - LH	95.0000	2 PC	190.00	
			8,389.00	
		Less 25%	2,097.25	6,291.75
Special Net				
21 FRONT COMPANY REG STICKER	30.0000	1 PC	30.00	
			30.00	30.00
Labour				
22 TO KNOCK OUT DENTS, A PILLAR LH, REMOVE, REPLACE ACCIDENT PARTS	500.0000	1 JOB	500.00	
23 TO RESPRAY PAINT ON ACCIDENT PORTIONS	600.0000	1 JOB	600.00	
24 TO CHECK WIRING	20.0000	1 JOB	20.00	
25 TO TRANSFER DOOR AND DOOR FITTING	60.0000	1 JOB	60.00	
26 TO TUFF-KOTE	30.0000	1 JOB	30.00	
			1,210.00	1,210.00

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716
TEL: 6741 5336 FAX: 6741 7208 Email: claims@procarcare.com.sg
GST:201006949C RCB NO:201006949C

M/S : VSP PTE LTD
6 PENJURU PLACE #01-33
PENJURU TECH HUB S(608781)

ATTN: INDIA
Your Ref No: TP 1121-6573
Claim Type: Third Party
Accident Date: 30/11/2021
TP Veh Reg No: GBD 6267 M


Estimate No: EST1507591
Date: 30 Nov 2021
Policy No: 20-MS003674-R01
Veh Reg No: GBF8849K
Make/Model: TOYOTA DYNA 150 5MT
Chassis No: JTFAT35Y20K207643
Engine No: 1KD2688595
Reg. Date: 31/03/2017

Estimate Repair Cost to Vehicle No :GBF8849K

Description	U/Price	Quantity	Price	Amount
			<u>S\$</u>	<u>S\$</u>
		Total		S\$ 7,531.75
		Add GST @ 7%		527.22
		Total Amount Payable		<u>S\$ 8,058.97</u>

TOTAL: SINGAPORE DOLLAR EIGHT THOUSAND FIFTY EIGHT AND CENTS NINETY SEVEN ONLY

For Progressive Car Care Pte Ltd



AUTHORISED SIGNATURE