SIN HOCK LEE MOTOR REPAIR

UEN NO. 24928500B GST NO. M90366191A

BLK 51 UBI AVENUE 1 #01-09

PAYA UBI INDUSTRIAL PARK SINGAPORE 408933

Tel No.: 6282 6184 Fax: 6287 5977

TUBE INNOVATION 13 OLD AIRPORT ROAD #01-55

SINGAPORE 390013

LKK Auto Consultants hence notify

the Repairer of the following: . To resurvey before/after spray painting

- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- . Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

· Supplementary item(s) must be resurveyed and

is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimate : ES211201-8852

Date: 06/12/2021 Vehicle Num.: GBE8852E

Chassis No: YARXT9HM0DZ070923

Accident Date: 29/11/2021

S/N	Quantity	Particular	Unit Price	Amount S\$
1 2 3 4 5 7	1 1 2	FRONT HEAD LAMP LH FRONT HEAD LAMP APRON PANEL LH FRONT BUMPER FRONT BUMPER SIDE RETAINER RH / LH FRONT FENDER LH FRONT FENDER INNER SHIELD LH Sub-Total List Parts S\$: Discount 25% Total List Parts S\$:	860.00 280.00 1,350.00 105.00 780.00 350.00	860.00 / S(280.00 / Y 280.00 / Y 280.00 / Y 210.00 % 140 Cra 780.00 DT 580 350.00 (4 145 3,830.00 195 2,872.50 nec 40
1	10	NETT ITEMS:: FRONT BUMPER CLIP SET Sub-Total Nett Parts S\$: Discount 0% Total Nett Parts S\$:	8.00_	80.00 80.00 0.00 80.00
		Total Parts S\$:	-	2,952.50
1 2 3	1 1	TO CHECK & RECTIFY WIRING SYSTEM TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS TO RE-SPRAY PAINTING ON THE CHANGED BODYPARTS, REPAIRED PORTION, & WHERE CONSISTENT TO THE ACCIDENT		80.00 1,000.00 400 450 1,200.00 400 450 2,280.00
		Labour Total S\$:		,

for SIN HOCK LEE MOTOR REPAIR

Note: This is only an estimate based on our premilinary inspection and does not cover additional labour time or which may be required after the work has begun.

E. & O.E.

Sub-Total S\$: **GST 7%**

5,232.50 366.28

5,598.78 Total S\$:

2388 2400

Udays