



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS3/SMR21012262/Rqf3e2	
			Date: 14/03/2022	
			Code: SMR	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	SG 5833T	Veh. Inspected	SMP 6643S	
Policy No.		Coverage (\$)	0.00	
Claim No.	BUS/11/21/5048	Excess (\$)	0.00	
Assign From	HUA YEN	Assign Date	03/12/2021	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA C-HR HYBRID 1.8S CVT	c.c	1797	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	ZYX102164212	Colour	YELLOW	
Odometer	120126 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R17	MICHELIN	6 mm	
L/H Front Tyre	215/60 R17	MICHELIN	6 mm	
R/H Rear Tyre	215/60 R17	MICHELIN	6 mm	
L/H Rear Tyre	215/60 R17	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.				
5. General Information				
Accident Date	30/11/2021	Inspection Date	03/12/2021	
Survey held at	ENG HUP AUTOPARTS ACCESSORIES CO. 387J BLK 1 WOODLANDS ROAD SINGAPORE 677899			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000-\$5,000				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	