

**Note: This document has not been finalised.**

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: ERGO Insurance Pte. Ltd.  
8 Temasek Boulevard  
#04-01 Suntec Tower Three  
Singapore 038988

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn:

Date: 21 Feb 2022

**Preliminary Advice**

Insured : YN8849X

Vehicle No

TP Vehicle : SLP5255Y  
No

Accident Date : 02/12/2021

Make : MAZDA 5

Assignment Date : 03/12/2021

Date of : 03/12/2021  
Inspection

Est. Duration of : 5  
Repair

Inspection At : ALFRED AUTO SERVICES & SUPPLIES (HQ)  
BLK 5035, ANG MO KIO AVE 3, #01-351, ANG MO KIO  
INDUSTRIAL PARK 2  
SINGAPORE 569538

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	17,359.80
Revised Amount	:S\$	5,650.56
Check Items (Estimated)	:S\$	0.00
Total	:S\$	5,650.56

Lump Sum Repair	:S\$	4,500.00
-----------------	------	----------

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$

Salvage Value	:S\$
Margin for Repair	:S\$

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.