

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5965S**AAD2111-121***Not Authorised*
11/11/2018 \$4250/p

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

06 DEC 2021**SHD5965S**

JTDKB3FU703075517

TOYOTA

PRIUS

20/11/2021

LONPAC

01/11/2018

	PART
1	HOOD SUB-ASSY
1	HINGE ASSY, HOOD, LH
1	HINGE ASSY, HOOD, RH
1	LOCK ASSY, HOOD
1	COVER, FRONT BUMPER
1	ABSORBER, FRONT BUMPER ENERGY
1	REAR BUMPER REINFORCEMENT
1	UNIT ASSY, HEADLAMP, LH
1	UNIT ASSY, HEADLAMP, RH
1	GRILLE SUB-ASSY, RADIATOR
1	EMBLEM ASSY, RADIATOR GRILLE
1	GRILLE, RADIATOR, LOWER NO.1

	LIST
\$	<i>N</i> 983.10 <i>X</i>
\$	<i>N</i> 58.90 <i>X</i>
\$	<i>N</i> 58.90 <i>X</i>
\$	<i>N</i> 135.00 <i>X</i>
\$	<i>Bu</i> 516.00 <i>—</i>
\$	<i>Sn</i> 79.60 <i>X</i>
\$	<i>N</i> 332.70 <i>✓</i>
\$	<i>mbcm</i> 2,637.60 <i>✓</i>
\$	<i>u</i> 2,637.60 <i>✓</i>
\$	<i>dit</i> 346.00 <i>—</i>
\$	<i>cm</i> 90.80 <i>—</i>
\$	<i>dit</i> 170.10 <i>✓</i>

TOTAL	\$	8,046.30
25%	\$	2,828.00
	\$	8,484.00

Special Nett

1SET	FRONT BUMPER CLIP
1	FRT NUMBER PLATE WITH MOULDING
1	FRT BUMPER SIDE RETAINER CLIP

\$	<i>N</i>	90.00	<i>505A</i>
\$	<i>N</i>	200.00	<i>455A</i>
\$	<i>nn</i>	75.00	<i>X</i>
TOTAL	\$	365.00	

TOTAL PARTS	\$	9,530.50
--------------------	-----------	-----------------

LABOUR

Trans-cab Auto Services Pte Ltd**AAD2111-121**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD5965S

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	3,000.00	2001
	\$	~ 380.00	X
To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	~ 240.00	X
To check steering geometry and computer wheel alignment	\$	~ 220.00	X
Putty And Spray Painting Of The Affected Portion.	\$	1,600.00	2201
To Check Electrical Lighting Concerned.	\$	170.00	201

TOTAL \$ 5,610.00**Over All Total \$ 14,459.00****(PART-BY-PART) Repair Days****20 days**
2 days**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer**Signature:****Date:**