

TP A19.
Xiao Tong.

SLN8606J. 2017 May.
Suzuki Swift. 1586cc
JSAFZC 32S00400026

Rees Number Plate	^{MP} MP	30(SN) X
Rees Number Plate Lamp x 02	^{MP} MP	45x2=90 X
Rees Bumper	Reps	637.60. X
Rees Bumper Clips.	New	30(SN) ✓
Rees Bumper Side Holder x 02.	^{MP} MP	38x2=76. X
Rees Bumper lower Garnish	Del'd	308.40. ✓
Reverse Sensor	Del'd	280(SN) LW(SN)
Tail Lamp x 02.	^{MP} MP	315x2=630 X

308.40 S/N: 230
25908

SLN 8606 J.

Panel Beating

~~400~~ 200

Spray Painting

~~600~~ 250

530

Wiring.

~~50~~ 30

To remove Reverse Sensor

~~100~~ 50

total: 1018.08

h/s: 800 ✓

02 Days

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: