

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733
Co. & GST Reg. No.: 199902271W

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 1 09:56

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120		Invoice No: 85017394 Date : 20/04/2022 Order : SFY806P Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120		
Regn No: SFY806P (V 47457)		Regn Date: 17/11/2020	Mileage: 15588	WIP No.: 56503	
Model: A4 2.0 TFSI S tronic 8WCA9G		Chassis: WAUZZZF42MA011901	Engine: DEM 026746	Dept: U	
You have been assisted by :- UB-Lim Kee Siang (43)					
		Details	Qty	Unit Price	Amount
Q	EXC	M: 8888 Insurance Excess/Liability	-1100.00	1.00	-1,100.00
S	BODYWORK	M: TO REMOVE AND TRANSFER RHS FRONT DOOR AND RHS REAR DOOR'S MULTI LOCK SYSTEM AND POWER WINDOW DEVICES.INSPECT FOR DAMAGE.	560.00	1.00	560.00
S	BODYWORK	M: TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR.CHECK FUNCTION.	360.00	1.00	360.00
S	BODYWORK	M: TO RENEW REAR WINDSCREEN AND 1/4 GLASS TO FACILITATE RENEWAL OR RHS REAR FENDER	600.00	1.00	600.00
S	BODYWORK	M: TO CARRY OUT WATER SEEPAGE TEST FOR REAR WINDSCREEN	150.00	1.00	150.00
S	BODYWORK	M: TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS,BATTERY MANAGER,FUSE AND RELAY TRAYS,ELECTRICAL AND AUDIO EQUIPMENT.INSPECT FOR DAMAGED AND RENEW WHERE NECESSARY.	1400.00	1.00	1,400.00
S	BODYWORK	M: TO REMOVE AND REINSTALL REAR SEAT,BACK REST, HAT TRAY,ABCD PILLAR TRIMS,LUGGAGE COMPARTMENT TRIMS.DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG.	1400.00	1.00	1,400.00
S	BODYWORK	M: TO DISMANTLE AND REINSTALL FRONT BUMPER AND REAR BUMPER.TO CUT OUT AND WELD RHS REAR FENDER.TO RENEW RHS FRONT FENDER,RHS FRONT DOOR AND RHS REAR DOOR.REORGANISE CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED.	4000.00	1.00	4,000.00
S	BODYWORK	M:	3925.00	1.00	3,925.00

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733
Co. & GST Reg. No.: 199902271W

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 2 09:56

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice No: 85017394 Date : 20/04/2022 Order : SFY806P Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	---	--

Regn No: SFY806P (V 47457) Regn Date: 17/11/2020 Mileage: 15588 WIP No.: 56503
Model: A4 2.0 TFSI S tronic 8WCA9G Chassis: WAUZZZF42MA011901 Engine: DEM 026746 Dept: U
You have been assisted by :- UB-Lim Kee Siang (43)

		Details	Qty	Unit Price	Amount
S	BODYWORK	TO RESPRAY REAR BUMPER, RHS FRONT FENDER, RHS FRONT DOOR, RHS WING MIRROR COVER, DOOR HANDLE, RHS REAR DOOR, RHS REAR FENDER, RHS SILL PANEL AND REAR END PANNELLING. M:	192.00	1.00	192.00
S	BODYWORK	TO CARRY OUT DIAGNOSTIC CHECK M:	1080.00	1.00	1,080.00
Q	OTHERS	TO SUPPLY ACRYLIC SEALANT, CAVITY WAX, STONE CHIP, METAL FILLER POWDER, 1/4 GLASS SEALANT AND REAR WINDSCREEN SEALANT. M:	400.00	1.00	400.00
X	A8W0831052B	TO INSTALL SOLAR FILM FOR REAR WINDSCREEN, 1/4 GLASS AND RHS FRONT DOOR WINDOW GLASS. DOOR Less 020%	1.00	3192.00	2,553.60
X	A8W0837912A	SEAL Less 020%	1.00	205.00	164.00
X	A8W2857410G 9B9	MOUNTING Less 020%	1.00	1089.00	871.20
X	A8W0857528 GRU	CAP Less 020%	1.00	289.00	231.20
X	A8W0857536H	MIRROR Less 020%	1.00	1667.00	1,333.60
X	A8W0837644C 2ZZ	009555/(V) (GER) TRIM- Less 020%	1.00	256.50	205.20
X	A8W5833052D	DOOR Less 020%	1.00	3192.00	2,553.60
X	A8W5839912C	SEAL Less 020%	1.00	205.00	164.00
X	A8W0837210A	PACKING-A/P GT Less 020%	1.00	3.60	2.88
X	A8W5809838A	009555/(V) (GER) SUBPA Less 020%	1.00	4052.00	3,241.60
X	AN 91233601	(LOC9)NUT Less 020%	2.00	3.00	4.80
X	A8W5845501F NVB	009555/(SK) (2) REARWI Less 020%	1.00	1154.00	923.20
X	A8W5845298H NVB	SIDE WINDO Less 020%	1.00	655.50	524.40
X	AD 00920002	PRIMER Less 020%	2.00	19.70	31.52
X	A8W0809906D	009555/(GER) INSERT-0 Less 020%	1.00	88.80	71.04
X	A8W0837240 GRU	TRIM Less 020%	1.00	87.40	69.92
X	A8W0837167	(A) (SK) (6) HOUSING-06 Less 020%	1.00	7.40	5.92
X	A8W0837878	COVER Less 020%	1.00	5.80	4.64
X	A8W0927754	SENSOR-A/P GT Less 020%	1.00	228.00	182.40
X	A8K9805673C	GROMMET-A/P GT Less 020%	1.00	1.60	1.28
X	A8W009012A	BOLT-A/P GT Less 020%	1.00	9.70	7.76

