

Attention: Motor Claim Department
RE: VEHICLE NO : XE5117D HINO 700 EURO 6 (SH COGENT LOGISTICS PTE LTD)

ESTIMATE
DATE : 1/12/2021
ACC DATE : 30/11/2021
SHEET NO. 1 OF 1 SHEET

S/NO.	QTY	DESCRIPTION	UNIT PRICE S\$	AMOUNT S\$
1	1	FRONT CORNER PANEL		655.00
2	1	FRONT CORNER PANEL LAMP		450.00
3	1	FRONT SIDE MIRROR BRACKET		468.00
4	1	FRONT SIDE MIRROR ARM LH		896.00
5	1	FRONT DOOR		4,898.00
6	1	FRONT DOOR (EURO 6) STICKER		189.00
7	1	FRONT DOOR OUTER LOWER MOULDING		368.00
8	1	FRONT DOOR OUTER LOWER INNER FRAME		898.00
9	1	FRONT DOOR SIGNAL LAMP		210.00
10	2	FRONT DOOR HINGE		470.00
11	1	FRONT DOOR CHECKER		325.00
12	1	FRONT DOOR INNER LOCK		792.00
13	1	FRONT DOOR TRIM LH		4,568.00
14	1	FRONT DOOR LINKAGE		789.00
				\$ 12,976.00

S/NO.	QTY	LABOUR & MISCELLANEOUS :	AMOUNT S\$
1	1	To remove damaged body panel with all necessary components/attachments apply hot-works where necessary straighten front door pillar, repair/reshape body dented panels in accordance with factory specifications replace new parts refit and align into position refit all necessary components / attachments	1,200.00
2	1	To spray paint replaced/repared body panels inclusive of preparatory works and painting materials	1,000.00
3	1	To check, diagnosis, trouble shoot, reset all the wiring fault code	120.00
4	1		

ISSUED BY

KOH WENG SHENG

KOH WENG SHENG

ESTIMATE CONFIRMED AND ACCEPTED BY

NAME, SIGNATURE, DATE SIGNED

Steve (LKK)
3/12/21, 5:11pm
DD- M AL
EX 011-?
L/S

My AL sy
4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: