

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: China Taiping Insurance
(Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Tan Kah Leong

Date: 13 Dec 2021

Preliminary Advice

Vehicle No	: XE5117D	Accident Date	: 30/11/2021
Make	: HINO SH1EEMA-KAS	Policy No.	: DMCVSNA00147682100
Assignment Date	: 03/12/2021	Excess	: S\$2,500.00
Date of Inspection	: 03/12/2021	Est. Duration of Repair	: 4
Inspection At	: VFIX AUTO PTE LTD 7 PENJURU CLOSE LEVEL 1 SINGAPORE 608779		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$ 18,836.00	(Estimate \$15,296.00 + Supplementary \$3,540.00)
Revised Amount	:S\$ 10,895.00	(Inclusive of supplementary)
Check Items (Estimated)	:S\$ 3,474.00	
Total	:S\$ 14,369.00	
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$ 150,000.00
COE / PARF Rebate	:S\$ 21,455.00
Salvage Value	:S\$
Margin for Repair	:S\$ 128,545.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : KINDLY APPROVE ON SUPPLEMENTARY.