

ASS. REQ. BY:

REF:

TMI/

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

854,064/2

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

12

days

Res.: Yes or No

Lum Sum:

1.31 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

S/HB 7779K

Yr Regn:

08, 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Prius

c.c

1798

Colour

M.P. White / PW

A/C:

Insured / Std / Nil / NA

Sp. Reading

T/Radio: Insured / Std / Nil / NA

Eng/No:

C/No:

JTDKB3FU503083339

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD / RIM or

Tyre Size:

F:

195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Pailan

Front

Rear

R/Bal.

9

mm

R/Bal.

7

mm

L/Bal.

9

mm

L/Bal.

7

mm

D.O.A.

27/11/21

D.O.I.

1/12/2021

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

N/S Fnt & Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1

Got BZ, battery flat

1/12

Max repair bill \$26,500

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. \$

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB7779K*Not Withheld***AAD2111-157***11 Sep @
Puchong After Rain*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

01 DEC 2021**SHB7779K**

JTDKB3FU503083339

TOYOTA

PRIUS

27/11/2021

Taka

30/08/2019

PART**LIST**

1	COVER, FRONT BUMPER	\$	R	516.00	✓
1	BRACKET, FRONT BUMPER EXTENSION MOUNTING	\$	DR	103.40	✓
1	REINFORCEMENT SUB-ASSY, FRONT BUMPER	\$	R	716.60	✓
1	REINFORCEMENT, FRONT BUMPER, NO.2	\$	R	246.10	✓
1	ABSORBER, FRONT BUMPER, LOWER	\$	CM	132.70	✓
1	ABSORBER, FRONT BUMPER ENERGY	\$	CM	79.60	✓
1	SUPPORT, FRONT BUMPER SIDE, RH	\$	DR	80.10	✓
1	SUPPORT, FRONT BUMPER SIDE, LH	\$	R	82.30	✓
1	COVER, ENGINE UNDER, NO.1	\$	CM	472.40	✓
1	COVER SUB-ASSY, ENGINE UNDER, NO.2	\$		241.90	?
1	EXTENSION, FRONT BUMPER, RH	\$	SL	120.10	X
1	EXTENSION, FRONT BUMPER, LH	\$	DR	120.10	✓
1	COVER, FRONT BUMPER HOLE, LH	\$	MR	29.30	✓
1	COVER, FRONT BUMPER HOLE, RH	\$	MR	29.30	✓
1	COVER SUB-ASSY, FRONT PILLAR, UPR LH	\$		100.40	?
1	LAMP ASSY, FOG, LH	\$	CM	951.40	✓
1	LAMP ASSY, FOG, RH	\$	SL	951.40	X
1	UNIT ASSY, HEADLAMP, LH	\$	CM	2,637.60	✓
1	COMPUTER SUB-ASSY, HEADLAMP, LH NO.1	\$		960.50	?
1	UNIT ASSY, HEADLAMP, RH	\$	MR	2,637.60	✓
1	COMPUTER SUB-ASSY, HEADLAMP, RH NO.1	\$	SL	960.50	X
1	MOTOR, HEADLAMP LEVELING, RH	\$		487.50	?
1	GRILLE SUB-ASSY, RADIATOR	\$	CM	346.00	✓
1	GRILLE, RADIATOR, LOWER NO.1	\$	CM	170.10	✓
1	EMBLEM ASSY, RADIATOR GRILLE	\$	MR	90.80	✓
1	COVER SUB-ASSY, FRONT PILLAR, UPR LH	\$	DR	100.40	✓
1	SUPPORT, RADIATOR, UPPER RH	\$	R	78.90	X
1	SUPPORT, RADIATOR, UPPER LH	\$	R	78.90	✓

Trans-cab Auto Services Pte Ltd**AAD2111-157**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB7779K

1	SUPPORT SUB-ASSY, RADIATOR, UPPER	\$	B ₁	377.10	✓
1	SUPPORT SUB-ASSY, RADIATOR, LOWER	\$	B ₁	409.90	✓
1	SUPPORT SUB-ASSY, RADIATOR, LH	\$	B ₁	245.10	✓
1	SUPPORT SUB-ASSY, RADIATOR, RH	\$	R	245.10	X
1	HOOD SUB-ASSY	\$	B ₁	983.10	✓
1	HINGE ASSY, HOOD, LH	\$	B ₁	58.90	✓
1	HINGE ASSY, HOOD, RH	\$	B ₁	58.90	✓
1	BRACE, HOOD LOCK SUPPORT	\$	B ₁	78.30	✓
1	INSULATOR, HOOD	\$	Return	410.90	✓
1	LOCK ASSY, HOOD	\$	B ₁	135.00	✓
1	SEAL, HOOD TO FRONT END PANEL	\$		51.60	?
1	WIRE, ENGINE ROOM MAIN	\$	CM	7,323.90	?
1	HORN ASSY, HIGH PITCHED	\$		134.80	?
1	HORN ASSY, LOW PITCHED	\$		134.80	?
1	GUIDE, RADIATOR AIR, NO.1 LH	\$	CM	69.90	✓
1	GUIDE, RADIATOR AIR, NO.1 RH	\$	SM	65.30	X
1	GUIDE, RADIATOR AIR, NO.3	\$		112.70	?
1	GUIDE, RADIATOR AIR, NO.2	\$		53.40	?
1	SEAL, RADIATOR TO SUPPORT, NO.3	\$		29.60	?
1	SEAL, RADIATOR TO SUPPORT, NO.2	\$		29.60	?
1	INLET, AIR CLEANER, NO.1	\$		155.60	?
1	INLET, AIR CLEANER, NO.3	\$		42.10	?
1	INLET, AIR CLEANER, NO.2	\$		112.70	?
1	HOSE, AIR CLEANER, NO.1	\$		74.00	?
1	JAR ASSY, WINDSHIELD WASHER	\$	SM	219.10	X
1	MOTOR AND PUMP ASSY, WINDSHIELD WASHER	\$	SM	292.40	X
1	INLET SUB-ASSY, WASHER	\$	SM	67.00	X
1	CONDENSER ASSY, COOLER	\$	B ₁	1,783.20	✓
1	HOSE SUB-ASSY, SUCTION	\$		646.80	?
1	HOSE SUB-ASSY, DISCHARGE	\$		402.90	?
1	PIPE SUB-ASSY, SUCTION	\$		465.80	?
1	SENSOR, AIRCONDITIONER PRESSURE	\$		342.80	?
1	TUBE & ACCESSORY ASSY, AIR CONDITIONER	\$		691.00	?
1	COMPRESSOR ASSY, W/MOTOR	\$		4,771.60	?
1	RADIATOR ASSY	\$	B ₁	2,218.00	✓
1	SHROUD, FAN	\$	CM	264.70	✓
1	FAN, RH	\$	CM	281.30	✓

Trans-cab Auto Services Pte Ltd**AAD2111-157**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB7779K

1 FAN, LH	\$	219.10	?
1 MOTOR, COOLING FAN, LH	\$	655.10	?
1 MOTOR, COOLING FAN, RH	\$	535.50	?
1 TANK ASSY, INVERTER RESERVE	\$	443.00	?
1 INVERTER WATER PUMP ASSY(W/MOTOR)	\$	518.60	?
1 BATTERY	\$	1,584.90	?
1 CLAMP, BATTERY, NO.2	\$	51.80	X
1 CLAMP SUB-ASSY, BATTERY	\$	115.50	X
1 TERMINAL, BATTERY POSITIVE	\$	58.10	X
1 COVER, FUSIBLE LINK	\$	33.90	X
1 SENSOR ASSY, BATTERY STATE	\$	306.10	?
1 BLOCK ASSY, FUSIBLE LINK	\$	119.60	?
1 TANK, RESERVE SEALED W/O CAP	\$	151.40	?
1 CLEANER ASSY, AIR	\$	1,147.00	?
1 BRACKET, HEADLAMP, LH	\$	34.80	—
1 BRACKET, HEADLAMP, RH	\$	34.80	X
1 STAY SUB-ASSY, FRONT BUMPER, LH	\$	47.50	—
1 STAY SUB-ASSY, FRONT BUMPER, RH	\$	47.50	X
1 BRACKET, FRONT BUMPER SIDE, LH	\$	59.30	—
1 BRACKET, FRONT BUMPER SIDE, RH	\$	59.30	X
1 BRACKET, RADIATOR GRILLE MOUNTING, LH	\$	36.60	?
1 BRACKET, RADIATOR GRILLE MOUNTING, RH	\$	36.60	?
1 MEMBER SUB-ASSY, FRONT SIDE, RH	\$	2,342.30	?
1 COVER, RADIATOR SUPPORT OPENING	\$	235.30	?
1 THERMISTOR ASSY	\$	80.90	?
1 ACTUATOR ASSY, SHIFT CONTROL	\$	1,036.40	?
1 COOLER, MOTOR COOLING	\$	297.20	?
1 MOULDING ASSY, BODY ROCKER PANEL, LH	\$	594.80	—
1 MIRROR ASSY, OUTER REAR VIEW, LH	\$	1,339.30	X
1 FENDER SUB-ASSY, FRONT LH	\$	977.80	—
1 LINER, FRONT FENDER, LH	\$	202.50	—
1 EMBLEM, SIDE PANEL	\$	54.60	—
1 PANEL SUB-ASSY, FRONT DOOR, LH	\$	1,300.70	X
1 TAPE, BLACK OUT, NO.2 FRT LH	\$	43.50	X
1 TAPE, BLACK OUT, NO.1 FRT LH	\$	13.30	X
1 TAPE, BLACK OUT, NO.3 FRT LH	\$	26.30	X
1 RIM	\$	1,900.10	—

Trans-cab Auto Services Pte Ltd

AAD2111-157

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB7779K

1	ABSORBER ASSY, SHOCK, FRONT LH	\$	B ₁	438.30	✓
1	ARM SUB-ASSY, FRONT SUSPENSION, LOWER NO.1 LH	\$	B ₁	760.10	✓
1	KNUCKLE, STEERING, LH	\$	B ₁	663.40	✓
TOTAL		\$		55,963.60	
25%		\$		13,990.90	
		\$		41,972.70	

Special Nett

1SET BUMPER CLIP FRT	\$	M	95.00	505N
1 FRONT NUMBER PLATE WITH MOULDING	\$	B ₁	200.00	455N
1SET CLIP, FRONT FENDER LINER	\$	M	85.00	✓
1SET FRNT BUMPER RETAINER CLIP	\$	nn	85.00	✓
4L Radiator Coolant	\$	M	120.00	505N
1 HOOD INSULATOR CLIP	\$	M	55.00	✓
1 Engine Under Cover Clip	\$	M	60.00	✓
1 DOOR STICKER 'TRANSCAB'	\$	M	100.00	505N
1 TYRE	\$	P ₁	350.00	909N
TOTAL	\$		1,150.00	

TOTAL PARTS \$ 43,122.70**LABOUR**

To Remove And Refit Rear Big and Small W/Screen Glass To Facilitate Bodywork Repair.

\$ nn 300.00 X

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ nn 380.00 X

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$ 2,200.00 909N

To transfer of rear end panel fittings, attachment and perform water seepage test.

\$ nn 380.00 X

To transfer of Tailgate fittings, attachments and perform water seepage test.

\$ nn 180.00 X

Trans-cab Auto Services Pte Ltd**AAD2111-157**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB7779K

To remove and refit electrical wiring, battery and other necessary items to facilitate bodywork repair.	\$	480.00	80
To transfer of Fender fittings, attachments and perform water seepage test.	\$	480.00	X
To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas.	\$	380.00	100
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00	?
To check steering geometry and computer wheel alignment	\$	220.00	60
To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	250.00	90
Towing Fees	\$	150.00	50
Putty And Spray Painting Of The Affected Portion.	\$	2,200.00	1320
To reinstall rear bumper parking sensor.	\$	170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	20
To transfer of luggage floor panel fittings, attachment and perform water seepage test.	\$	380.00	X
To transfer of tire, rim and on wheel balancing.	\$	220.00	20
To replace, refix and top up coolant for radiator	\$	170.00	50
To lift-up / out engine with gear box and refit.	\$	440.00	?
To remove and refit radiator support cross-member and other necessary items to enable bodywork repair.	\$	380.00	?

Trans-cab Auto Services Pte Ltd

AAD2111-157

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB7779K

To conduct and perform a comprehensive vehicle diagnostic check
and reset vehicle warning indicators.

	\$	380.00	X
TOTAL	\$	10,290.00	

Over All Total	\$	53,412.70
-----------------------	----	------------------

(PART-BY-PART) Repair Days

25 DAYS

12 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	29/11/2021 21:08 (SGT)
Date of Accident	27/11/2021 17:30 (SGT)
Exact Location of Accident	Near Block 1, Singapore
Additional Location Information	JUNCTION OF ZION ROAD AND TIONG BAHRU ROAD
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHB7779K
INSURED/POLICYHOLDER	
Is company?	Yes
Name Of Registered Owner	TRANS-CAB SERVICES PTE LTD_
Company Reg No	2XXXXXX78K
Email Address	claims@transcab.com.sg
Mobile Phone No	(Phone) +65-62876666
Alternative Phone No	(Office) +65-62876666

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	PRIUS 5DR HATCHBACK (AUTO)
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private hire
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Taxi
Transmission	Auto
CC	1767

INSURANCE COMPANY

Name of Insurance Company	AXA Insurance Pte Ltd
Type of Coverage	ThirdParty
Fleet Policy	Yes
Policy Number	VFX/P2413997
Cover Note Number	-

DRIVER

Name of Driver	SUM WAH CHEONG
NRIC No	SXXXX516G

Date Of Birth	31/05/1961
Occupation	Outdoor
Date Of Driving Pass	09/01/1981
Driving experience	40 YEARS AND 10 MONTHS
Gender	Male
Mobile Number	(Phone) +65-97880070
Alt. Phone Number	-
Email Address	claims@transcab.com.sg
Address	502A WOODLANDS DR 14
Address complement	#05-28
Postcode	731502
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Hirer
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Side Swipe
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	Yes
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

PASSENGER 1

Name	P1
Gender	Female

DETAILS OF POLICE ACTION

Was the accident reported to the police?	Yes
Police Station Name	Traffic Police
Police Station Phone No	(Phone) +65-65470000
Alt. Police Station Phone No	(Fax) +65-65474900
Police Station Address	10 Ubi Avenue 3 Singapore 408865
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT



REFER TO POLICE REPORT

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLU1002K
Vehicle Manufacturer	Honda



Policyholder's Signature
Date & Time:

Driver's Signature
(if driver is not the policyholder)
Date & Time:

VERIFIED BY AJAX MARS (ARC)
REPORTING OFFICER
WONG JIN KEAT

Reporting Centre Personnel's Signature
Name
NRIC/PPN No.:



**SINGAPORE
POLICE FORCE**

Police Station Of Origin:
Traffic Police
10 Lili Avenue 3 SINGAPORE 408665
Tel No: 65470000



1/202111200070

Page 1

Report No: 1/202111200070

CONTINUATION OF REPORT

Driver			
Name	SUM WAH CHEONG	ID No.	S1489516G
Related Vehicle	SHB7779K (Car)	Contact No.	97880070
Hospital/Clinic	SINGAPORE GENERAL HOSPITAL	Class of Driving Licence & Expiry Date	Class: 3 Date of Expiry: NIL
Date Treatment	27/11/2021	Date Discharge	27/11/2021
No. of Days granted Medical Leave	04	Degree of Injury	NIL

Brief Details.

ON THE ABOVE STATED DATE, TIME AND LOCATION

I WAS AT ZION RD TWDS HOOT KIAN RD X TIONG BAHRU RD. I WAS ON 2ND LANE AS THERE WAS ROAD WORK ON THE FIRST LANE. I WAS GOING STRAIGHT AND I WAS HIT ON LEFT SIDE OF MY TAXI AND I SWERVED TO THE RIGHT AND I COLLIDED INTO THE TRAFFIC LIGHT. CASE IS UNDER TP 10 MD NOOR EXT 65475201.

THATS ALL.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	878K

Vehicle Details

Vehicle No.:	5HB7779K
Vehicle to be Exported:	Yes
Intended Deregistration Date:	29 Nov 2021
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS 5DR HATCHBACK (AUTO)
Primary Colour:	Red
Manufacturing Year:	2018
Engine No.:	2ZR2C51280
Chassis No.:	JTDKB3FU503083339
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$26,605.00
Original Registration Date:	30 Aug 2019
First Registration Date:	30 Aug 2019
Transfer Count:	0
Actual ARF Paid:	\$14,247.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	29 Aug 2027
PARF Rebate Amount:	\$10,685.00

Intended COE Rebate Details

COE Expiry Date:	29 Aug 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$23,463.00
COE Rebate Amount:	\$16,864.00
Total Rebate Amount:	\$27,549.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory age (if applicable), whichever is earlier.

The information contained herein is correct as at 29 Nov 2021

OK