

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB7779K

AAD2111-157

Not Withheld
11 Sep @
Recovery After Pain

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

01 DEC 2021**SHB7779K**

JTDKB3FU503083339

TOYOTA

PRIUS

27/11/2021

ToKa

30/08/2019

PART**LIST**

1	COVER, FRONT BUMPER	\$	R	516.00	✓
1	BRACKET, FRONT BUMPER EXTENSION MOUNTING	\$	DR	103.40	✓
1	REINFORCEMENT SUB-ASSY, FRONT BUMPER	\$	R	716.60	✓
1	REINFORCEMENT, FRONT BUMPER, NO.2	\$	R	246.10	✓
1	ABSORBER, FRONT BUMPER, LOWER	\$	CM	132.70	✓
1	ABSORBER, FRONT BUMPER ENERGY	\$	CM	79.60	✓
1	SUPPORT, FRONT BUMPER SIDE, RH	\$	DR	80.10	✓
1	SUPPORT, FRONT BUMPER SIDE, LH	\$	R	82.30	✓
1	COVER, ENGINE UNDER, NO.1	\$	CM	472.40	✓
1	COVER SUB-ASSY, ENGINE UNDER, NO.2	\$		241.90	?
1	EXTENSION, FRONT BUMPER, RH	\$	SL	120.10	X
1	EXTENSION, FRONT BUMPER, LH	\$	DR	120.10	✓
1	COVER, FRONT BUMPER HOLE, LH	\$	MR	29.30	✓
1	COVER, FRONT BUMPER HOLE, RH	\$	MR	29.30	✓
1	COVER SUB-ASSY, FRONT PILLAR, UPR LH	\$		100.40	?
1	LAMP ASSY, FOG, LH	\$	CM	951.40	✓
1	LAMP ASSY, FOG, RH	\$	SL	951.40	X
1	UNIT ASSY, HEADLAMP, LH	\$	CM	2,637.60	✓
1	COMPUTER SUB-ASSY, HEADLAMP, LH NO.1	\$		960.50	?
1	UNIT ASSY, HEADLAMP, RH	\$	MR	2,637.60	✓
1	COMPUTER SUB-ASSY, HEADLAMP, RH NO.1	\$	SL	960.50	X
1	MOTOR, HEADLAMP LEVELING, RH	\$		487.50	?
1	GRILLE SUB-ASSY, RADIATOR	\$	CM	346.00	✓
1	GRILLE, RADIATOR, LOWER NO.1	\$	CM	170.10	✓
1	EMBLEM ASSY, RADIATOR GRILLE	\$	MR	90.80	✓
1	COVER SUB-ASSY, FRONT PILLAR, UPR LH	\$	DR	100.40	✓
1	SUPPORT, RADIATOR, UPPER RH	\$	R	78.90	X
1	SUPPORT, RADIATOR, UPPER LH	\$	R	78.90	✓

Trans-cab Auto Services Pte Ltd**AAD2111-157**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB7779K

1	SUPPORT SUB-ASSY, RADIATOR, UPPER	\$	<i>R₁</i>	377.10	✓
1	SUPPORT SUB-ASSY, RADIATOR, LOWER	\$	<i>R₁</i>	409.90	✓
1	SUPPORT SUB-ASSY, RADIATOR, LH	\$	<i>R₁</i>	245.10	✓
1	SUPPORT SUB-ASSY, RADIATOR, RH	\$	<i>R₁</i>	245.10	X
1	HOOD SUB-ASSY	\$	<i>R₁</i>	983.10	✓
1	HINGE ASSY, HOOD, LH	\$	<i>R₁</i>	58.90	✓
1	HINGE ASSY, HOOD, RH	\$	<i>R₁</i>	58.90	✓
1	BRACE, HOOD LOCK SUPPORT	\$	<i>R₁</i>	78.30	✓
1	INSULATOR, HOOD	\$	<i>Return</i>	410.90	✓
1	LOCK ASSY, HOOD	\$	<i>R₁</i>	135.00	✓
1	SEAL, HOOD TO FRONT END PANEL	\$		51.60	?
1	WIRE, ENGINE ROOM MAIN	\$	<i>CM</i>	7,323.90	?
1	HORN ASSY, HIGH PITCHED	\$		134.80	?
1	HORN ASSY, LOW PITCHED	\$		134.80	?
1	GUIDE, RADIATOR AIR, NO.1 LH	\$	<i>CM</i>	69.90	✓
1	GUIDE, RADIATOR AIR, NO.1 RH	\$	<i>SM</i>	65.30	X
1	GUIDE, RADIATOR AIR, NO.3	\$		112.70	?
1	GUIDE, RADIATOR AIR, NO.2	\$		53.40	?
1	SEAL, RADIATOR TO SUPPORT, NO.3	\$		29.60	?
1	SEAL, RADIATOR TO SUPPORT, NO.2	\$		29.60	?
1	INLET, AIR CLEANER, NO.1	\$		155.60	?
1	INLET, AIR CLEANER, NO.3	\$		42.10	?
1	INLET, AIR CLEANER, NO.2	\$		112.70	?
1	HOSE, AIR CLEANER, NO.1	\$		74.00	?
1	JAR ASSY, WINDSHIELD WASHER	\$	<i>SM</i>	219.10	X
1	MOTOR AND PUMP ASSY, WINDSHIELD WASHER	\$	<i>SM</i>	292.40	X
1	INLET SUB-ASSY, WASHER	\$	<i>SM</i>	67.00	X
1	CONDENSER ASSY, COOLER	\$	<i>R₁</i>	1,783.20	✓
1	HOSE SUB-ASSY, SUCTION	\$		646.80	?
1	HOSE SUB-ASSY, DISCHARGE	\$		402.90	?
1	PIPE SUB-ASSY, SUCTION	\$		465.80	?
1	SENSOR, AIRCONDITIONER PRESSURE	\$		342.80	?
1	TUBE & ACCESSORY ASSY, AIR CONDITIONER	\$		691.00	?
1	COMPRESSOR ASSY, W/MOTOR	\$		4,771.60	?
1	RADIATOR ASSY	\$	<i>R₁</i>	2,218.00	✓
1	SHROUD, FAN	\$	<i>CM</i>	264.70	✓
1	FAN, RH	\$	<i>CM</i>	281.30	✓

Trans-cab Auto Services Pte Ltd**AAD2111-157**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB7779K

1 FAN, LH	\$	219.10	?
1 MOTOR, COOLING FAN, LH	\$	655.10	?
1 MOTOR, COOLING FAN, RH	\$	535.50	?
1 TANK ASSY, INVERTER RESERVE	\$	443.00	?
1 INVERTER WATER PUMP ASSY(W/MOTOR)	\$	518.60	?
1 BATTERY	\$	1,584.90	?
1 CLAMP, BATTERY, NO.2	\$	51.80	X
1 CLAMP SUB-ASSY, BATTERY	\$	115.50	X
1 TERMINAL, BATTERY POSITIVE	\$	58.10	X
1 COVER, FUSIBLE LINK	\$	33.90	X
1 SENSOR ASSY, BATTERY STATE	\$	306.10	?
1 BLOCK ASSY, FUSIBLE LINK	\$	119.60	?
1 TANK, RESERVE SEALED W/O CAP	\$	151.40	?
1 CLEANER ASSY, AIR	\$	CM 1,147.00	?
1 BRACKET, HEADLAMP, LH	\$	34.80	—
1 BRACKET, HEADLAMP, RH	\$	34.80	X
1 STAY SUB-ASSY, FRONT BUMPER, LH	\$	47.50	—
1 STAY SUB-ASSY, FRONT BUMPER, RH	\$	47.50	X
1 BRACKET, FRONT BUMPER SIDE, LH	\$	CM 59.30	—
1 BRACKET, FRONT BUMPER SIDE, RH	\$	59.30	X
1 BRACKET, RADIATOR GRILLE MOUNTING, LH	\$	36.60	?
1 BRACKET, RADIATOR GRILLE MOUNTING, RH	\$	36.60	?
1 MEMBER SUB-ASSY, FRONT SIDE, RH	\$	2,342.30	?
1 COVER, RADIATOR SUPPORT OPENING	\$	235.30	?
1 THERMISTOR ASSY	\$	80.90	?
1 ACTUATOR ASSY, SHIFT CONTROL	\$	1,036.40	?
1 COOLER, MOTOR COOLING	\$	297.20	?
1 MOULDING ASSY, BODY ROCKER PANEL, LH	\$	CM 594.80	—
1 MIRROR ASSY, OUTER REAR VIEW, LH	\$	1,339.30	X
1 FENDER SUB-ASSY, FRONT LH	\$	977.80	—
1 LINER, FRONT FENDER, LH	\$	CM 202.50	—
1 EMBLEM, SIDE PANEL	\$	54.60	—
1 PANEL SUB-ASSY, FRONT DOOR, LH	\$	1,300.70	X
1 TAPE, BLACK OUT, NO.2 FRT LH	\$	43.50	X
1 TAPE, BLACK OUT, NO.1 FRT LH	\$	13.30	X
1 TAPE, BLACK OUT, NO.3 FRT LH	\$	26.30	X
1 RIM	\$	1,900.10	—

Trans-cab Auto Services Pte Ltd

AAD2111-157

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB7779K

1	ABSORBER ASSY, SHOCK, FRONT LH	\$	R ₁	438.30	✓
1	ARM SUB-ASSY, FRONT SUSPENSION, LOWER NO.1 LH	\$	R ₁	760.10	✓
1	KNUCKLE, STEERING, LH	\$	R ₁	663.40	✓
TOTAL		\$		55,963.60	
25%		\$		13,990.90	
		\$		41,972.70	

Special Nett

1SET BUMPER CLIP FRT	\$	nn	95.00	505n
1 FRONT NUMBER PLATE WITH MOULDING	\$	R ₁	200.00	455n
1SET CLIP, FRONT FENDER LINER	\$	nn	85.00	✓
1SET FRNT BUMPER RETAINER CLIP	\$	nn	85.00	✓
4L Radiator Coolant	\$	nn	120.00	505n
1 HOOD INSULATOR CLIP	\$	nn	55.00	✓
1 Engine Under Cover Clip	\$	nn	60.00	✓
1 DOOR STICKER 'TRANSCAB'	\$	nn	100.00	505n
1 TYRE	\$	nn	350.00	909n
TOTAL		\$	1,150.00	
TOTAL PARTS		\$	43,122.70	

LABOUR

To Remove And Refit Rear Big and Small W/Screen Glass To Facilitate Bodywork Repair.

\$ nn 300.00 X

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ nn 380.00 X

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$ 2,200.00 909n

To transfer of rear end panel fittings, attachment and perform water seepage test.

\$ nn 380.00 X

To transfer of Tailgate fittings, attachments and perform water seepage test.

\$ nn 180.00 X

Trans-cab Auto Services Pte Ltd**AAD2111-157**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB7779K

To remove and refit electrical wiring, battery and other necessary items to facilitate bodywork repair.	\$	480.00	80
To transfer of Fender fittings, attachments and perform water seepage test.	\$	nn 480.00	X
To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas.	\$	380.00	100
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00	?
To check steering geometry and computer wheel alignment	\$	220.00	60
To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	250.00	90
Towing Fees	\$	150.00	50
Putty And Spray Painting Of The Affected Portion.	\$	2,200.00	1320
To reinstall rear bumper parking sensor.	\$	nn 170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	20
To transfer of luggage floor panel fittings, attachment and perform water seepage test.	\$	nn 380.00	X
To transfer of tire, rim and on wheel balancing.	\$	220.00	20
To replace, refix and top up coolant for radiator	\$	170.00	50
To lift-up / out engine with gear box and refit.	\$	440.00	?
To remove and refit radiator support cross-member and other necessary items to enable bodywork repair.	\$	380.00	?

Trans-cab Auto Services Pte Ltd

AAD2111-157

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB7779K

To conduct and perform a comprehensive vehicle diagnostic check
and reset vehicle warning indicators.

	\$	380.00	X
TOTAL	\$	10,290.00	

Over All Total	\$	53,412.70
-----------------------	----	------------------

(PART-BY-PART) Repair Days

25 DAYS

12 days

**LKK Auto Consultants hence notify
the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: