

ASS. REQ. BY:

REF:

TMI/

CC3/TMI21012282/Kvc

Kenneth

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured: SLU 1002K

Policy No. MU012018

Claims No. M2105491

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

854,064/2

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

12

days

Res.: Yes or No

Lump Sum:

1.31 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

S/HB 7779K

Yr Regn:

08, 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Prius

c.c

1798

Colour

M.P. White / PW

A/C:

Insured / Std / Nil / NA

Sp. Reading

T/Radio: Insured / Std / Nil / NA

Eng/No:

C/No:

JTDKB3FU503083339

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD / RIM or

Tyre Size:

F:

195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Pailan

Front

Rear

R/Bal.

9

mm

R/Bal.

7

mm

L/Bal.

9

mm

L/Bal.

7

mm

D.O.A.

27/11/21

D.O.I.

1/12/2021

Survey held at

Des. of Damages: Fnt / Rear / O/S / N/S / UIC / Rooftop or

N/S Fnt &amp; Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1

Got BZ, battery flat

11/12

Max repair bill \$26,500

29/12/22

Lump Sum \$21,400 (un-confirmed)

Date/Time, File Pass to?

☐

: Prell. Report

☐

: Final Report

1)

Date/Time, File Return to?

2) 29/12/22-typist

Days Of Repair: 12

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. \$

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

**Trans-cab Auto Services Pte Ltd**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHB7779K***Not Notified***AAD2111-157***11 Sep @  
Puchong After Rain*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

**01 DEC 2021****SHB7779K**

JTDKB3FU503083339

TOYOTA

PRIUS

27/11/2021

Taka

30/08/2019

**PART****LIST**

|   |                                          |    |    |          |   |
|---|------------------------------------------|----|----|----------|---|
| 1 | COVER, FRONT BUMPER                      | \$ | R  | 516.00   | ✓ |
| 1 | BRACKET, FRONT BUMPER EXTENSION MOUNTING | \$ | DR | 103.40   | ✓ |
| 1 | REINFORCEMENT SUB-ASSY, FRONT BUMPER     | \$ | R  | 716.60   | ✓ |
| 1 | REINFORCEMENT, FRONT BUMPER, NO.2        | \$ | R  | 246.10   | ✓ |
| 1 | ABSORBER, FRONT BUMPER, LOWER            | \$ | CM | 132.70   | ✓ |
| 1 | ABSORBER, FRONT BUMPER ENERGY            | \$ | CM | 79.60    | ✓ |
| 1 | SUPPORT, FRONT BUMPER SIDE, RH           | \$ | DR | 80.10    | ✓ |
| 1 | SUPPORT, FRONT BUMPER SIDE, LH           | \$ | R  | 82.30    | ✓ |
| 1 | COVER, ENGINE UNDER, NO.1                | \$ | CM | 472.40   | ✓ |
| 1 | COVER SUB-ASSY, ENGINE UNDER, NO.2       | \$ |    | 241.90   | ? |
| 1 | EXTENSION, FRONT BUMPER, RH              | \$ | SL | 120.10   | X |
| 1 | EXTENSION, FRONT BUMPER, LH              | \$ | DR | 120.10   | ✓ |
| 1 | COVER, FRONT BUMPER HOLE, LH             | \$ | MR | 29.30    | ✓ |
| 1 | COVER, FRONT BUMPER HOLE, RH             | \$ | MR | 29.30    | ✓ |
| 1 | COVER SUB-ASSY, FRONT PILLAR, UPR LH     | \$ |    | 100.40   | ? |
| 1 | LAMP ASSY, FOG, LH                       | \$ | CM | 951.40   | ✓ |
| 1 | LAMP ASSY, FOG, RH                       | \$ | SL | 951.40   | X |
| 1 | UNIT ASSY, HEADLAMP, LH                  | \$ | CM | 2,637.60 | ✓ |
| 1 | COMPUTER SUB-ASSY, HEADLAMP, LH NO.1     | \$ |    | 960.50   | ? |
| 1 | UNIT ASSY, HEADLAMP, RH                  | \$ | MR | 2,637.60 | ✓ |
| 1 | COMPUTER SUB-ASSY, HEADLAMP, RH NO.1     | \$ | SL | 960.50   | X |
| 1 | MOTOR, HEADLAMP LEVELING, RH             | \$ |    | 487.50   | ? |
| 1 | GRILLE SUB-ASSY, RADIATOR                | \$ | CM | 346.00   | ✓ |
| 1 | GRILLE, RADIATOR, LOWER NO.1             | \$ | CM | 170.10   | ✓ |
| 1 | EMBLEM ASSY, RADIATOR GRILLE             | \$ | MR | 90.80    | ✓ |
| 1 | COVER SUB-ASSY, FRONT PILLAR, UPR LH     | \$ | DR | 100.40   | ✓ |
| 1 | SUPPORT, RADIATOR, UPPER RH              | \$ | R  | 78.90    | X |
| 1 | SUPPORT, RADIATOR, UPPER LH              | \$ | R  | 78.90    | ✓ |

**Trans-cab Auto Services Pte Ltd****AAD2111-157**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHB7779K**

|   |                                        |    |                |          |   |
|---|----------------------------------------|----|----------------|----------|---|
| 1 | SUPPORT SUB-ASSY, RADIATOR, UPPER      | \$ | B <sub>1</sub> | 377.10   | ✓ |
| 1 | SUPPORT SUB-ASSY, RADIATOR, LOWER      | \$ | B <sub>1</sub> | 409.90   | ✓ |
| 1 | SUPPORT SUB-ASSY, RADIATOR, LH         | \$ | B <sub>1</sub> | 245.10   | ✓ |
| 1 | SUPPORT SUB-ASSY, RADIATOR, RH         | \$ | R              | 245.10   | X |
| 1 | HOOD SUB-ASSY                          | \$ | B <sub>1</sub> | 983.10   | ✓ |
| 1 | HINGE ASSY, HOOD, LH                   | \$ | B <sub>1</sub> | 58.90    | ✓ |
| 1 | HINGE ASSY, HOOD, RH                   | \$ | B <sub>1</sub> | 58.90    | ✓ |
| 1 | BRACE, HOOD LOCK SUPPORT               | \$ | B <sub>1</sub> | 78.30    | ✓ |
| 1 | INSULATOR, HOOD                        | \$ | Return         | 410.90   | ✓ |
| 1 | LOCK ASSY, HOOD                        | \$ | B <sub>1</sub> | 135.00   | ✓ |
| 1 | SEAL, HOOD TO FRONT END PANEL          | \$ |                | 51.60    | ? |
| 1 | WIRE, ENGINE ROOM MAIN                 | \$ | CM             | 7,323.90 | ? |
| 1 | HORN ASSY, HIGH PITCHED                | \$ |                | 134.80   | ? |
| 1 | HORN ASSY, LOW PITCHED                 | \$ |                | 134.80   | ? |
| 1 | GUIDE, RADIATOR AIR, NO.1 LH           | \$ | CM             | 69.90    | ✓ |
| 1 | GUIDE, RADIATOR AIR, NO.1 RH           | \$ | SM             | 65.30    | X |
| 1 | GUIDE, RADIATOR AIR, NO.3              | \$ |                | 112.70   | ? |
| 1 | GUIDE, RADIATOR AIR, NO.2              | \$ |                | 53.40    | ? |
| 1 | SEAL, RADIATOR TO SUPPORT, NO.3        | \$ |                | 29.60    | ? |
| 1 | SEAL, RADIATOR TO SUPPORT, NO.2        | \$ |                | 29.60    | ? |
| 1 | INLET, AIR CLEANER, NO.1               | \$ |                | 155.60   | ? |
| 1 | INLET, AIR CLEANER, NO.3               | \$ |                | 42.10    | ? |
| 1 | INLET, AIR CLEANER, NO.2               | \$ |                | 112.70   | ? |
| 1 | HOSE, AIR CLEANER, NO.1                | \$ |                | 74.00    | ? |
| 1 | JAR ASSY, WINDSHIELD WASHER            | \$ | SM             | 219.10   | X |
| 1 | MOTOR AND PUMP ASSY, WINDSHIELD WASHER | \$ | SM             | 292.40   | X |
| 1 | INLET SUB-ASSY, WASHER                 | \$ | SM             | 67.00    | X |
| 1 | CONDENSER ASSY, COOLER                 | \$ | B <sub>1</sub> | 1,783.20 | ✓ |
| 1 | HOSE SUB-ASSY, SUCTION                 | \$ |                | 646.80   | ? |
| 1 | HOSE SUB-ASSY, DISCHARGE               | \$ |                | 402.90   | ? |
| 1 | PIPE SUB-ASSY, SUCTION                 | \$ |                | 465.80   | ? |
| 1 | SENSOR, AIRCONDITIONER PRESSURE        | \$ |                | 342.80   | ? |
| 1 | TUBE & ACCESSORY ASSY, AIR CONDITIONER | \$ |                | 691.00   | ? |
| 1 | COMPRESSOR ASSY, W/MOTOR               | \$ |                | 4,771.60 | ? |
| 1 | RADIATOR ASSY                          | \$ | B <sub>1</sub> | 2,218.00 | ✓ |
| 1 | SHROUD, FAN                            | \$ | CM             | 264.70   | ✓ |
| 1 | FAN, RH                                | \$ | CM             | 281.30   | ✓ |

**Trans-cab Auto Services Pte Ltd****AAD2111-157**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHB7779K**

|                                         |    |             |   |
|-----------------------------------------|----|-------------|---|
| 1 FAN, LH                               | \$ | 219.10      | ? |
| 1 MOTOR, COOLING FAN, LH                | \$ | 655.10      | ? |
| 1 MOTOR, COOLING FAN, RH                | \$ | 535.50      | ? |
| 1 TANK ASSY, INVERTER RESERVE           | \$ | 443.00      | ? |
| 1 INVERTER WATER PUMP ASSY(W/MOTOR)     | \$ | 518.60      | ? |
| 1 BATTERY                               | \$ | 1,584.90    | ? |
| 1 CLAMP, BATTERY, NO.2                  | \$ | 51.80       | X |
| 1 CLAMP SUB-ASSY, BATTERY               | \$ | 115.50      | X |
| 1 TERMINAL, BATTERY POSITIVE            | \$ | 58.10       | X |
| 1 COVER, FUSIBLE LINK                   | \$ | 33.90       | X |
| 1 SENSOR ASSY, BATTERY STATE            | \$ | 306.10      | ? |
| 1 BLOCK ASSY, FUSIBLE LINK              | \$ | 119.60      | ? |
| 1 TANK, RESERVE SEALED W/O CAP          | \$ | 151.40      | ? |
| 1 CLEANER ASSY, AIR                     | \$ | CM 1,147.00 | ? |
| 1 BRACKET, HEADLAMP, LH                 | \$ | 34.80       | — |
| 1 BRACKET, HEADLAMP, RH                 | \$ | 34.80       | X |
| 1 STAY SUB-ASSY, FRONT BUMPER, LH       | \$ | 47.50       | — |
| 1 STAY SUB-ASSY, FRONT BUMPER, RH       | \$ | 47.50       | X |
| 1 BRACKET, FRONT BUMPER SIDE, LH        | \$ | CM 59.30    | — |
| 1 BRACKET, FRONT BUMPER SIDE, RH        | \$ | 59.30       | X |
| 1 BRACKET, RADIATOR GRILLE MOUNTING, LH | \$ | 36.60       | ? |
| 1 BRACKET, RADIATOR GRILLE MOUNTING, RH | \$ | 36.60       | ? |
| 1 MEMBER SUB-ASSY, FRONT SIDE, RH       | \$ | 2,342.30    | ? |
| 1 COVER, RADIATOR SUPPORT OPENING       | \$ | 235.30      | ? |
| 1 THERMISTOR ASSY                       | \$ | 80.90       | ? |
| 1 ACTUATOR ASSY, SHIFT CONTROL          | \$ | 1,036.40    | ? |
| 1 COOLER, MOTOR COOLING                 | \$ | 297.20      | ? |
| 1 MOULDING ASSY, BODY ROCKER PANEL, LH  | \$ | CM 594.80   | — |
| 1 MIRROR ASSY, OUTER REAR VIEW, LH      | \$ | 1,339.30    | X |
| 1 FENDER SUB-ASSY, FRONT LH             | \$ | 977.80      | — |
| 1 LINER, FRONT FENDER, LH               | \$ | CM 202.50   | — |
| 1 EMBLEM, SIDE PANEL                    | \$ | 54.60       | — |
| 1 PANEL SUB-ASSY, FRONT DOOR, LH        | \$ | 1,300.70    | X |
| 1 TAPE, BLACK OUT, NO.2 FRT LH          | \$ | 43.50       | X |
| 1 TAPE, BLACK OUT, NO.1 FRT LH          | \$ | 13.30       | X |
| 1 TAPE, BLACK OUT, NO.3 FRT LH          | \$ | 26.30       | X |
| 1 RIM                                   | \$ | 1,900.10    | — |

**Trans-cab Auto Services Pte Ltd**

AAD2111-157

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHB7779K**

|              |                                               |    |                |                  |   |
|--------------|-----------------------------------------------|----|----------------|------------------|---|
| 1            | ABSORBER ASSY, SHOCK, FRONT LH                | \$ | B <sub>1</sub> | 438.30           | ✓ |
| 1            | ARM SUB-ASSY, FRONT SUSPENSION, LOWER NO.1 LH | \$ | B <sub>1</sub> | 760.10           | ✓ |
| 1            | KNUCKLE, STEERING, LH                         | \$ | B <sub>1</sub> | 663.40           | ✓ |
| <b>TOTAL</b> |                                               | \$ |                | <b>55,963.60</b> |   |
| 25%          |                                               | \$ |                | <b>13,990.90</b> |   |
|              |                                               | \$ |                | <b>41,972.70</b> |   |

**Special Nett**

|                                    |    |                |                  |      |
|------------------------------------|----|----------------|------------------|------|
| 1SET BUMPER CLIP FRT               | \$ | M              | 95.00            | 505N |
| 1 FRONT NUMBER PLATE WITH MOULDING | \$ | B <sub>1</sub> | 200.00           | 455N |
| 1SET CLIP, FRONT FENDER LINER      | \$ | M              | 85.00            | ✓    |
| 1SET FRNT BUMPER RETAINER CLIP     | \$ | nn             | 85.00            | ✓    |
| 4L Radiator Coolant                | \$ | M              | 120.00           | 505N |
| 1 HOOD INSULATOR CLIP              | \$ | M              | 55.00            | ✓    |
| 1 Engine Under Cover Clip          | \$ | M              | 60.00            | ✓    |
| 1 DOOR STICKER 'TRANSCAB'          | \$ | M              | 100.00           | 505N |
| 1 TYRE                             | \$ | P <sub>1</sub> | 350.00           | 909N |
| <b>TOTAL</b>                       |    | \$             | <b>1,150.00</b>  |      |
| <b>TOTAL PARTS</b>                 |    | \$             | <b>43,122.70</b> |      |

**LABOUR**

To Remove And Refit Rear Big and Small W/Screen Glass To Facilitate Bodywork Repair.

\$ nn 300.00 X

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ nn 380.00 X

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$ 2,200.00 909N

To transfer of rear end panel fittings, attachment and perform water seepage test.

\$ nn 380.00 X

To transfer of Tailgate fittings, attachments and perform water seepage test.

\$ nn 180.00 X

**Trans-cab Auto Services Pte Ltd****AAD2111-157**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHB7779K**

|                                                                                                         |    |          |      |
|---------------------------------------------------------------------------------------------------------|----|----------|------|
| To remove and refit electrical wiring, battery and other necessary items to facilitate bodywork repair. | \$ | 480.00   | 80   |
| To transfer of Fender fittings, attachments and perform water seepage test.                             | \$ | 480.00   | X    |
| To dismantle and refit aircon assy and attachment, vacuum and charge-in-gas.                            | \$ | 380.00   | 100  |
| Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.                         | \$ | 380.00   | ?    |
| To check steering geometry and computer wheel alignment                                                 | \$ | 220.00   | 60   |
| To Rust-Proofing and apply undercoat Of The Affected Areas.                                             | \$ | 250.00   | 90   |
| Towing Fees                                                                                             | \$ | 150.00   | 50   |
| Putty And Spray Painting Of The Affected Portion.                                                       | \$ | 2,200.00 | 1320 |
| To reinstall rear bumper parking sensor.                                                                | \$ | 170.00   | X    |
| To Check Electrical Lighting Concerned.                                                                 | \$ | 170.00   | 20   |
| To transfer of luggage floor panel fittings, attachment and perform water seepage test.                 | \$ | 380.00   | X    |
| To transfer of tire, rim and on wheel balancing.                                                        | \$ | 220.00   | 20   |
| To replace, refix and top up coolant for radiator                                                       | \$ | 170.00   | 50   |
| To lift-up / out engine with gear box and refit.                                                        | \$ | 440.00   | ?    |
| To remove and refit radiator support cross-member and other necessary items to enable bodywork repair.  | \$ | 380.00   | ?    |

**Trans-cab Auto Services Pte Ltd**

**AAD2111-157**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

**SHB7779K**

To conduct and perform a comprehensive vehicle diagnostic check  
and reset vehicle warning indicators.

|              |    |                  |   |
|--------------|----|------------------|---|
|              | \$ | 380.00           | X |
| <b>TOTAL</b> | \$ | <b>10,290.00</b> |   |

|                       |    |                  |
|-----------------------|----|------------------|
| <b>Over All Total</b> | \$ | <b>53,412.70</b> |
|-----------------------|----|------------------|

**(PART-BY-PART) Repair Days**

**25 DAYS**

*12 days*

**LKK Auto Consultants** hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

**Acknowledged by Repairer**

Signature:

Date:

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

|                                 |                                            |
|---------------------------------|--------------------------------------------|
| Date of Submission              | 29/11/2021 21:08 (SGT)                     |
| Date of Accident                | 27/11/2021 17:30 (SGT)                     |
| Exact Location of Accident      | Near Block 1, Singapore                    |
| Additional Location Information | JUNCTION OF ZION ROAD AND TIONG BAHRU ROAD |
| Country/State of Loss           | Singapore                                  |

### DETAILS OF OWN VEHICLE

|                             |                             |
|-----------------------------|-----------------------------|
| Vehicle Registration Number | SHB7779K                    |
| INSURED/POLICYHOLDER        |                             |
| Is company?                 | Yes                         |
| Name Of Registered Owner    | TRANS-CAB SERVICES PTE LTD_ |
| Company Reg No              | 2XXXXXX78K                  |
| Email Address               | claims@transcab.com.sg      |
| Mobile Phone No             | (Phone) +65-62876666        |
| Alternative Phone No        | (Office) +65-62876666       |

### VEHICLE PARTICULARS

|                                                                              |                            |
|------------------------------------------------------------------------------|----------------------------|
| Manufacturer                                                                 | Toyota                     |
| Model                                                                        | PRIUS 5DR HATCHBACK (AUTO) |
| Variant                                                                      | -                          |
| Exact purpose for which vehicle was being used at time of accident           | Private hire               |
| Are you claiming under your own insurance policy for repair to your vehicle? | No - Claiming third party  |
| Vehicle Category                                                             | Taxi                       |
| Transmission                                                                 | Auto                       |
| CC                                                                           | 1767                       |

### INSURANCE COMPANY

|                           |                       |
|---------------------------|-----------------------|
| Name of Insurance Company | AXA Insurance Pte Ltd |
| Type of Coverage          | ThirdParty            |
| Fleet Policy              | Yes                   |
| Policy Number             | VFX/P2413997          |
| Cover Note Number         | -                     |

### DRIVER

|                |                |
|----------------|----------------|
| Name of Driver | SUM WAH CHEONG |
| NRIC No        | SXXXX516G      |

|                                                              |                        |
|--------------------------------------------------------------|------------------------|
| Date Of Birth                                                | 31/05/1961             |
| Occupation                                                   | Outdoor                |
| Date Of Driving Pass                                         | 09/01/1981             |
| Driving experience                                           | 40 YEARS AND 10 MONTHS |
| Gender                                                       | Male                   |
| Mobile Number                                                | (Phone) +65-97880070   |
| Alt. Phone Number                                            | -                      |
| Email Address                                                | claims@transcab.com.sg |
| Address                                                      | 502A WOODLANDS DR 14   |
| Address complement                                           | #05-28                 |
| Postcode                                                     | 731502                 |
| Is the driver the policyholder?                              | No                     |
| If No, Relationship of the Driver with the Insured           | Hirer                  |
| Does Driver Own Other Vehicles?                              | No                     |
| Vehicle Registration Number of Other Vehicle Owned by Driver | -                      |
| Insurance Company of Other Vehicle Owned by Driver           | -                      |

#### GENERAL INFORMATION OF THE ACCIDENT

|                    |            |
|--------------------|------------|
| Type of Accident   | Side Swipe |
| Weather Conditions | Clear      |
| Road Surface       | Dry        |

#### OTHER INFORMATION

|                                                                                                     |     |
|-----------------------------------------------------------------------------------------------------|-----|
| Was any foreign vehicle involved in the accident?                                                   | No  |
| Number of vehicles involved in the accident                                                         | 2   |
| Was anybody injured in the Accident?                                                                | Yes |
| Was any injured conveyed to hospital by ambulance?                                                  | Yes |
| Was any other vehicle or property damaged?                                                          | Yes |
| Number of Passengers (Including Driver)                                                             | 2   |
| Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? | No  |

#### PASSENGER 1

|        |        |
|--------|--------|
| Name   | P1     |
| Gender | Female |

#### DETAILS OF POLICE ACTION

|                                           |                                  |
|-------------------------------------------|----------------------------------|
| Was the accident reported to the police?  | Yes                              |
| Police Station Name                       | Traffic Police                   |
| Police Station Phone No                   | (Phone) +65-65470000             |
| Alt. Police Station Phone No              | (Fax) +65-65474900               |
| Police Station Address                    | 10 Ubi Avenue 3 Singapore 408865 |
| Was notice of intended Prosecution given? | No                               |
| If yes, against whom?                     | -                                |

#### CIRCUMSTANCES OF ACCIDENT

#### REFER TO POLICE REPORT


#### ATTACHMENT(S)

|                                               |     |
|-----------------------------------------------|-----|
| Are accident photos available for attachment? | Yes |
| Was there any video captured by Car Camera?   | No  |
| Was there any audio recorded?                 | No  |

#### DETAILS OF OTHER VEHICLE PROPERTY 1

|                             |          |
|-----------------------------|----------|
| Vehicle Registration Number | SLU1002K |
| Vehicle Manufacturer        | Honda    |

ACCIDENT DIAG



*[Handwritten signature]*

VERIFIED BY AJAX MARS (ARC)  
REPORTING OFFICER  
WONG JIN KEAT

Policyholder's Signature  
Date & Time:

Driver's Signature  
(if driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name  
NRIC/PPN No.:



**SINGAPORE  
POLICE FORCE**

Police Station Of Origin:  
Traffic Police  
10 Lili Avenue 3 SINGAPORE 408865  
Tel No: 65470000



1/202111200070

Page 1

Report No: 1/202111200070

**CONTINUATION OF REPORT**

|                                   |                            |                                        |                                 |
|-----------------------------------|----------------------------|----------------------------------------|---------------------------------|
| <b>Driver</b>                     |                            |                                        |                                 |
| Name                              | SUM WAH CHEONG             | ID No.                                 | S1489516G                       |
| Related Vehicle                   | SHB7779K (Car)             | Contact No.                            | 97880070                        |
| Hospital/Clinic                   | SINGAPORE GENERAL HOSPITAL | Class of Driving Licence & Expiry Date | Class: 3<br>Date of Expiry: NIL |
| Date Treatment                    | 27/11/2021                 | Date Discharge                         | 27/11/2021                      |
| No. of Days granted Medical Leave | 04                         | Degree of Injury                       | NIL                             |

**Brief Details.**

**ON THE ABOVE STATED DATE, TIME AND LOCATION**

I WAS AT ZION RD TWDS HOOT KIAN RD X TIONG BAHRU RD. I WAS ON 2ND LANE AS THERE WAS ROAD WORK ON THE FIRST LANE. I WAS GOING STRAIGHT AND I WAS HIT ON LEFT SIDE OF MY TAXI AND I SWERVED TO THE RIGHT AND I COLLIDED INTO THE TRAFFIC LIGHT. CASE IS UNDER TP 10 MD NOOR EXT 65475201.

THATS ALL.

> Back to OneMotoring

### Enquire PARF/COE Rebate for Registered Vehicle

#### Vehicle Owner Particulars

Owner ID Type: Company  
Owner ID: 878K

#### Vehicle Details

Vehicle No.: 5HB7779K  
Vehicle to be Exported: Yes  
Intended Deregistration Date: 29 Nov 2021  
Vehicle Make: TOYOTA  
Vehicle Model: PRIUS 5DR HATCHBACK (AUTO)  
Primary Colour: Red  
Manufacturing Year: 2018  
Engine No.: 2ZR2C51280  
Chassis No.: JTDKB3FU503083339  
Maximum Power Output: 90.0 kW (120 bhp)  
Open Market Value: \$26,605.00  
Original Registration Date: 30 Aug 2019  
First Registration Date: 30 Aug 2019  
Transfer Count: 0  
Actual ARF Paid: \$14,247.00

#### Intended PARF Rebate Details

PARF Eligibility: Yes  
PARF Eligibility Expiry Date: 29 Aug 2027  
PARF Rebate Amount: \$10,685.00

#### Intended COE Rebate Details

COE Expiry Date: 29 Aug 2027  
COE Category: A - Car up to 1600cc & 97kW (130bhp)  
COE Period(Years): 8  
PQP Paid: \$23,463.00  
COE Rebate Amount: \$16,864.00  
Total Rebate Amount: \$27,549.00

#### Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory age (if applicable), whichever is earlier.

The information contained herein is correct as at 29 Nov 2021

OK