

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI21012285/EVY3E2

Date: 04/01/2022

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMB1SNW00012732100	
Claimant Vehicle No :	PC8388Z	Insured Vehicle No :	PC1013B	
Date of Loss:	03/12/2021	Nature of Claim:	TP	Claim No: SNM21D206993/C02/CHEESC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	PC8388Z	Engine No:	N04CUH14618
Make & Model:	TOYOTA COASTER, 4.0 D (M)	Chassis No:	JTGEP538X06000328
Reg. Date:	23/04/2012 (Man. Year: 2011)	Odometer:	452326 km
Colour:	White		
Engine Capacity:	4009 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/75 R17	Rear Tyre Size:	215/75 R17
Front Left Side:	Dunlop 4 mm	Rear Left Side:	Dunlop 4 mm
Front Right Side:	Dunlop 4 mm	Rear Right Side:	Dunlop 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,147.36	5,834.39	3,312.97	36.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,320.00	2,300.00	1,020.00	30.72
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,467.36	8,134.39	4,332.97	34.75
Approved Total (Overridden) (S\$)		6,500.00		
(S\$)	12,467.36	6,500.00	5,967.36	47.86
+ GST 7.00/7.00% (S\$)	872.72	455.00	417.72	47.86
Nett Amount (S\$)	13,340.08	6,955.00	6,385.08	47.86

INSPECTION

Date of Assignment:	30/12/2021		
Date Inspected:	06/12/2021	Inspected At:	Connect3 (HQ) 566 Woodlands Road Singapore 728697
Estimated Period of Repair:	7.0 days		

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 04 Jan 2022)	
Parts:	N/A	TOYOTA COASTER 4.0 D (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for PC8388Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT PANEL	Dented	3,345.60 F	*2,700.00 FL
2	1		*FRONT HEADLAMP LH	Cut	922.50 F	*922.50 FL
3	1		*FRONT LH HEADLAMP SIDE GARNISH	Cut	96.12 F	*96.12 FL
4	1		*FRONT HEADLAMP LH BRACKET	Not Necessary	135.68 F	*- FL
5	1		*WIPER PANEL (BLACK)	Dented	1,606.30 F	*1,606.30 FL
6	1		*LH REAR VIEW MIRROR	Cut	138.31 F	*138.31 FL
7	1		*LH REAR VIEW MIRROR (ROUND - BOTTOM)	Not Necessary	491.76 F	*- FL
8	1		*LH REAR VIEW MIRROR BRACKET	Cut	165.90 F	*165.90 FL
9	1		*FRONT BUMPER BRACKET LH	Not Necessary	135.13 F	*- FL
10	1		*FRONT BUMPER	Dented	1,256.50 F	*1,256.50 FL
11	1		*FRONT WINDSCREEN MOULDING	Necessary	638.56 F	*638.56 FL
12	1		*TOYOTA EMBLEM	Necessary	95.00 F	*95.00 FL
13	3		*SEALANT	Necessary	120.00 FS	*120.00 FS
					Sub Total (\$\$)	9,147.36 7,739.19
					- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00 1,904.80
					Total Parts (\$\$)	9,147.36 5,834.39

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK WIRING	New	20.00	20.00
2	LABOUR TO REMOVE & REFIT FRONT WINDSCREEN	New	180.00	150.00
3	SPRAY PAINTING	New	1,000.00	600.00
4	APPLY ANTI RUST	New	120.00	30.00
5	LABOUR CHARGES	New	2,000.00	1,500.00
Gross Labour Cost (\$)			3,320.00	2,300.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >