

CONNECT 3

566 Woodlands Road (Mandai Estate) Singapore 728697

Tel: (65) 9850-9666 Email: Connect3winnie@gmail.com

R o c : 5 3 3 6 0 0 6 1 L

G S T : 5 3 3 6 0 0 6 1 L

QT21/PC8388Z/TPC

China Taiping Insurance (Singapore) Pte Ltd
3 Anson Rd #15-02
Springleaf Tower
Singapore 079909

List - 7619.19

- 25%

5714.39

Nett
labour

2420

= 8134.39

QUOTATION

L/S - 6507.51

= 6500

Dear Sir,

Cost of Repair to Vehicle PC8388Z

With reference to the above-mentioned, we are pleased to quote as follows:-

No.	DESCRIPTION	QTY	U/PRICE (S\$)	AMOUNT (S\$)
1.	Front panel / 00	1	3,345.60	2700/3,345.60
2.	Front Headlamp LH / CVT	1	922.50	922.50
3.	Front LH headlamp side garnish / CVT	1	96.12	96.12
4.	Front headlamp LH bracket ? X NR	1	135.68	135.68
5.	Wiper panel (black) / 00	1	1,606.30	1,606.30
6.	LH rear view mirror / CVT	1	138.31	138.31
7.	LH rear view mirror (round - bottom) X NR	1	491.76	491.76
8.	LH rear view mirror bracket / CVT	1	165.90	165.90
9.	Front bumper bracket LH ? X NR	1	135.13	135.13
10.	Front bumper / 00	1	1,256.50	1,256.50
11.	Front windscreen moulding / NEC	1	638.56	638.56
12.	Toyota emblem / NEC	1	95.00	95.00
13.	Sealant / NEC	3	40.00	120.00
14.	Check wiring	1	20.00	20.00
15.	Labour to remove & refit front windscreen	1	180.00	150 180.00

17.	Spray painting	1	1,000.00	600	1,000.00
18.	Apply anti rust	1	120.00	30	120.00
19.	Labour charges \$9000 1500 /	SUB-TOTAL			SS11,667.36

13,667.36

- Price before 7% gst

Thank you.

Yours faithfully,

Winnie Chai
HP: 9850-9666



Steve (LKK)
6/12/21, 11:20am

Whe R
L/S
My ALH
7 d/s

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: