

TO :

ESTIMATE REPORT

1ST Quotation

FAX NO:

06/12/2021 9:52

JOB-NO: 50113792

Page 1 of 2

OWNER'S PARTICULARS

NAME: CityCab PTE LTD (Fleet)

CONTACT: 65533880

ADDRESS: 383 SIN MING DRIVE
SINGAPORE 575717 0

64739522

VEHICLE DETAILS

LICENSE NO: SHB3757A

TRANS: AUTO

CHASSIS: KMHCB51CVKU164767

MAKE / MODEL: HYUNDAI / AE IONIQ HEV 1.6 Di

ENGINE: G4LEKU298147

OWNER'S INSURER: AXA INSURANCE SINGAPORE PTE LTD

JOB-CODE: TP

SA: Ding Auto User 2

CLAIM DETAILS

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
LABOUR							
1 TO STRAIGHTEN AND PANEL BEAT OF ACCIDENT AFFECTED AREA	1.00	1,200.00	0.00	1,200.00	244	4.00	Y
2 TO RUST PROOFING OF THE AFFECTED AREA	1.00	170.00	0.00	170.00	30		Y
3 TO REMOVE AND REFIT OF NECESSARY ITEMS TO FACILITATE BODYWORK REPAIR	1.00	300.00	0.00	300.00	X		Y
4 TO DIAGNOSTIC, CHECK WIRING AND LIGHTING SYSTEM AND CLEAR FAULT CODE	1.00	260.00	0.00	260.00	30		Y
5 TO REFIT REAR REVERSE SENSOR	1.00	150.00	0.00	150.00	30		Y
6 TO RESPRAY REAR BUMPER	1.00	250.00	0.00	250.00	200		Y
7 TO RESPRAY REAR REVERSE SENSOR	1.00	250.00	0.00	250.00	50		Y
8 TO RESPRAY REAR END PANEL	1.00	250.00	0.00	250.00	1 200		Y
9 TO RESPRAY REAR TAILGATE PANEL	1.00	250.00	0.00	250.00	X		Y
10 TO RESPRAY REAR BUMPER CENTER MOULDING	1.00	250.00	0.00	250.00	100		Y
11 TO RESPRAY REAR BUMPER LOWER MOULDING	1.00	250.00	0.00	250.00	1 X		Y
TOTAL:		3,580.00	0.00	3,580.00			

MATERIALS

1 REAR BUMPER COVER / CRU	1.00	659.60	459	131.92	527.68	L	Y
2 REAR BUMPER CENTER MOULDING / BR	1.00	362.30		72.46	289.84	L	Y
3 REAR BUMPER LOWER MOULDING / X nn	1.00	156.30		31.26	125.04	L	Y
4 REAR BUMPER REINFORCEMENT / BR	1.00	361.30		72.26	289.04	L	Y
5 REAR LH BUMPER REINFORCEMENT BRACKET / X nn	1.00	146.30		29.26	117.04	L	Y
6 REAR RH BUMPER REINFORCEMENT BRACKET / BT	1.00	146.30		29.26	117.04	L	Y
7 SMART KEY ANTENNA / BR	1.00	128.86	40.50	25.77	103.09	L	Y
8 REAR BUMPER CENTER UNDER COVER / X nn	1.00	86.30		17.26	69.04	L	Y
9 REAR RH BUMPER RETAINER / X nn	1.00	78.22		15.64	62.58	L	Y
10 REAR LICENCE PLATE LAMP / X nn	1.00	120.80		24.16	96.64	L	Y
11 REAR FOG LAMP ASSY / Cut	1.00	356.80	201.50	151.36	285.44	L	Y
12 REAR TAILGATE HYBRID EMBLEM / X nn	1.00	51.20		10.24	40.96	L	Y
13 REAR TAILGATE HYUNDAI EMBLEM / X nn	1.00	68.20		13.64	54.56	L	Y
14 REAR TAILGATE IONIQ EMBLEM / X nn	1.00	48.20		9.64	38.56	L	Y
15 REAR BOOT LOCK / X nn	1.00	284.44		56.89	227.55	L	Y
16 REAR BOOT WEATHERSTRIP / X nn	1.00	275.40		55.08	220.32	L	Y
17 TAILLAMP RH / X nn	1.00	905.20		181.04	724.16	L	Y

1570.90
-20%
1256.72

G-STAR-WI-ET-001-02-Rev00

CLAIM DETAILS

DESCRIPTION

DESCRIPTION	QTY	QUOTED COSTS	DISCOUNT	DISC PRICE	IND	SUR.DISP	REV PRICE
18 REAR END PANEL TRIM BOARD X nn	1.00	240.50	48.10	192.40	L	Y	
19 REAR BUMPER CLIP SET - n/c	1.00	75.00	0.00	75.00	S	nett	Y
20 REAR REVERSE SENSOR SET - dntd	2.00	400.00	0.00	800.00	S	nett	Y
21 REAR BUMPER PROTECTOR X nn	1.00	170.00	0.00	170.00	S	Y	
22 REAR BUMPER MOULDING CLIP SET - n/c	1.00	60.00	0.00	60.00	S	nett	Y
23 TAILLAMP GUIDE CLIP SET X nn	1.00	55.00	0.00	55.00	S	Y	
24 REAR TAILGATE "6552-1111" STICKER X nn	1.00	140.00	0.00	140.00	S	Y	
25 REAR TAILGATE "COMFORT DELGRO" STICKER X nn	1.00	140.00	0.00	140.00	S	Y	
26 REAR TAILGATE "BOOK NOW" STICKER X nn	1.00	140.00	0.00	140.00	S	Y	
27 REAR LICENCE PLATE NUMBER WITH FRAME - OR	1.00	100.00	0.00	100.00	S	nett	Y
28 REAR BUMPER UNDER COVER CLIP SET 2x nn	1.00	65.00	0.00	65.00	S	Y	
TOTAL:		5,821.22	895.24	4,925.98			
TOTAL PARTS & LABOUR:		9,401.22	895.24	8,505.98			

EXCESS/LOADING: S\$ 0.00

No. Of Day: _____

RE-SURVEY: BEFORE/AFTER PAINTING
PART-BY-PART OR LUMP SUM: S\$ _____

DATE OF SURVEY: ____ / ____ / ____

SURVEYED BY: _____

CONTACT NO: _____

FAX NO: _____

NOTE: LUMP SUM AMOUNT WOULD BE REVISED IF SUPPLEMENT REPAIR IS REQUIRED

DAuto002

Ding Auto User 2

ESTIMATOR

STA AUTOCENTRE

TEL: _____

FAX: _____

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

Wm 12 P/P
M FL SK
3 d/s

L - 1040
nett - 285
P - 1256.72
2581.72