COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

DATE:

2-Dec-21

MODEL

Toyota Prius

HASURANCE CHINA TAIPING (PP)

VEHICLE NO SHC3074G

MVA LIM TS

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT	/at
	Front Bumper	1		\$499.90	EJC
	Front Bumper Side Bracket RH	1		\$82.30	1
	Front Bumper Clips	10	\$2.20	\$22.00 🗸	
	Front Bumper Grille RH	1		\$28.38 \$1,570.55	NC10D/
	Front Wheel Rim RH	1		\$1,570.55	1001
	ALTO TOTAL			\$2,203.13	
	SUB TOTAL LESS 25%			\$550.78	
	DISCOUNTED TOTAL			\$1,652.35	
	Front Wheel Tyre RH	1		\$216.00	Suc
	NETT TOTAL			\$216.00	
	TOTAL SPARE PARTS			\$1,868.35	
	Labour Charge			\$400.00	350
	Panel Beating			\$300.00	250 /
	Spray Painting Charge			\$120.00	XNN /
	Wheel Alignment			\$120.00	(10.5
	TOTAL LABOUR			\$820.00	Ü
	ESTIMATE TOTAL			\$2,688.35	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

ThrouneChhauto-lom
82235769
2/12/2/ 1500
Mp her paint photo
2 clays wp

LKK Auto Consultants hence notify

the Repairer of the following: • To resurvey before/after spray painting

- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Date/70pm 12 12 2/01 18 50

PA70 :

ARC Repair TP(CLSO)] am MAED

JOB CARD Sales Indet: 4141682

s. no.305496499

COMPOST TRANSPORTATION FTR LTD 7010045 383 SIN MING DRIVE

Singapore SINGAPORE 575717 65508755

TOYOTA

SHC30749

PRIUS HVBRID (04A02.12.2021 11:15

28.02.2020

JTDKB3FU303091164

TAPPETOME

DAME FROM CHIEF THE

SOME CARREST

JOB DESCRIPTION

cident Date: 01.12.2021 TURE: 3P 01.12.2021/C

NO 0010

LABOR CODE

PB

DESCRIPTION PANEL BEATING-SHC3074G



ED & PASSED OUT BY		

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

agement Stip

SHC3074G

Vehicle No.

Exit Pass

SHC3074G

Service Advisor

Signature/Date

LIMTS

Name of Service Advisor

Date

imed to Service Reception upon collection

To be kept by Security Guard