COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

LXX-

DATE:

2-Dec-21

MODEL

Toyota Prius

VEHICLE NO SHC3074G

Wheel Alignment

HEURANCE CHINA TAIPING (PP)

MVA LIM TS

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT / Cut
	Front Bumper	1		\$499.90
	Front Bumper Side Bracket RH X	1		302.30
	Front Bumper Clips	10	\$2.20	\$22.00 / 1/6
	Front Bumper Grille RH XSVC	1		\$28.38
	Front Wheel Rim RH XNN	1		\$1,570.55
	MOULDING FRONT BUMPER SIDE RH - SUB TOTAL LESS 25% DISCOUNTED TOTAL			\$85.10 NEC \$2,203.13 \$550.78 \$1,652.35
		1		\$216.00 × 5uc
	Front Wheel Tyre RH NETT TOTAL	·		\$216.00
	TOTAL SPARE PARTS			\$1,868.35
	Labour Charge Panel Beating Spray Painting Charge			\$400.00 \$300.00 \$120.00 XNN

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

TOTAL LABOUR

ESTIMATE TOTAL

Though Elphauto. lom
82235769
2/12/2/ 1500
Plp hfr paint photo
2 clays wp

LKK Auto Consultants hence notify

\$820.00

\$2,688.35

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- · Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- . No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed <u>and</u> is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Date/70pm 12 12 2/01 18 50

PA70 :

ARC Repair TP(CLSO)] am HATEL

JOB CARD Sales Indet: 4141682

s. no.305496499

COMPOST TRANSPORTATION FTR LTD 7010045 383 SIN MING DRIVE

Singapore SINGAPORE 575717 65508755

TOYOTA

SHC30749

PRIUS HVBRID (04A02.12.2021 11:15

28.02.2020

JTDKB3FU303091164

TAPPETOME

DAME FROM CHIEF THE

SOME CARREST

JOB DESCRIPTION

cident Date: 01.12.2021 TURE: 3P 01.12.2021/C

NO 0010

LABOR CODE

PB

DESCRIPTION PANEL BEATING-SHC3074G



ED & PASSED OUT BY		

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

agement Stip

SHC3074G

Vehicle No.

Exit Pass

SHC3074G

Service Advisor

Signature/Date

LIMTS

Name of Service Advisor

Date

imed to Service Reception upon collection

To be kept by Security Guard