

⏪

⏩

1 of 2 ?

⏴

⏵

↺

↻

100% ▾

🖨

📄

Find | Next



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD			Ref: CS3/FCI21012291/Vqf3	
36 ROBINSON ROAD			Date: 06/12/2021	
#16-01 CITY HOUSESINGAPORE 068877			Code: FCI2	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	SMB 1515K	Veh. Inspected	SME 6035E	
Policy No.		Coverage (\$)	0.00	
Claim No.	D21003368MFBP	Excess (\$)	0.00	
Assign From	(CWS) JOANNE TAN JO ANN	Assign Date	06/12/2021	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	01/12/2021	Inspection Date	06/12/2021	
Survey held at	8 kaki bukit ave 4 #01-48 premier kaki bukit			
Repairer	MCWELL VENTURES PTE LTD			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				