

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte.
Ltd.
AIG Building, 78 Shenton Way
#09-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Azlan, Syazairdina

Date: 07 Dec 2021

Preliminary Advice

Vehicle No	: SKG6661K	Accident Date	: 04/12/2021
Make	: KIA SORENTO	Policy No.	: 2070052758
Assignment Date	: 06/12/2021	Excess	: S\$0.00
Date of Inspection	: 06/12/2021	Est. Duration of Repair	: 6
Inspection At	: CYCLE & CARRIAGE KIA PTE LTD (PANDAN GARDENS) 209 PANDAN GARDENS SINGAPORE 609339		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	11,539.20
Revised Amount	:S\$	6,208.40
Check Items (Estimated)	:S\$	3,671.20
Total	:S\$	9,879.60

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$ 165,000.00
COE / PARF Rebate	:S\$ 51,710.00
Salvage Value	:S\$

Margin for Repair

:S\$ 113,290.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to part prices and labour cost check.