



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
CHINA TAIPING INSURANCE (S) PTE LTD		Ref:	CS3/CTI21012300/Vqy3
3 ANSON ROAD #16-00		Date:	06/12/2021
SPRINGLEAF TOWERSINGAPORE 079909		Code:	CTI
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	PC 8576Y	Veh. Inspected	FBR 3246U
Policy No.		Coverage (\$)	0.00
Claim No.	SNM21D206992/C02/PC8576Y/LEEPG	Excess (\$)	0.00
Assign From	CECILIA LEE PENG GEOK	Assign Date	06/12/2021
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	28/11/2021	Inspection Date	06/12/2021
Survey held at	BLK 3006 UBI ROAD 1 #01-386		
Repairer	S1 MOTORING		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			