

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III21012303/AGA3Q2**Date:** 21/07/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D19MFL0005549_02
Claimant Vehicle No : SMP6553T **Insured Vehicle No :** GBB9932S
 Date of Loss: 01/12/2021 Nature of Claim: TP Claim No: MFL2021D0005313

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMP6553T**
 Make & Model: TOYOTA AQUA HYBRID, 1.5 E S CVT (A) Engine No: 1NZR607438
 Reg. Date: 07/10/2019 (Man. Year: 2018) Chassis No: NHP106695712
 Colour: Purple Odometer: 60751 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/60 R15 Rear Tyre Size: 185/60 R15
 Front Left Side: Firenza 6 mm Rear Left Side: Firenza 6 mm
 Front Right Side: Firenza 6 mm Rear Right Side: Firenza 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,952.56	2,045.42	12,907.14	86.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,530.00	1,770.00	3,760.00	67.99
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,482.56	3,815.42	16,667.14	81.37
Approved Total (Overridden) (S\$)		3,050.00		
Nett Amount (S\$)	20,482.56	3,050.00	17,432.56	85.11
+ Car Rental (5.0 x S\$80.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		3,486.45		
Global Sum Settlement (S\$)		3,450.00		

INSPECTION

Date of Assignment: 06/12/2021
 Date Inspected: 06/12/2021 Inspected At: PROVI AUTOWORKS PTE LTD (HQ)
 8 Kaki Bukit Avenue 4, #02-24 Premier @ Kaki
 Bukit
 Singapore 415875
 Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Jul 2022)
Parts:	144	TOYOTA AQUA HYBRID 1.5 E S CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMP6553T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Not Necessary	1,501.70 FL	*- FL
2	2		*FRONT BUMPER SIDE RETAINER	Not Necessary	250.00 FL	*- FL
3	1		*FRONT FENDER RH	Dented	706.50 FL	*706.50 FL
4	1		*FRONT FENDER QUARTER GARNISH RH	Not Necessary	97.80 FL	*- FL
5	1		*REAR FENDER EMBLEM (HYBRID)	Necessary	120.00 FL	*85.00 FL
6	1		*FRONT FENDER INNER COWLING RH	Torn	178.90 FL	*178.90 FL
7	1		*FRONT ABSORBER LH	Not Necessary	398.60 FL	*- FL
8	1		*FRONT LOWER ARM LH	Not Necessary	672.30 FL	*- FL
9	1		*FRONT KNUCKLE ARM LH	Not Necessary	890.00 FL	*- FL
10	1		*FRONT WHEEL BEARING LH	Not Necessary	289.00 FL	*- FL
11	1		*FRONT ORIGINAL RIM LH	Not Necessary	879.00 FL	*- FL
12	1		*FRONT DOOR RH	Dented	1,097.50 FL	*1,097.50 FL
13	2		*FRONT DOOR BLACK STICKER GARNISH RH	Necessary	90.00 FL	*90.00 FL
14	1		*FRONT DOOR OUTER MOULDING RH	Cut	198.00 FL	*198.00 FL
15	1		*FRONT DOOR OUTER HANDLE RH	Repair	267.00 FL	*- FL
16	1		*FRONT DOOR OUTER HANDLE COVER RH	Repair	45.00 FL	*- FL
17	1		*FRONT DOOR INNER TRIM RH	Not Necessary	578.20 FL	*- FL
18	1		*FRONT DOOR INNER LOCK RH	Not Necessary	312.00 FL	*- FL
19	1		*FRONT DOOR LOCK CATCH RH	Not Necessary	56.00 FL	*- FL
20	1		*FRONT DOOR WEATHERSTRIP RH	Not Necessary	198.00 FL	*- FL
21	1		*FRONT DOOR REGULATOR MOTOR RH	Not Necessary	457.30 FL	*- FL
22	1		*FRONT DOOR REGULATOR MOTOR RH	Not Necessary	322.00 FL	*- FL
23	1		*FRONT DOOR CHANNEL RH	Not Necessary	98.00 FL	*- FL
24	1		*FRONT DOOR CHANNEL SEAL RH	Not Necessary	155.20 FL	*- FL
25	1		*ROCKER PANEL	Repair	1,254.00 FL	*- FL
26	1		*CENTER PILLAR OUTER	Repair	1,212.00 FL	*- FL
27	1		*REAR DOOR RH	Repair	1,045.20 FL	*- FL
28	2		*REAR DOOR BLACK STICKER GARNISH RH	Not Necessary	90.00 FL	*- FL
29	1		*REAR DOOR OUTER MOULDING RH	Cut	198.00 FL	*198.00 FL
30	1		*REAR DOOR INNER TRIM RH	Not Necessary	594.00 FL	*- FL
31	1		*REAR DOOR INNER LOCK RH	Not Necessary	298.50 FL	*- FL
32	1		*REAR DOOR LOCK CATCH RH	Not Necessary	56.00 FL	*- FL
33	1		*REAR DOOR WEATHERSTRIP RH	Not Necessary	198.00 FL	*- FL
34	1		*DRIVER SEAT BELT	Not Necessary	954.00 FL	*- FL
35	1		*SRS AIRBAG CONTOR UNIT	Not Necessary	1,258.00 FL	*- FL
36	1		*FRONT BUMPER CLIP	Not Necessary	50.00 FS	*- FS
37	1		*FRONT TYRE RH	Not Necessary	450.00 FS	*- FS
38	1		*SET FRONT DOOR INNER TRIM CLIP	Necessary	50.00 FS	*30.00 FS
39	1		*SET REAR DOOR INNER TRIM CLIP	Not Necessary	50.00 FS	*- FS
40	1		*RIM HUP CAP	Cracked	500.00 FS	*100.00 FS
41	1		*CENTER PILLER SEALANT	Not Necessary	120.00 FS	*- FS
42	1		*ROCKER PANEL SEALANT	Not Necessary	120.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	18,355.70	2,683.90
- List Item Discount on L Items 20.00/25.00% (\$\$)	3,403.14	638.48

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
Total Parts (S\$)					14,952.56	2,045.42
Report was unsubmitted during this print-out.						

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING ,REMOVAL AND REPLACING PARTS	New	1,800.00	700.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,800.00	800.00
3	TO PERFORM LIGHTING & WIRING CHECK	New	150.00	30.00
4	TO APPLY ANTI-RUST & TUFF KOTE	New	250.00	80.00
5	REMOVE AND INSTALL FRONT DOOR PART	New	180.00	80.00
6	REMOVE AND INSTALL REAR DOOR PART	New	180.00	0.00
7	REMOVE AND INSTALL CARPET SEAT AND INTERIOR	New	450.00	0.00
8	REMOVE AND INSTALL FRONT UNDER CARRIAGE	New	600.00	0.00
9	TO CHECK FOUR WHEEL ALIGNMENT	New	120.00	80.00
Gross Labour Cost (\$)			5,530.00	1,770.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >