



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR21012304/Atf3e2	
			Date: 30/05/2022	
			Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHB 810Z	Veh. Inspected	FBS 8873X
	Policy No.		Coverage (\$)	0.00
	Claim No.	TAX/11/21/2029	Excess (\$)	0.00
	Assign From	HUA YEN	Assign Date	06/12/2021
2. Vehicle Particulars & Condition				
	Make & Model	YAMAHA MTN155	c.c	155
	Engine No.	HIDDEN	Year of Reg.	2021
	Chassis No.	MH3RG711000001203	Colour	WHITE
	Odometer	-	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	110/70 R17	IRC	6 mm
	L/H Front Tyre			mm
	R/H Rear Tyre	140/70 R17	IRC	6 mm
	L/H Rear Tyre			mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S AND N/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	17/11/2021	Inspection Date	06/12/2021
	Survey held at	PRO-JEX V2D MOTOR PTE LTD 25 KAKI BUKIT ROAD 4 #03-94 SYNERGY @ KB SINGAPORE 417800		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	