



HKL LIM TEAM MOTORSPORT

Bik 1008 #01-24, Bukit Merah Lane 3, Singapore 159722
Email: support@hklmteammotorsport.com.sg

Tel: 6275 6656, 6275 6566, 62727292 Fax: 6272 9291
Website: www.hklmteammotorsport.com.sg

FBP4278G

1	FRONT FORK ASSY LH/RH	/ BT (To repair)	\$1,600	280 / nett
2	FRONT FORK UNDER BRACKET	x nn	\$480	
3	STEERING CONE BEARING	- nec	\$120	/
4	FRONT FENDER	/ cut	\$180	/
5	FRONT WHEEL RIM	x nn	\$750	
6	FRONT WHEEL SHALF	x nn	\$60	
7	HANDLE BAR	/ BT	\$280	/
8	HANDLE BAR GRIP	x nn	\$25	
9	HANDLE BAR BALANCER	/ cut	\$60	/
10	HANDLE BAR GUARD SET	- cut	\$420	/
11	SIDE MIRROR LH	- cut	\$70	/
12	GEAR PEDAL	/ BT	\$120	/
13	FUEL TANK PANEL LH	- cut	\$280	/
14	SIDE STAND	/ BT	\$120	/
15	SIDE STAND PLATE	- cut	\$60	/
16	RADIATOR	/ DP	\$650	/
17	RADIATOR LH PANEL	- cut	\$95	/
18	LOWER COWLING	x nn	\$150	
19	REAR FOOT REST LH	/ cut	\$60	/
20	P PLATE	/ nec	\$12	/
21	TOP BOX	- cut	\$280	/
22	LABOUR		\$780	280 nett

23. Fairing Sticker - \$150 / nec

TOTAL AMOUNT:

\$6,652

6843.70

Steve CLKK)
9/12/21, 11:00a

W/L PL
3 d/s
P/P
M BIL sy

24. Gear pedal rod. & ss - BT

25. " " screw \$08 - BT

nett
560 /

P-3020
-10%
2718 /

Steve
21/12/21

P/P = 3278