

Hsiao Jeng

SJE :

Date of Survey : _____

Date of ReSurvey: _____

Contacts : _____

Vehicle Nos : **GBH 7166 T**

Model : Toyota Hiace

Year : 2018

Chassis No : GDH2012001915

*** AGREED Cost Of Repair and Repair Day/s with SJE ***

Amount: _____

Working Day: _____

Nos.	PARTS	Qty	Unit S\$	2018 TOTAL S\$	
1	Bonnet	1	\$ 844.50	\$ 634.30	844.50
2	Bonnet Logo	1	\$ 121.30	\$ 68.10	121.30
3	Bonnet Lock	1	\$ 181.90	\$	181.90
4	Front Bumper	1	\$ 568.20	\$ 468.20	568.20
5	Front Bumper Bracket	1	\$ 277.10	\$	277.10
6	Front Bumper Side Retainer	2	\$ 57.40 198.90	\$ 114.80	397.80
7	Front Bumper Reinforcement	1	\$ 571.80	\$	571.80
8	Front Bumper Lower Grille	1	\$ 271.50	\$ 208.90	271.50
9	Front Grille	1	\$ 781.30	\$ 329.50	781.30
10	Front Grille Outer Chrome Garnish	3	\$ 190.60 258.60	\$ 570.60	775.80
11	Front Grille Base	1	\$ 223.10	\$	223.10
12	Front Support Panel	1	\$ 571.80	\$	571.80
13	Front Support Panel Centre Bracket	1	\$ 65.30	\$	65.30
14	Front Support Panel Top Cover	1	\$ 271.60	\$	271.60
15	Front Support Panel Top Cover Rubber	1	\$ 121.60	\$	121.60
16	Headlamp	2	\$ 534.80 875.60	\$ 1109.60	1751.20
17	Radiator	1	\$ 1,817.10	\$	1,817.10
18	A/c Condenser	1	\$ 1,417.50	\$	1,417.50
Parts Sub Total :				\$ 5144.00	11,030.40
Discount :				\$ 1286.00	2,757.60
PARTS TOTAL :				\$	8,272.80

3858.00

DDV
NECV
NDX
BRV
NSX
NECV
NDX
BRV
BRV
BRV
BRV
NDX
NDX
NDX
NDX
BRV
NDX
BTV

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Sundries	1	\$ 80.00	\$ 80.00
2	Bonnet Sealant	1	\$ 100.00	\$ 100.00
3	Front Bumper Clips	1	\$ 50.00	\$ 50.00
4	Front Bumper Lower Grille Clips	1	\$ 50.00	\$ 50.00
5	Front Grille Clips	1	\$ 50.00	\$ 50.00
6	Front Grille Wrap Sticker	1	\$ 180.00	\$ 180.00
7	Front Support Panel Sealant	1	\$ 100.00	\$ 100.00
8	Front Support Panel Top Cover Clips	1	\$ 50.00	\$ 50.00
9	Coolant	1	\$ 80.00	\$ 80.00
10	A/c Fluid	1	\$ 80.00	\$ 80.00
11	Front Number Plate	1	\$ 80.00	\$ 80.00
SPECIAL NETT TOTAL :				\$ 900.00

200.00

Nos.	LABOUR	S\$
1	R&R Bonnet Component	\$ 150.00
2	R&R Radiator	\$ 150.00
3	R&R A/c Condenser	\$ 150.00
4	Diagnostic Reset Fault Code	\$ 300.00
5	Check wiring	\$ 100.00
6	Uplostery	\$ 300.00
7	Panel Beating	\$ 1,600.00
8	Rust Proofing	\$ 200.00
9	Spray Painting	\$ 1,600.00
LABOUR TOTAL :		\$ 4,550.00

1330.00

PARTS TOTAL : \$ 8,272.80
SPECIAL NETT TOTAL : \$ 900.00
LABOUR TOTAL : \$ 4,550.00
GRAND TOTAL : \$ 13,722.80

Parts 3858.00
SN 200.00
Labour 1330.00
@ 20% 5388.00
1077.60
4310.40

LS 4300/2
Trim Mm
31/1/2022

Survey 6/12/2021
Resurvey 7/12/2021
TGM in 1500hrs
TGM in 1645 hrs

Lump sum repair
Repair days 6

LS 4,300/2

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: