

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? Yes or No

GIA / PR Seen:

Consistent? Yes or No

Est. Repairs:

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Date / Time

Action / Instruction

Veh No:

Yr Regn:

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

c.c

Colour:

A/C:

Insured / Std / NI / NA

Sp. Reading

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

) S + RS ___ \$

) Photos

) Others

Report Format :

Lump Sum / I.B.I.: (\$

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

TOTAL

14/12/21 H/S 6200 confirmed mile Alan.

FASTECH AUTO PTE LTD
1 Kaki Bukit Ave 6 #01-48 Autobay
Singapore 417883
Tel No: 67452063/ 67467158 Fax No: 67458520
Tax Reg No : 200006262D

HS/M Tony

not Authorized
200
6/11/21
1/5 = 6200 /
4 day

VEHICLE No: SGP 1806T

1PC	REAR WINDSCREEN	11	\$1,655.10	X
1PC	REAR WINDSCREEN MOULDING	11	\$185.50	X
1PC	TAILGATE	22 1810.10	\$1,994.45	—
1PC	TAILGATE OUTER CHROME GARNISH	11	\$688.10	X
1PC	TAILGATE EMBLEM	11	\$68.90	X
1PC	TAILGATE INNER LOCK	20/shield 455.20	\$509.23	—
1PC	TAILGATE INNER TRIM BOARD	20-11 665.10	\$681.20	—
1PC	TAILGATE INNER PULL GARNISH	20-11	\$65.20	—
1PC	TAILGATE WEATHERSTRIP	20-11 329.50	\$399.45	—
1PC	TAILGATE KEYLESS SMART	11	\$185.30	X
1PC	TAILGATE KEYLESS BUZZLE	0-11	\$188.90	—
1PC	REAR BUMPER	22 088.50	\$1,655.10	—
2PCS	REAR BUMPER REFLECTORS @\$145.00	11	\$290.00	X
2PCS	REAR BUMPER SIDE RETAINERS @\$105.10	015 1st	\$210.20	12C
2PCS	REAR BUMPER BRACKETS @\$98.00	11	\$196.00	X
1PC	REAR END PANEL	22 700.50	\$755.23	—
1PC	REAR END PANEL TOP GARNISH	20-11 188.30	\$366.10	—
2PCS	TAILLAMPS @\$885.00	11	\$1,770.00	X
2PCS	TAILLAMP LOWER APRON GARNISHS @\$385.10	R	\$770.20	X
1PC	REAR FLOOR PANEL	R	\$1,410.50	X
1PC	REAR FLOOR PANEL TOP BOARD	20-11	\$655.80	—
1PC	REAR FLOOR PANEL CLOTH	11	\$820.10	X
2PCS	REAR FENDER INNER TRIM BOARDS @\$891.10	N/S an 015 2nd	\$1,782.20	12C
			\$17,302.76	

S.NETT

1PC	REAR WINDSCREEN SEALANT	11	\$50.00	40
1PC	REAR WINDSCREEN INNER SEAL	11	\$50.00	40
1PC	REAR LICENCE PLATE	11	\$50.00	X
1SET	REAR BUMPER REVERSE SENSOR	shield	\$380.00	200
1SET	REAR BUMPER CLIPS	11	\$50.00	—
1SET	TAILGATE INNER TRIM BOARD CLIPS	11	\$50.00	—
1PC	REAR END PANEL SEALANT	11	\$50.00	—
1SET	REAR REVERSCAMERA	11	\$380.00	X

TO CHECK WIRING	\$50.00	30
TO DISMANTLE & REPLACED REAR REVERSE SENSOR	\$80.00	50
TO DISMANTLE & REFIX REAR WINDSCREEN	\$150.00	120
TO DISMANTLE & REFIX CUSHION UPHOLSTERY	\$120.00	80

TO TRANSFER TAILGATE MECHANISM
 TO SPRAY RUST PROOFING
 TO RESET & REPROGRAMME SYSTEM
 LABOUR FOR PANEL BEATING & REPLACED PARTS
 TO PUTTY & SPRAY PAINTING

\$100.00 60
 \$100.00 80
 17 \$120.00 X
 \$1,500.00 880
 \$1,500.00 980
 TOTAL \$22,082.76

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-6743.30
 282
 P-5057.47
 5.1430
 L-2280
 7762.47
 282
 6112