

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III21012312/UGA3Q2**Date:** 18/04/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D19MFL0005549_02

Claimant Vehicle No : FBR2118M **Insured Vehicle No :** GBL1635A

Date of Loss: 01/12/2021 Nature of Claim: TP Claim No: MFL2021D0005306

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBR2118M**

Make & Model: YAMAHA XSR155 MANUAL, 155cc Engine No: G3J6E0259377

Reg. Date: 21/03/2020 (Man. Year: 2020) Chassis No: MH3RG4760LK003470

Colour: Black Odometer: 48242 km

Engine Capacity: 155 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 110/70-17 Rear Tyre Size: 140/70-17

Front Left Side: Metzeler 7 mm Rear Left Side: Metzeler 7 mm

Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,744.90	1,902.40	6,842.50	78.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,230.00	350.00	880.00	71.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,974.90	2,252.40	7,722.50	77.42
Approved Total (Overridden) (S\$)		1,800.00		
Nett Amount (S\$)	9,974.90	1,800.00	8,174.90	81.95
+ Loss of Use (6.0 x S\$20.00/day) (S\$)		120.00		
+ Other Costs (S\$)		50.00		
Nett Liability (S\$)		1,970.00		

INSPECTION

Date of Assignment: 06/12/2021

Date Inspected: 06/12/2021 Inspected At:

Erofia Motor Trading Pte Ltd - (kaki Bukit) (HQ)
1 Kaki Bukit Avenue 6, #02-62 AutoBay @ Kaki Bukit
Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 26 Jan 2022)	
Parts:	N/A	YAMAHA XSR155 MANUAL 155cc (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBR2118M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER	Cracked / Cut	220.00 FL	*220.00 FL
2	1		*FRONT FENDER SITE COVER-R/H	Cracked	80.00 FL	*80.00 FL
3	1		*FRONT FORK ASSY (O/S)	Damaged	3,450.00 FL	*900.00 FL
4	1		*FRONT FORK UNDER BRACKET	Not Necessary	1,060.00 FL	*- FL
5	1		*FRONT RIM	Not Necessary	1,250.00 FL	*- FL
6	1		*FRONT RIM SHAFT	Not Necessary	165.00 FL	*- FL
7	1		*FRONT RIM BEARING	Not Necessary	98.00 FL	*- FL
8	1		*FRONT BRAKE CALIPER	Not Necessary	720.00 FL	*- FL
9	1		*FRONT BRAKE DISC	Not Necessary	420.00 FL	*- FL
10	1		*HANDLE BAR	Bent	260.00 FL	*260.00 FL
11	1		*SET HANDLE BAR END	Cut	136.00 FL	*60.00 FL
12	1		*SET HAND GRIP	Not Necessary	80.00 FL	*- FL
13	1		*SET FRONT SIGNALS	Not Necessary	260.00 FL	*- FL
14	1		*SET FRONT MIRROR	Not Necessary	180.00 FL	*- FL
15	1		*CLUTCH LEVER	Cut	108.00 FL	*80.00 FL
16	1		*FRONT FOOTREST -L/H	Cracked	128.00 FL	*68.00 FL
17	1		*FRONT FOOTREST BRACKET	Not Necessary	180.00 FL	*- FL
18	1		*GEAR PEDAL	Cut	180.00 FL	*180.00 FL
19	1		*SIDE STAND	Repair	168.00 FL	*- FL
20	1		*REAR FOOTREST -L/H	Cut	98.00 FL	*68.00 FL
21	1		*REAR FOOTREST BRACKET	Not Necessary	220.00 FL	*- FL
22	1		*FORK OIL	O/S Necessary	42.00 FS	*20.00 FS
23	1		*FORK OIL SEAL	O/S Necessary	68.00 FS	*38.00 FS
24	1		*STEERING CONE	Necessary	120.00 FS	*120.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	9,691.00	2,094.00
- List Item Discount on L Items 10.00/10.00% (\$)	946.10	191.60
Total Parts (\$)	8,744.90	1,902.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PROVIDE TOWING SERVICE (LOD)	New	50.00	50.00
2	TO CHECK WIRING AND RESET HEADLAMP FOCUSING	New	80.00	0.00
3	TO REPAIR BODY FRAME	New	480.00	0.00
4	TO PROVIDE LABOUR	New	620.00	300.00
Gross Labour Cost (\$\$)			1,230.00	350.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >