


ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: FBR 2118M
 at Workshop m/s Enofo
 of _____
 Insured: GA 1635A
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____
 (Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: \$12,800
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 4 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: LTA 3821

Veh No: FBR 2118M Yr Regn: 21/13/20
 Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or
 Make: Yamaha XSR 155 c.c 155
 Colour: Black A/C: Insured / Std / NI / NA
 Sp. Reading: 48242 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: MH3RG 4760LK 003470
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Good / Jammed / Leaked / Burnt or
 Brake: Good / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 110/70-17
 R: 140/70-17
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or metzler
 Front _____ Rear _____
 R/Bal. 7 mm R/Bal. 7 mm
 L/Bal. _____ mm L/Bal. _____ mm
 D.O.A. 11/12/21 D.O.I. 6/12/21
 Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
015 F+ , 115 Body
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

new bike \$15500
check o1 report

4/12/21 1/5 \$1800 confirmed with mteco.

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

) S + RS, SI

☐

: Interview (\$

) Photos

☐

: Tech. Invs (\$

) Others

☐

: Weekend (\$

)

Report Format :

Lump Sum / I.B.I.: (\$

TOTAL

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

E-mail: erofia@singnet.com.sg

INDIA

Owner : Jacon Eu (87821867)

Accident Date : 01-Dec-21

Vehicle No : FBR2118M

Yamaha

Vehicle Model : XSR155 Manual

Estimated Repair Costs

4 days

Qty	Description	Amount S(\$)
<u>List Items</u>		
1	Front fender	one/one \$ 220.00 ✓
1	Front fender site cover - R/H	one \$ 80.00 ✓
1	Front fork assy o/s	900 o/s Day \$ 3,450.00 ✓
1	Front fork under bracket	11 \$ 1,060.00 X
1	Front rim	11 \$ 1,250.00 X
1	Front rim shaft	11 \$ 165.00 X
1	Front rim bearing	11 \$ 98.00 X
1	Front brake caliper	11 \$ 720.00 X
1	Front brake disc	11 \$ 420.00 X
1	Handle bar	but \$ 260.00 ✓
1	Handle bar end (1 set)	60 one \$ 136.00 ✓
1	Hand grip (1 set)	11 \$ 80.00 X
1	Front signals (1 set)	11 \$ 260.00 X
1	Front mirror (1 set)	11 \$ 180.00 ✓
1	Clutch lever	80 one \$ 108.00 ✓
1	Front footrest - L/H	68 one \$ 128.00 ✓
1	Front footrest bracket	11 \$ 180.00 X
1	Gear pedal	cut \$ 180.00 ✓
1	Side stand	2 \$ 168.00 X
1	Rear footrest - L/H	68 one \$ 98.00 ✓
1	Rear footrest bracket	11 \$ 220.00 X
		\$ 9,461.00
Less 10%		\$ 946.10
		\$ 8,514.90

Special Net Items

2	Fork oil	o/s \$ net 42.00 20
2	Fork oil seal	o/s \$ net 68.00 38
1	Steering cone	\$ net 120.00 ✓
		\$ 230.00

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

E-mail: erofia@singnet.com.sg

Owner : Jacon Eu (87821867)

Accident Date : 01-Dec-21

Yamaha

Vehicle No : FBR2118M

Vehicle Model : XSR155 Manual

Estimated Repair Costs

S/No. Labour

1	To provide towing service (LOD)	\$	50.00	✓
2	To check wiring and reset headlamp focusing	\$	12 80.00	X
3	To repair body frame	\$	11 480.00	X
4	To provide labour	\$	620.00	300
		\$	1,230.00	

Grand Total

\$ 9,974.90

Singapore Dollars: Nine Thousand Nine Hundred Seventy-Four and Cents: Ninety only

EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

p. 1916
102
1724
222.4

BIKE RECOVERY SERVICE

HP: 8298 6622

Business Reg. No: 201216510M

CASH SALE

NO: 02164

Date: 3/12/21

Particular: _____

Vehicle No: FBR 2118 M Model No: XSR

From: 682 Edgedale . To: Kui Fook Senh To ERO FIA

Time: (Day/Night): _____

Others: _____

CASH \$: 50/-

NOTE: Vehicle is towed at owner's risk. The Company accepts no responsibility for damages or others misdemeanour to your vehicle while being towed.