



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CS3/CTI21012315/Gty3 Date: 06/12/2021 Code: CTI	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SJX 7592S	Veh. Inspected	SMJ 4183Y
	Policy No.	DMPCSNW00166112000	Coverage (\$)	0.00
	Claim No.	SNM21D207033/C02/TOHHS	Excess (\$)	0.00
	Assign From	ALFRED TOH	Assign Date	06/12/2021
2. Vehicle Particulars & Condition				
	Make & Model		c.c	0
	Engine No.	HIDDEN	Year of Reg.	
	Chassis No.		Colour	
	Odometer	-	Steering	
	Brakes		Modification	
	General			
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm
4. Description of Damages				
5. General Information				
	Accident Date	03/12/2021	Inspection Date	06/12/2021
	Survey held at	ECO AUTOMOBILE CLAIMS & REPAIR PTE LTD 15 KAKI BUKIT ROAD 4 #01-53 BARTLEY BIZ CENTRE SINGAPORE 417808		
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			