

****Don't bother the red colour marked.**

BIFROST AUTO PTE LTD

8 KAKI BUKIT AVE 4, PREMIER @ KAKI BUKIT #01-49 SINGAPORE 415875

Tel: +65 64524457

Fax: +65 64524584

Company Reg No: 201929175W

Estimate		Vehicle No: SGE205S	
		Make and model: Toyota Wish	
		Chassis: ZNE100282567	
Qty	Spare parts		
1	Tailgate	\$	✓ 1,201.40 DDV✓
1	Tailgate windscreen glass	\$	945.00 NDX
1	Tailgate windscreen glass rubber moulding	\$	✓ 72.90 NECV
1	Tailgate centre emblem	\$	✓ 50.20 NECV
1	Tailgate outer chrome garnish	\$	239.50 NNX
1	Tailgate lock	\$	443.50 501.30 JMV
1	Tailgate lock catch	\$	32.80 NDX
1	Tailgate inner trim board ✗	\$	✓ 328.80 BRV
1	Tailgate weatherstrip	\$	304.60 NDX
1	Rear bumper	\$	450.00 495.40 DDV
1	Rear bumper RH reflector	\$	59.06 NDX
1	Rear bumper LH reflector	\$	48.90 59.06 BRV
1	Rear bumper RH bracket	\$	✓ 48.44 } BRV
1	Rear bumper LH bracket	\$	✓ 48.44 } BRV
1	Rear bumper RH retainer	\$	✓ 57.05 } NECV
1	Rear bumper RH retainer	\$	✓ 57.05 } NECV
1	RH taillamp assy ✗	\$	417.90 472.90 BRV
1	RH taillamp sponge gasket	\$	✓ 22.30 NECV
1	LH taillamp assy	\$	417.90 472.90 BRV
1	LH taillamp sponge gasket ✗	\$	✓ 22.30 NECV
1	Rear LH fender inner trim board	\$	709.30 } NDX
1	Rear RH fender inner trim board	\$	709.30 } NDX
1	End panel ✗	\$	✓ 468.90 DDV
1	End panel (inner)	\$	135.00 NSX
1	End panel inner garnish	\$	213.00 245.60 BRV
1	Rear compartment top cover board	\$	245.60 NDX
1	Spare tyre carriage	\$	328.50 NDX
1	Exhaust silencer	\$	798.00 } NDX
1	Exhaust silencer gasket	\$	67.00 } NDX
		\$	4,360.90 9,198.60
		-25%	\$ 1,092.25 2,299.65
		\$	3,276.74 6,898.95
Qty	Spare parts		

- 1 Tailgate windscreen glass sealant
- 1 Tailgate windscreen glass inner seal
- 1 Tailgate reverse camera
- 1 Tailgate emblem
- 1 set Tailgate inner trim board clips
- 1 set Rear bumper clips
- 1 set Rear bumper reverse sensor
- 1 End panel joint sealant

\$ 30.00	70.00 NECV ✓
\$ 30.00	50.00 NECV ✓
\$	550.00 NDX
\$	55.00 RPTX
\$ 30.00	70.00 NECV ✓
\$ 30.00	70.00 NECV ✓
\$ 200.00	320.00 SC ✓
\$ 40.00	60.00 NECV ✓
<u>360.00</u>	

Labour and painting

Labour charges to remove, check, replace and reinstall damages bodyparts.
To panel beating, cut / weld and re-align all affected panels

\$ 600.00 1,000.00 ✓

Spray painting on affected panels

\$ 600.00 1,000.00 ✓

Check wiring and lighting system

\$ -80.00

Apply rust coating chemical on affected panels

\$ -80.00

Remove and reinstall tailgate windscreen glass to assist repair

\$ 120.00 200.00 ✓

Remove and replace tailgate inner mechanism to new gate

60

\$ 80.00 180.00 ✓

Remove and replace rear inner trims, garnish and boards to assist repair

\$ 250.00 NNX

Remove and replace rear bumper reverse sensors to assist repair

\$ 60.00 100.00 ✓

Remove and replace exhaust silencer and gasket

\$ 120.00 NNX

Remove and replace tailgate reverse camera to assist repair

\$ 150.00 NNX

Survey Resurvey
7/12/2021 9/12/2021
TGuin Win TGuin Win

Lump sum repair
Repair days 8

Total: \$ 11,303.95

1400 hrs

1445 hrs

* Wrapping must provide invoice.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer
Signature:
Date:

Parts	5,276.74
SN	360.00
Labour	1,160.00
	5,096.74
@ 20%	1,019.35
	4,077.39

LS H050/2 TGuin Win
12/12/21