



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile  |  |  |                |
|--|--|--|----------------|
| CHINA TAIPING INSURANCE (S) PTE LTD<br>3 ANSON ROAD #16-00<br>SPRINGLEAF TOWERSINGAPORE 079909   |  | Ref: CS3/CTI21012321/Evy3<br>Date: 06/12/2021<br>Code: CTI |                |
| <b>1. Policy Particulars :- (THIRD PARTY CLAIM)</b>  |  |  |                |
| <b>Insured Veh.</b>  | GX 6228L   | <b>Veh. Inspected</b>                                      | SMS 719G       |
| <b>Policy No.</b>  | DMCVSNW00037742107   | <b>Coverage (\$)</b>                                       | 0.00           |
| <b>Claim No.</b>   | SNM21D206878/C02/IRENE   | <b>Excess (\$)</b>   | 0.00           |
| <b>Assign From</b>   | IRENE TAY  | <b>Assign Date</b>   | 06/12/2021     |
| <b>2. Vehicle Particulars &amp; Condition</b>  |  |  |                |
| <b>Make &amp; Model</b>  |  | <b>c.c</b>   | 0              |
| <b>Engine No.</b>  | HIDDEN   | <b>Year of Reg.</b>  |                |
| <b>Chassis No.</b>   |  | <b>Colour</b>  |                |
| <b>Odometer</b>  | -  | <b>Steering</b>  |                |
| <b>Brakes</b>  |  | <b>Modification</b>  |                |
| <b>General</b>   |  |  |                |
| <b>3. Conditions of Tyres</b>  |  |  |                |
|  | <b>Size</b>  | <b>Make</b>  | <b>Balance</b> |
| <b>R/H Front Tyre</b>  |  |  | mm             |
| <b>L/H Front Tyre</b>  |  |  | mm             |
| <b>R/H Rear Tyre</b>   |  |  | mm             |
| <b>L/H Rear Tyre</b>   |  |  | mm             |
| <b>4. Description of Damages</b>   |  |  |                |
|  |  |  |                |
| <b>5. General Information</b>  |  |  |                |
| <b>Accident Date</b>   | 26/11/2021   | <b>Inspection Date</b>                                     | 06/12/2021     |
| <b>Survey held at</b>  | WENG FATT MOTOR ENGINEERING<br>BLK 1004 BUKIT MERAH LANE 3 #01-15 SINGAPORE 159720 |  |                |
| <b>5a. Remarks</b>   |  |  |                |
| A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.<br>B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.<br>THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.<br>C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. |  |  |                |