

(02/11/13) wef

ASS. REC. BY: marcus

REF:

CC4/ASM21012325/UGS3**ASSIGNMENT**

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: JQR8144at Workshop m/s Entire

of _____

Insured: GP 6563K

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: RM5000IDAC Accident Report: Consistent? **Yes or No**GIA / PR Seen: Consistent? **Yes or No**Est. Repairs: 5 days Res.: **Yes or No**Lum Sum: 2 % 3 Val.: **Yes or No**

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: SV 950Veh No: JQR8144 Yr Regn: 17/1/15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or 1152Make: Yamaha Legend c.c. 115Colour: Red A/C: **Insured / Std / NI / NA**Sp. Reading: 2910 T/Radio: **Insured / Std / NI / NA**

Eng/No: _____

C/No: PMYUE0720 F0043743Gen. Cond: **Good / Fair / Poor / Burnt**Steering: **Inorder / Jammed / Leaked / Burnt or** affectedBrake: **Inorder / Jammed / Leaked / Burnt or**Modi: **Nil / S/Rim / STD A/Rim or**Tyre Size: F: 70/90-17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

Rear

R/Bal. 3 mm R/Bal. 1 mm

L/Bal. _____ mm L/Bal. _____ mm

D.O.A. 1/6/21 D.O.I. 7/1/21

Survey held at _____

Des. of Damages: **Frt / Rear / O/S / N/S / U/C / Rooftop or**N/S, 0/5 90/4

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

21/1/21 4/5 8 1650 continued with MR 720.

Date/Time, File Pass to?

☐

Preli. Report

Days Of Repair: _____

1)

☐

Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2)

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Survey Fee:

Transportation:

S + RS, \$

Photos

Others

Report Format : _____

Lump Sum / I.B.I. (\$) _____)

TOTAL



**SINGA
POLICE**

Traffic Police
10 Ubi Avenue 3
Singapore 408865
Tel +65 6547 6200
Fax +65 6547 6259
www.police.gov.sg

Your Ref :
Our Ref : TP/IP/26771/2021
Date : 14 October 2021

**MOHAMAD NAZRI BIN ISMAIL
AUTO POOL PTE LTD
1 BUKIT BATOK CRESCENT
WCEGA PLAZA #04-35
SINGAPORE 658064**

Dear Sir/Mdm,

**ROAD TRAFFIC ACCIDENT INVOLVING JQR8144 AND GP6563K ALONG KEPPEL
ROAD TOWARDS MCE AFTER AYE, LAMPPOST 6 ON 1 JUNE 2021 AT ABOUT 10.23
A.M.**

I refer to the above accident.

2. We have completed our investigations into the case. Our investigations revealed that the offence of **Careless Driving Causing Grievous Hurt under Section 65(1)(b) of the Road traffic Act, Chapter 276, punishable under Section 65(3)(a) read with Section 65(6)(d) of the Road Traffic Act** was disclosed against the driver of **GP6563K**. Action has been initiated against the driver for the aforesaid offence.
3. Should you need any clarification, please contact Investigation Officer Ng Beifeng at Tel: 6547 6845.

Yours faithfully,

**NG BEIFENG
for HEAD INVESTIGATION
TRAFFIC POLICE
SINGAPORE POLICE FORCE**

NP 510

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

E-mail: erofia@singnet.com.sg

AXIA

Name : Siti Norhana Binti Sukimin
(83740107)

Accident Date : 01-Jun-21

Vehicle No : JQR8144

Yamaha
Vehicle Model : **Lagenda 115**
Ziest

Estimated Repair Costs

Qty	Description	Amount S(\$)
<u>List Items</u>		
2	Front fork tube assy <i>sent/hu</i>	\$ 640.00 ✓
1	Fork under bracket <i>hu</i>	120 \$ 185.00 ✓
1	Front wheel rim <i>worand / sent</i>	\$ 380.00 ✓
1	Front rim shaft <i>in</i>	\$ 45.00 x
1	Front rim bearing <i>sent</i>	30 \$ 42.00 ✓
1	Front brake disc <i>sent</i>	\$ 185.00 x
1	Handle bar <i>sent</i>	\$ 88.00 ✓
2	Handle bar ends <i>sent</i>	50 \$ 78.00 ✓
1	Hand grip (1 set) <i>in</i>	\$ 138.00 x
1	Handle bar inner bracket <i>one</i>	60 \$ 88.00 ✓
1	Meter <i>sent</i>	420 \$ 485.00 ✓
2	Side mirrors (1 set) <i>BRO</i>	80 \$ 120.00 ✓
2	Front signals <i>o/s one</i>	60 \$ 160.00 1pc
1	Front signal lower garnish <i>one</i>	\$ 115.00 ✓
1	Brake lever <i>sent</i>	\$ 48.00 ✓
1	Master pump <i>in</i>	\$ 280.00 x
1	Fairing assy (1 set) <i>one</i>	\$ 525.00 ✓
1	Basket <i>in</i>	\$ 65.00 ✓
1	Front footrest bracket <i>sent</i>	\$ 65.00 ✓
2	Front footrest rubbers <i>to in</i>	60 \$ 70.00 ✓
1	Brake pedal <i>sent</i>	\$ 68.00 ✓
1	Gear pedal <i>sent</i>	\$ 68.00 ✓
2	Rear footrests <i>sent</i>	\$ 80.00 x
2	Rear footrest brackets <i>in</i>	\$ 156.00 x
1	Magnet housing <i>one</i>	\$ 280.00 ✓
1	Side stand <i>in</i>	\$ 70.00 x
1	Main stand <i>sent</i>	\$ 95.00 ✓
1	Exhaust assy <i>in</i>	\$ 685.00 x
1	Exhaust protector - chrome <i>sent</i>	\$ 78.00 ✓
1	Exhaust protector - matt black <i>sent</i>	\$ 60.00 ✓
		\$ 5,442.00
Less 10%		\$ 544.20
		\$ 4,897.80

3390

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

E-mail: erofia@singnet.com.sg

Name : **Siti Norhana Binti Sukimin**
(83740107)

Accident Date : **01-Jun-21**

Vehicle No : **JQR8144**

Yamaha
Vehicle Model : **Legenda 115**
Ziest

Estimated Repair Costs

Special Net Items

1	Number plate (1 set)	sent/acc	\$	38.00	20
2	Fork oils	17	\$	30.00	X
2	Fork oil seals	17	\$	56.00	X
1	Steering cone (1 set)	acc	60 \$	90.00	✓
1	Sticker	Sticker acc	\$	120.00	60
1	Rear box	mis	\$	380.00	200
1	Rear box bracket	acc	\$	180.00	X
1	E.R.P. IU (LOD)	acc	\$	180.00	X
			\$	1,074.00	

S/No. Labour

1	To provide towing service (LOD)	\$	35.00	✓
2	To check wiring and reset headlamp focusing	\$ 17	80.00	X
3	To provide labour	\$	420.00	380
4	To repair body frame	\$ 17	350.00	X
		\$	885.00	

Grand Total

\$ 6,856.80

Singapore Dollars: Six Thousand Eight Hundred Fifty-Six and Cents: Eighty only

EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

3800
204