

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG21012327/BEA3Q2**Date:** 13/04/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800064841
Claimant Vehicle No :	SLF6370T	Insured Vehicle No :	SJS717Y
Date of Loss:	03/12/2021	Nature of Claim:	TP
		Claim No:	4583631100SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLF6370T	Engine No:	3ZRB750648
Make & Model:	TOYOTA HARRIER, 2.0 Premium (A)	Chassis No:	ZSU600074569
Reg. Date:	01/09/2016 (Man. Year: 2016)	Odometer:	141289 km
Colour:	Silver		
Engine Capacity:	1986 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55 R18	Rear Tyre Size:	235/55 R18
Front Left Side:	KASPER 4 mm	Rear Left Side:	KASPER 4 mm
Front Right Side:	KASPER 4 mm	Rear Right Side:	KASPER 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,596.32	7,445.90	9,150.42	55.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,600.00	2,410.00	2,190.00	47.61
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,196.32	9,855.90	11,340.42	53.50
Approved Total (Overridden) (S\$)		7,850.00		
(S\$)	21,196.32	7,850.00	13,346.32	62.97
+ GST 7.00/7.00% (S\$)	1,483.74	549.50	934.24	62.97
Nett Amount (S\$)	22,680.06	8,399.50	14,280.56	62.97
+ Car Rental (9.0 x S\$150.00/day + 7.00% GST) (S\$)		1,444.50		
+ Doc/Search Fee (S\$)		7.45		
+ Other Costs (S\$)		90.00		
Nett Liability (S\$)		9,941.45		
Global Sum Settlement (S\$)		9,940.00		

INSPECTION

Date of Assignment:	06/12/2021	
Date Inspected:	06/12/2021	Inspected At: 160 SIN MING DRIVE #01-14
Estimated Period of Repair:	8.0 days	Repairer: Team Autopro Pte Ltd - Sin Ming (HQ)

Adjuster: Lim Teow Guan**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	1,821.50 FL	*1,369.50 FL
2	1		*TAILGATE LOGO	Necessary	68.40 FL	*68.40 FL
3	1		*TAILGATE EMBLEM HARRIER	Necessary	95.40 FL	*75.30 FL
4	1		*TAILGATE OUTER GARNISH	Broken	490.50 FL	*402.20 FL
5	1		*TAILGATE LOCK ASSY	Jammed	497.35 FL	*355.50 FL
6	1		*TAILGATE STRIKER	Not Damaged	41.50 FL	*- FL
7	1		*TAILGATE INNER TRIM BOARD	Broken	581.60 FL	*581.60 FL
8	2		*TAILGATE ELECTRICAL DAMPER	Not Damaged	1,321.00 FL	*- FL
9	2		*TAILGATE HINGES	Not Damaged	137.00 FL	*- FL
10	1		*TAILGATE WEATHERSTRIP	Torn	341.66 FL	*341.66 FL
11	1		*TAILGATE LAMP	N/S Broken	1,370.40 FL	*559.00 FL
12	1		*TAILGATE WINDSCREEN MOULDING	Necessary	195.20 FL	*133.00 FL
13	1		*TAILGATE SMART KEYLESS SENSOR	Not Necessary	230.50 FL	*- FL
14	1		*TAILGATE BUZZER	Not Necessary	188.30 FL	*- FL
15	1		*REAR BUMPER	Broken	1,675.30 FL	*1,381.00 FL
16	1		*REAR BUMPER LOWER	Broken	501.60 FL	*453.20 FL
17	2		*REAR BUMPER SIDE RETAINER	Necessary	340.00 FL	*150.80 FL
18	2		*REAR BUMPER BRACKET	Necessary	137.00 FL	*137.00 FL
19	1		*REAR BUMPER REINFORCEMENT	No such part	715.00 FL	*- FL
20	1		*REAR BUMPER SPONGE	Broken	227.80 FL	*127.80 FL
21	1		*REAR BUMPER REFLECTOR	Not Damaged	156.90 FL	*- FL
22	1		*REAR END PANEL	Dented	921.30 FL	*715.50 FL
23	1		*REAR END PANEL TOP GARNISH	Broken	397.40 FL	*321.30 FL
24	1		*SPARE TYRE PANEL	Dented	796.38 FL	*796.38 FL
25	1		*SPARE TYRE PANEL TOP BOARD	Not Damaged	733.40 FL	*- FL
26	1		*SPARE TYRE PANEL TOOLS TRAY	Not Damaged	507.30 FL	*- FL
27	2		*TAILLAMP	Broken	1,770.40 FL	*1,185.40 FL
28	2		*TAILLAMP LOWER BRACKET	No such part	209.00 FL	*- FL
29	1		*REAR FENDER LH	Repair	1,476.00 FL	*- FL
30	2		*FENDER INNER TRIM BOARD	Not Damaged	1,650.00 FL	*- FL
31	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
32	1		*TAILGATE SEALANT	Necessary	100.00 FS	*30.00 FS
33	1		*TAILGATE OUTER GARNISH CLIPS	Necessary	50.00 FS	*30.00 FS
34	1		*TAILGATE INNER TRIM BOARD CLIPS	Necessary	60.00 FS	*30.00 FS
35	2		*TAILGATE LAMP SEAL	Necessary	120.00 FS	*60.00 FS
36	2		*TAILGATE LAMP CLIPS	No such part	100.00 FS	*- FS
37	1		*TAILGATE WINDSCREEN SEALANT	Necessary	100.00 FS	*60.00 FS
38	1		*TAILGATE WINDSCREEN INNER SEAL	Not Necessary	60.00 FS	*- FS
39	1		*TAILGATE WINDSCREEN PRIMER AND CLEANER	Not Necessary	80.00 FS	*- FS
40	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
41	1		*REAR BUMPER LOWER CLIPS	Necessary	50.00 FS	*30.00 FS
42	2		*REAR BUMPER REVERSE SENSOR	Scratched	500.00 FS	*200.00 FS
43	1		*REAR END PANEL SEALANT	Necessary	100.00 FS	*30.00 FS
44	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	50.00 FS	*20.00 FS
45	2		*TAILLAMP SEAL	Necessary	120.00 FS	*60.00 FS
46	2		*TAILLAMP CLIPS	Not Necessary	100.00 FS	*- FS
47	2		*REAR FENDER INNER TRIM BOARD CLIPS	Not Necessary	100.00 FS	*- FS
48	1		*REAR NUMBER PLATE W/CASING	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	21,495.09	9,734.54
- List Item Discount on L Items 25.00/25.00% (\$\$)	4,898.77	2,288.64
Total Parts (\$\$)	16,596.32	7,445.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	R&R TAILGATE COMPONENT	New	150.00	80.00
2	R&R TAILGATE WINDSCREEN	New	250.00	120.00
3	R&R REAR BUMPER REVERSE SENSOR	New	100.00	60.00
4	DIAGNOSTIC RESET FAULT CODE	New	300.00	120.00
5	CHECK WIRING	New	100.00	30.00
6	UPHOLSTERY	New	300.00	0.00
7	PANEL BEATING	New	1,600.00	1,000.00
8	RUST PROOFING	New	200.00	0.00
9	SPRAY PAINTING	New	1,600.00	1,000.00
Gross Labour Cost (S\$)			4,600.00	2,410.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >