

ASS. REC. BY: TGum

REF:

CCA/GRB21012328/Bea3

Ashen

ASSIGNMENT

From: _____ Date: 7/12/2021

Veh No: SJ8 1649P Yr Regn: 27/4/2009

Estimated Cost: _____

Type: M.Car / Bus / Van / Lorry / Taxi / Prime Mover /

OD / WS / TP RES / OD RES / EVA / INV / MV

Truck / Trailer or _____

To Inspect Vehicle No: SJ8 1649P

Make: Suzuki SX4 Sedan c.c. 1586

at Workshop m/s Bifrost Auto

Colour: Green A/C: Insured / Std / NI / NA

of 8 Kakit Ave 4 Premier #01-49

Sp. Reading: 194012 T/Radio: Insured / Std / NI / NA

Insured: _____

Eng/No: M16A1A63574

Policy No. _____

C/No: JSAG YC 21500203747

Claims No. _____

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured: _____ Excess: _____

Steering: In order / Jammed / Leaked / Burnt or _____

(Client's Record)


Brake: In order / Jammed / Leaked / Burnt or _____

Make of Veh: _____

Modi: Nil / RIM / STD A/Rim or _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Tyre Size: F: 205/55/17 MIC

R: 215/50/17 Yoko

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Bal. or Market Value: 14,000/-

Front _____ Rear _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

R/Bal. 4 mm R/Bal. 5 mm

GIA / PR Seen: _____ Consistent? : Yes or No

L/Bal. 4 mm L/Bal. 5 mm

Est. Repairs: 5 days Res.: Yes or No

D.O.A. 6/12/2021 D.O.I. 7/12/21

Lum Sum: _____ % 3 Val.: Yes or No

Survey held at Bifrost Auto

CA / REV / REP. / 24 HRS UP

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or _____

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Range : 3,000/- - 4,000/-
	Recommended COR: LS 3,500.00 TGum Min
	MV 14,000/-
	PV 5,802/-
	NV 8,198/-

Date/Time, File Pass to? : Preli. Report

Days Of Repair: _____

1) : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

Survey Fee:	_____
Transportation:	_____
_____ \$ + RS _____ \$	_____
Photos	_____
Others	_____
TOTAL	_____

2) _____

Add Fee: : Site Insp (\$ _____)

: Interview (\$ _____)

: Tech. Invs (\$ _____)

: Weekend (\$ _____)

Report Format: _____

Lump Sum / L.S. / C. _____

BIFROST AUTO PTE LTD
 8 KAKI BUKIT AVE 4 #01-49
 SINGAPORE 415875
 TEL: 64524457 FAX: 64524584
 ATT: IKHWAN HP 93290237

Estimate for SJQ1649P(Suzuki SX4 Sedan)

			2009
1 *REAR BUMPER	546.00	\$694.65	BRV
1 *REAR BUMPER REFLECTOR R	19.00	\$124.10	} BRV ✓
1 *REAR BUMPER REFLECTOR L	19.00	\$124.10	
2 *REAR BUMPER BRACKET		\$156.00	NSX
2 *REAR BUMPER SIDE RETAINER	46.00	\$128.10	NECV ✓
1 *REAR BUMPER REINFORCEMENT	215.30	\$269.80	BR ✓
1 *REAR BUMPER LOWER CENTRE SPOILER	600.00	\$827.05	DLV ✓
1 *REAR BUMPER SIDE LOWER SPOILER		\$764.30	NSX
1 *TAIL LAMP L	241.85	\$517.20	} BRV ✓
1 *TAIL LAMP R	241.85	\$517.20	
1 *REAR BOOT LID	750.00	\$874.20	BT ✓
1 *REAR BOOT MECHANISM LOCK	135.00	\$215.10	JMV ✓
1 *REAR BOOT WEATHERSTRIP		✓ \$112.60	TNV ✓
1 *REAR BOOT LID SPORTS LOGO		✓ \$48.50	} NECV ✓
1 *REAR BOOT LID SUZUKI EMBLEM		✓ \$66.75	
1 *REAR BOOT LID SX4 EMBLEM		✓ \$27.35	
1 *REAR END PANEL	216.75	\$434.85	DD ✓
1 *REAR END PANEL TOP GARNISH	68.55	\$102.75	BRV ✓
1 *REAR SPARE WHEEL PANEL		\$565.90	NDX
1 *REAR EXHAUST SILENCER BOX ASSY		\$634.70	BDXR
	3354.50	\$7,205.20	
Less 15%	503.18	\$1,080.78	
	<u>2851.33</u>	<u>\$6,124.42</u>	
*REVERSE CAMERA		\$300.00	NDX
*REVERSE SENSOR	200.00	\$280.00	SC ✓
*REAR BUMPER CLIPS	30.00	\$45.00	NECV ✓
*END PANEL TOP GARNISH CLIPS		✓ \$30.00	NECV ✓
	<u>260</u>	<u>\$655.00</u>	
TO REMOVE AND REARRANGE ELECTRICAL WIRINGS, CHECK LIGHTINGS		\$80.00	NSX
TO REMOVE AND REPLACE UPHOLSTERY, TRIM GARNISHES TO FACILITATE REPAIR		\$100.00	NSX
TO REMOVE, REPAIR AND REPLACE DAMAGE BODYPARTS AND WHERE CONSISTENT TO THE ACCIDENT		\$1,200.00	600.00 ✓
PUTTY AND RESPRAY PAINTING ON AFFECTED PORTIONS		\$1,000.00	600.00 ✓
TO REMOVE AND RENEW REVERSE SENSOR		\$150.00	60.00 ✓
RUST PROOFING ON AFFECTED PORTIONS		\$100.00	} NNX
TO REMOVE, REPLACE EXHAUST SILENCER BOX & RE-ALIGN		\$120.00	
		<u>\$2,750.00</u>	
			12,600.00

Total

\$9,529.42

Survey & Resurvey

7/12/2021

1500 hrs

TG Kim

Lump sum repair

Repair days 5

Parts	2851.33
SN	260.00
Labour	1260.00
	<hr/>
	4371.33
@ 20%	874.27
	<hr/>
	3497.06

LS 3500hr

TG Kim
8/2/2022

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: