

**Note: This document has not been finalised.**

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Christina Wong

Date: 11 Feb 2022

**Preliminary Advice**

Insured : SMH7047Z  
Vehicle No  
TP Vehicle No : SMT3596T  
Make : TOYOTA ESTIMA  
Date of Inspection : 07/12/2021  
Inspection At : BIFROST AUTO PTE LTD (KAKI BUKIT)  
8 KAKI BUKIT AVE 4, #01-49, PREMIER @ KAKI BUKIT  
SINGAPORE 415875

Accident Date : 30/11/2021  
Assignment Date : 06/12/2021  
Est. Duration of Repair : 6

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	19,381.02
Revised Amount	:S\$	7,118.94
Check Items (Estimated)	:S\$	0.00
Total	:S\$	7,118.94

Lump Sum Repair	:S\$	5,700.00
-----------------	------	----------

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$

Salvage Value :S\$  
Margin for Repair :S\$

**Remarks**

- ( ) The vehicle is economical for repair
  - ( ) The vehicle is not economical for repair
  - ( ) Part-by-Part repair
  - ( X ) Lump Sum repair
- 
- ( X ) The above survey was conducted on a 'without prejudice' basis.  
Please note that the preliminary advice amount (Revised & Check Items)  
stated are subject to consistency check, part prices and labour cost.