

**Note: This document has not been finalised.**

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Christina Wong

Date: 09 Dec 2021

**Preliminary Advice**

Insured : SMS8221Y  
Vehicle No  
TP Vehicle No : SLL2695B  
Make : MAZDA 5  
Date of Inspection : 06/12/2021  
Inspection At : CHENG HOE MOTOR PTE LTD (YISHUN)  
BLK 1019 #01-374/382, YISHUN INDUSTRIAL PARK A  
SINGAPORE 768761

Accident Date : 04/12/2021  
Assignment Date : 06/12/2021  
Est. Duration of Repair : 4

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,248.64
Revised Amount	:S\$	3,436.64
Check Items (Estimated)	:S\$	412.00
Total	:S\$	3,848.64

Lump Sum Repair :S\$

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$

Salvage Value :S\$

Margin for Repair :S\$

**Remarks**

- ( ) The vehicle is economical for repair
- ( ) The vehicle is not economical for repair
- ( ) Part-by-Part repair
- ( ) Lump Sum repair
  
- ( X ) The above survey was conducted on a 'without prejudice' basis. Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.